

**MONTGOMERY TOWNSHIP BOARD OF EDUCATION  
1014 ROUTE 601  
SKILLMAN, NEW JERSEY 08558  
PHONE: (609) 466-7601  
FAX: (609) 466-0944**

**Addendum No. 1  
for  
B20-01, District Fire Alarm Testing, Maintenance and Repair**

*See attached Revised Notice to Bidders – Addendum #1*

**Attachment #1**

Question: Is a bid bond required?

*No, upon further review it has been determined that a **Bid Bond** is “not” required with this bid.*

Question: Are the fire alarm devices bar coded?

*No, the fire alarm devices are not bar coded and the district does not intend to bar code the devices at this time.*

Question: Would you happen to have the device counts of each of the seven sites list on the bid? We would need to know the quantities of, for example, smoke detectors, manual pull stations, heat detectors, horns/strobes etc.

*Please review the attached Fire Alarm and Life Safety System Inspection Certificates.*

**Attachment #2**

**Note:** No additional questions will be accepted after April 5, 2019.

**Attachment #1**

**MONTGOMERY TOWNSHIP BOARD OF EDUCATION  
REVISED NOTICE TO BIDDERS  
Addendum #1**

The Montgomery Township Board of Education has **revised** the sealed bid opening date and time until **11:00 A.M. on Wednesday, April 17, 2019**, and will be publicly opened and read thereafter in the office of the School Business Administrator/Board Secretary, Administration Building, 1014 Route 601, Skillman, New Jersey, 08558, for the following:

**B20-01, District Fire Alarm Testing, Maintenance and Repair**

The bid package may be examined at the office of the School Business Administrator/Board Secretary as stated above and each bidder, thereof, may obtain one copy. Requests may be made to (609) 466-7635 or the District Homepage, [www.mtsd.k12.nj.us](http://www.mtsd.k12.nj.us), click-on Departments/Business Office/Bids.

Bids must be submitted on the standard proposal form in the manner designated therein and required by the specifications. Bids must be enclosed in sealed envelopes bearing the name of the bidder on the outside, **clearly marked with the bid description and bid number**, and addressed to School Business Administrator/Board Secretary of the Montgomery Township Board of Education, 1014 Route 601, Skillman, New Jersey 08558. Sealed bids must be delivered to the Administration Building on or before the time and date stated above. The Montgomery Township Board of Education assumes no Responsibility for bids mailed incorrectly or misdirected in delivery.

No bidder may withdraw his bid for a period of sixty (60) days after the date set for the opening thereof.

Bidders are required to comply with the Affirmative Action requirements of N.J.S.A. 10:5-31 et seq. and N.J.A.C. 17:27. If applicable the bidders are required to comply with the Prevailing Wage Law as required under Chapter 150 of the laws of 1963, State of New Jersey.

Bidding shall be in conformance with the applicable requirements of N.J.S.A. 18A:18A-1 et seq., pertaining to the "Public School Contracts Law".

Mr. Mark Kramer  
School Business Administrator/Board Secretary  
April 5, 2019

# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery High School  
1016 Co. RD. 601  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
*Dec 17, 2018*

Building: Montgomery High School  
Contact: Dave Klein  
Title: B&G

Company: Alarm & Communication Technologies  
Contact: Robert Kilcher  
Title: Inspector

# Executive Summary

Generated by: BuildingReports.com

Building Information		
<b>Building:</b> Montgomery High School	<b>Contact:</b> Dave Klein	
<b>Address:</b> 1016 Co. RD. 601	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Robert Kilcher	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 2018416983	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 2018416983	
<b>Country:</b> United States of America	<b>Email:</b> RobertK@njact.com	
System Control Unit		
<b>Manufacturer:</b> EST	<b>Inspection Date:</b> 10/03/2018	<b>IDC Style:</b>
<b>Model Number:</b> EST-3	<b>Install Date:</b> 08/22/2016	<b>SLC Style:</b> 4
<b>Software Version:</b> 5.32	<b>Version Date:</b> 10/12/2017	<b>NAC Style:</b> Y
<b>Location:</b> 1st Building manager's office rm H-101	<b>Current Protection:</b> Breaker	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b> Digital Communicator	<b>Mfg:</b> Honeywell	<b>Model #:</b> IPGSM-4G
<b>Test Time/Date:</b> 10/3/18 1:52:38 PM	<b>Restore Time</b>	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	58	7.73%	58	100.00%	32	55.17%	26	44.83%
Initiating	673	89.73%	556	82.62%	556	100.00%	0	0%
Supervisory	19	2.53%	19	100.00%	19	100.00%	0	0%
<b>Totals</b>	<b>750</b>	<b>100%</b>	<b>633</b>	<b>84.40%</b>	<b>607</b>	<b>95.89%</b>	<b>26</b>	<b>4.11%</b>
Certification								
Company: Alarm & Communication Technologies				Building: Montgomery High School				
Inspector: Robert Kilcher				Contact: Dave Klein				
Signed:				Signed:				

# Discrepancy Report

Generated by: [BuildingReports.com](http://BuildingReports.com)

Building: Montgomery High School		Control Panel: 1 - EST EST-3		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
🔍 ScanID	📍 Location	🔧 Problem	📍 Address	📖 Reference
<i>Control</i>				
<b>Battery</b>				
33368830	1st H-101 in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
33368831	1st H-101 in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626200	1st Room A108C bottom BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626199	1st Room A108C bottom BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626193	1st Room A108C in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626194	1st Room A108C in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626198	1st Room A108C top BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626197	1st Room A108C top BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626214	1st Room A137 storage	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626215	1st Room A137 storage	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626219	1st Room B127 storage	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626218	1st Room B127 storage	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626184	1st Room E119 BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626183	1st Room E119 BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626166	1st Room F117 next to FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626167	1st Room F117 next to FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626128	1st Room H101 next to FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)

42626129	1st Room H101 next to FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626294	1st Admin building Room D17 in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626293	1st Admin building Room D17 in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626254	2nd Room B212 BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626253	2nd Room B212 BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626250	2nd Room B258 bottom BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626251	2nd Room B258 bottom BPS	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626245	2nd Room B258 electrical closet in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626244	2nd Room B258 electrical closet in FACP	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)

***Code References***

NFPA72 Table 14.4.3.2 (9a)(1)	Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations
----------------------------------	--

# Proposed Solutions Report

Generated by: BuildingReports.com

Building: Montgomery High School			Control Panel: 1 - EST EST-3		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<b>Control</b>					
<b>Battery</b>					
33368830	1st H-101 in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
33368831	1st H-101 in FACP	Replace	PS- 12180 F2	T/M	<input type="checkbox"/>
42626200	1st Room A108C bottom BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626199	1st Room A108C bottom BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626193	1st Room A108C in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
42626194	1st Room A108C in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
42626198	1st Room A108C top BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626197	1st Room A108C top BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626214	1st Room A137 storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626215	1st Room A137 storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626219	1st Room B127 storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626218	1st Room B127 storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626184	1st Room E119 BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626183	1st Room E119 BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626166	1st Room F117 next to FACP	Replace	UT1270	T/M	<input type="checkbox"/>
42626167	1st Room F117 next to FACP	Replace	UT1270	T/M	<input type="checkbox"/>
42626128	1st Room H101 next to FACP	Replace	UT1270	T/M	<input type="checkbox"/>
42626129	1st Room H101 next to FACP	Replace	UT1270	T/M	<input type="checkbox"/>
42626294	1st Admin building Room D17 in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
42626293	1st Admin building Room D17 in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
42626254	2nd Room B212 BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626253	2nd Room B212 BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626250	2nd Room B258 bottom BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626251	2nd Room B258 bottom BPS	Replace	UT1270	T/M	<input type="checkbox"/>
42626245	2nd Room B258 electrical closet in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
42626244	2nd Room B258 electrical closet in FACP	Replace	ps-12180 F2	T/M	<input type="checkbox"/>
<b>PO #:</b> (none)				<b>T/M</b>	



# Notes & Recommendations

Generated by: *BuildingReports.com*

<b>Building: Montgomery High School</b>				
<i>The Notes &amp; Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.</i>				
<b>General Note</b>				
Smoke in hall 2nd Fl by room A203 hanging by wires.				
Customer says phone line 1 goes into trouble frequently, did not happen while on site.				
All descriptions can be better identified for emergency situations.				
<b>Building: Montgomery High School</b>		<b>Control Panel: 1 - EST EST-3</b>		
<b>ScanID</b>	<b>Note</b>	<b>Device Type</b>	<b>Location</b>	<b>Comment</b>
<b>Control</b>				
42626127	2	Power Supply	1st Room H101 next to FACP	Passed
Transformer in BPS is hissing				

# Inspection & Testing

Generated by: BuildingReports.com

Building: Montgomery High School		Control Panel: 1 - EST EST-3		
<p><i>The Inspection &amp; Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time &amp; date at which testing occurred.</i></p>				
Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Annunciator	1st Admin building AD40 vestibule exit	Tested	2:21:57 PM	10/03/2018
Annunciator	1st A1000 main office	Tested	1:04:00 PM	10/03/2018
Annunciator	1st A1001 main office work area	Tested	1:04:57 PM	10/03/2018
Annunciator	1st By A1 main exit	Tested	1:03:13 PM	10/03/2018
Annunciator	1st By B11 vestibule exit	Tested	12:56:29 PM	10/03/2018
Annunciator	1st By E47 vestibule exit	Tested	2:27:33 PM	10/03/2018
Annunciator	1st F45 vestibule exit	Tested	1:44:47 PM	10/03/2018
Annunciator	1st G25 vestibule exit	Tested	2:37:16 PM	10/03/2018
Battery	1st Admin building Room D17 in BPS	Tested	1:56:18 PM	10/03/2018
Battery	1st Admin building Room D17 in BPS	Tested	1:56:12 PM	10/03/2018
Battery	1st Admin building Room D17 in communicator	Tested	1:52:52 PM	10/03/2018
Battery	1st Room F117 in FACP	Tested	2:30:56 PM	10/03/2018
Battery	1st Room F117 in FACP	Tested	2:31:45 PM	10/03/2018
Battery	2nd Room B258 top BPS	Tested	12:31:02 PM	10/03/2018
Battery	2nd Room B258 top BPS	Tested	12:31:06 PM	10/03/2018
Communicator	1st Admin building Room D17	Tested	1:52:38 PM	10/03/2018
Control Panel	1st Building manager's office rm H-101	Tested	7:54:03 AM	10/03/2018
Power Supply	1st Admin building Room D17 next to FACP	Tested	1:55:48 PM	10/03/2018
Power Supply	1st bottom Room A108C storage	Tested	1:13:08 PM	10/03/2018
Power Supply	1st top Room A108C storage	Tested	1:12:46 PM	10/03/2018
Power Supply	1st Room A137 storage	Tested	12:58:03 PM	10/03/2018
Power Supply	1st Room B127 storage	Tested	12:52:54 PM	10/03/2018
Power Supply	1st Room E119 elec. closet	Tested	1:25:33 PM	10/03/2018
Power Supply	1st Room F117 next to FACP	Tested	2:29:41 PM	10/03/2018
Power Supply	1st Room H101 next to FACP	Tested	12:24:48 PM	10/03/2018
Power Supply	2nd bottom Room B258 electrical closet	Tested	12:30:37 PM	10/03/2018
Power Supply	2nd top Room B258 electrical closet	Tested	12:30:00 PM	10/03/2018
Power Supply	2nd Room B212 storage	Tested	12:35:30 PM	10/03/2018
<b>Initiating</b>				
Duct Detector	1st AHU2 in G116 test sw (F117)	Tested	10:25:14 AM	10/04/2018
Duct Detector	1st MUA 1 kitchen prep D118 test sw (H101)	Tested	10:25:40 AM	10/04/2018
Duct Detector	1st MUA 2 kitchen prep D118 test sw (H101)	Tested	10:25:41 AM	10/04/2018
Duct Detector	1st RTU1 practice room A-130 test sw	Tested	10:25:19 AM	10/04/2018
Duct Detector	1st RTU10 girls locker room test sw (F117)	Tested	10:25:15 AM	10/04/2018
Duct Detector	1st RTU11 main lobby gym E-1142 test sw (F117)	Tested	10:25:16 AM	10/04/2018
Duct Detector	1st RTU19 hall by aux. gym test sw (F117)	Tested	10:25:17 AM	10/04/2018
Duct Detector	1st RTU2 scene shop A-1121 test sw	Tested	10:25:21 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Duct Detector	1st RTU23 hall by E2312 test sw (B258)	Tested	10:25:38 AM	10/04/2018
Duct Detector	1st RTU24 main gym E-1142 test sw (F117)	Tested	10:25:17 AM	10/04/2018
Duct Detector	1st RTU25 main gym east E-1142 test sw (F117)	Tested	10:25:18 AM	10/04/2018
Duct Detector	1st RTU26 women's locker room G116 test sw (F117)	Tested	10:25:19 AM	10/04/2018
Duct Detector	1st RTU27 admin return test sw	Tested	10:25:26 AM	10/04/2018
Duct Detector	1st RTU27 admin supply test sw	Tested	10:25:25 AM	10/04/2018
Duct Detector	1st RTU28 admin return test sw	Tested	10:25:28 AM	10/04/2018
Duct Detector	1st RTU28 admin supply test sw	Tested	10:25:27 AM	10/04/2018
Duct Detector	1st RTU3 hall A-122 by A-1137 test sw	Tested	10:25:21 AM	10/04/2018
Duct Detector	1st RTU4 Hall by auditorium test sw	Tested	10:25:22 AM	10/04/2018
Duct Detector	1st RTU5 H.S. Admin test sw	Tested	10:25:23 AM	10/04/2018
Duct Detector	1st RTU6 Hall by stage test sw	Tested	10:25:25 AM	10/04/2018
Duct Detector	1st RTU7 Family science D1129 test sw (H101)	Tested	10:25:41 AM	10/04/2018
Duct Detector	1st RTU8 Prep/Serving D118/121 test sw (H101)	Tested	10:25:42 AM	10/04/2018
Duct Detector	1st RTU9 trainers area test sw (F117)	Tested	10:25:15 AM	10/04/2018
Duct Detector	2nd RTU12 hall B225 by B2228 test sw (B258)	Tested	10:25:34 AM	10/04/2018
Duct Detector	2nd RTU13 hall by B2218 test sw (B258)	Tested	10:25:35 AM	10/04/2018
Duct Detector	2nd RTU15 hall / media center test sw (B258)	Tested	10:25:36 AM	10/04/2018
Duct Detector	2nd RTU16 hall by A2206 test sw (B258)	Tested	10:25:36 AM	10/04/2018
Duct Detector	2nd RTU17 hall by C2207 test sw (B258)	Tested	10:25:37 AM	10/04/2018
Duct Detector	2nd RTU18 hall by B2227 test sw (B258)	Tested	10:25:38 AM	10/04/2018
Duct Detector	2nd RTU22 hall by E2308 test sw (B258)	Tested	10:25:39 AM	10/04/2018
Duct Detector	2nd RTU23 hall by E2312 test sw (B258)	Tested	10:25:39 AM	10/04/2018
Heat Detector	1st Above Ceiling Admin 100 AD Vestibule	Tested	1:25:12 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 101 AD Lobby	Tested	1:25:44 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 110 AD108 Copy Rm	Tested	1:31:11 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 114 AD107 Sm Conf Rm	Tested	1:26:48 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 115 AD03 Super Storage	Tested	1:29:16 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 116 AD01 Lounge East	Tested	1:28:39 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 117 AD02 Women's Lav East	Tested	1:28:04 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 118 AD104 Men's Lav East	Tested	1:27:30 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 138 AD137 Conf Rm Pupil Svc	Tested	1:29:52 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 146 Woman's Lav West	Tested	1:23:10 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 158 AD112 Meeting Rm	Tested	1:30:38 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 161 AD13 Mech Rm West	Tested	1:23:44 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin 162 AD12 Cust Clst West	Tested	1:24:24 PM	12/11/2018
Heat Detector	1st Above Ceiling Admin Corr 177 by 161 Mech Rm	Tested	1:26:11 PM	12/11/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	1st Above Ceiling Admin Corridor 124	Tested	1:23:15 PM	12/11/2018
Pull Station	1st Admin corr. 126	Tested	1:43:41 PM	10/04/2018
Pull Station	1st Admin corr. 177 by exit door	Tested	1:45:26 PM	10/04/2018
Pull Station	1st Admin corr. 179 by exit door	Tested	1:42:59 PM	10/04/2018
Pull Station	1st Admin transport 169 AD116 exit	Tested	1:49:58 PM	10/04/2018
Pull Station	1st Admin vestibule 100 exit	Tested	1:46:34 PM	10/04/2018
Pull Station	1st Admin vestibule 174 exit	Tested	1:44:49 PM	10/04/2018
Pull Station	1st In f153b boiler room by exit ad35	Tested	1:42:15 PM	10/04/2018
Smoke Detector	1st Admin 175 electrical Rm AD17	Tested/Cleaned	10:24:09 AM	10/04/2018
Smoke Detector	1st Admin corr. 121	Tested/Cleaned	10:24:25 AM	10/04/2018
Smoke Detector	1st Admin corr. 122 by Rm 107 AD140	Tested/Cleaned	10:24:25 AM	10/04/2018
Smoke Detector	1st Admin corr. 122 by Rm 108!AD139	Tested/Cleaned	10:24:26 AM	10/04/2018
Smoke Detector	1st Admin corr. 123 by Rm 114 AD107	Tested/Cleaned	10:24:22 AM	10/04/2018
Smoke Detector	1st Admin corr. 123 by Rm 118 AD04	Tested/Cleaned	10:24:18 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 at corr. 123 intersect	Tested/Cleaned	10:24:16 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 by lunch 157 AD09	Tested/Cleaned	10:24:13 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 by Rm 120 AD06	Tested/Cleaned	10:24:17 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 by room 142 AD123	Tested/Cleaned	10:24:16 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 by room 144 AD121	Tested/Cleaned	10:24:15 AM	10/04/2018
Smoke Detector	1st Admin corr. 159 by room 152 AD111	Tested/Cleaned	10:24:15 AM	10/04/2018
Smoke Detector	1st Admin corr. 175 at corr. 159 intersect	Tested/Cleaned	10:24:12 AM	10/04/2018
Smoke Detector	1st Admin corr. 175 at vest. 174 intersect	Tested/Cleaned	10:24:11 AM	10/04/2018
Smoke Detector	1st Admin corr. 176 by 167 AD113	Tested/Cleaned	10:24:10 AM	10/04/2018
Smoke Detector	1st Admin corr. 176 by Rm 177 AD16	Tested/Cleaned	10:24:08 AM	10/04/2018
Smoke Detector	1st Admin corr. 176 by storage 165 AD11	Tested/Cleaned	10:24:10 AM	10/04/2018
Smoke Detector	1st Admin corr. 177 by corr. 176 intersect	Tested/Cleaned	10:24:13 AM	10/04/2018
Smoke Detector	1st Admin corr. 177 by exit door	Tested/Cleaned	10:24:14 AM	10/04/2018
Smoke Detector	1st Admin corr. 178	Tested/Cleaned	10:24:08 AM	10/04/2018
Smoke Detector	1st Admin corr. 179	Tested/Cleaned	10:24:07 AM	10/04/2018
Smoke Detector	1st Admin lobby 101 by Rm 103A	Tested/Cleaned	10:24:24 AM	10/04/2018
Smoke Detector	1st Admin lobby 101 by Rm 112 AD105	Tested/Cleaned	10:24:23 AM	10/04/2018
Smoke Detector	1st Admin vestibule 100 exit	Tested/Cleaned	10:24:24 AM	10/04/2018
Smoke Detector	1st Aud lobby south by women's rm A-142	Tested/Cleaned	10:21:44 AM	10/04/2018
Smoke Detector	1st Auditorium foyer A103	Tested/Cleaned	10:21:42 AM	10/04/2018
Smoke Detector	1st Auditorium south lobby by vestibule	Tested/Cleaned	10:21:45 AM	10/04/2018
Smoke Detector	1st BLDG mgr h101	Tested/Cleaned	10:19:42 AM	10/04/2018
Smoke Detector	1st cafe lobby by nurse e-1110	Tested/Cleaned	10:21:20 AM	10/04/2018
Smoke Detector	1st Cafe lobby by school store e106	Tested/Cleaned	10:21:16 AM	10/04/2018
Smoke Detector	1st cafe lobby by stair e1	Tested/Cleaned	10:21:19 AM	10/04/2018
Smoke Detector	1st Cafe lobby by student org e107	Tested/Cleaned	10:21:15 AM	10/04/2018
Smoke Detector	1st Cafe lobby e108 by north vestibule	Tested/Cleaned	10:21:18 AM	10/04/2018
Smoke Detector	1st Cafe lobby e108 center	Tested/Cleaned	10:21:16 AM	10/04/2018
Smoke Detector	1st East vestibule to cafe lobby e108	Tested/Cleaned	10:21:18 AM	10/04/2018
Smoke Detector	1st Gym lobby by student org e107	Tested/Cleaned	10:21:14 AM	10/04/2018
Smoke Detector	1st Hall A122 by aud lobby south	Tested/Cleaned	10:21:43 AM	10/04/2018
Smoke Detector	1st Hall by acid tank f-163	Tested/Cleaned	10:21:49 AM	10/04/2018
Smoke Detector	1st hall by aerobics f-1116	Tested/Cleaned	10:21:34 AM	10/04/2018
Smoke Detector	1st Hall by art A-184	Tested/Cleaned	10:22:13 AM	10/04/2018
Smoke Detector	1st Hall by art room A-1185	Tested/Cleaned	10:22:12 AM	10/04/2018
Smoke Detector	1st Hall by athletic director e1162	Tested/Cleaned	10:21:11 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Hall by aud foyer A103	Tested/Cleaned	10:21:43 AM	10/04/2018
Smoke Detector	1st Hall by auditorium north ramp	Tested/Cleaned	10:22:09 AM	10/04/2018
Smoke Detector	1st Hall by auditorium south ramp	Tested/Cleaned	10:22:18 AM	10/04/2018
Smoke Detector	1st Hall by aux gym north	Tested/Cleaned	10:21:01 AM	10/04/2018
Smoke Detector	1st Hall by aux gym west lobby	Tested/Cleaned	10:21:00 AM	10/04/2018
Smoke Detector	1st Hall by B1117	Tested/Cleaned	10:19:54 AM	10/04/2018
Smoke Detector	1st Hall by B1118	Tested/Cleaned	10:19:49 AM	10/04/2018
Smoke Detector	1st Hall by B1119	Tested/Cleaned	10:19:53 AM	10/04/2018
Smoke Detector	1st Hall by bld mgr h101	Tested/Cleaned	10:19:43 AM	10/04/2018
Smoke Detector	1st Hall by boiler room h104	Tested/Cleaned	10:20:31 AM	10/04/2018
Smoke Detector	1st Hall by Book storage room B108	Tested/Cleaned	10:20:08 AM	10/04/2018
Smoke Detector	1st Hall by boys team rm f1106	Tested/Cleaned	10:20:58 AM	10/04/2018
Smoke Detector	1st Hall by boys/girls locker rooms	Tested/Cleaned	10:20:30 AM	10/04/2018
Smoke Detector	1st Hall by C.I.C.I. Rm A-121	Tested/Cleaned	10:22:11 AM	10/04/2018
Smoke Detector	1st Hall by class A-1135	Tested/Cleaned	10:22:16 AM	10/04/2018
Smoke Detector	1st Hall by class D-1118	Tested/Cleaned	10:22:07 AM	10/04/2018
Smoke Detector	1st Hall by coaches rm E-145	Tested/Cleaned	10:21:01 AM	10/04/2018
Smoke Detector	1st hall by color dark rm F-134	Tested/Cleaned	10:21:39 AM	10/04/2018
Smoke Detector	1st Hall by courtyard A entry	Tested/Cleaned	10:22:04 AM	10/04/2018
Smoke Detector	1st Hall by courtyard center	Tested/Cleaned	10:21:53 AM	10/04/2018
Smoke Detector	1st Hall by courtyard exit / aux gym	Tested/Cleaned	10:21:29 AM	10/04/2018
Smoke Detector	1st Hall by courtyard south end	Tested/Cleaned	10:21:52 AM	10/04/2018
Smoke Detector	1st Hall by custodian closet f141	Tested/Cleaned	10:21:52 AM	10/04/2018
Smoke Detector	1st Hall by English department B1106	Tested/Cleaned	10:20:06 AM	10/04/2018
Smoke Detector	1st Hall by exam room by E113	Tested/Cleaned	10:20:27 AM	10/04/2018
Smoke Detector	1st hall by F-1121	Tested/Cleaned	10:21:35 AM	10/04/2018
Smoke Detector	1st hall by F-1123	Tested/Cleaned	10:21:36 AM	10/04/2018
Smoke Detector	1st Hall by girls locker e1127	Tested/Cleaned	10:20:28 AM	10/04/2018
Smoke Detector	1st Hall by girls team rm E1148	Tested/Cleaned	10:20:45 AM	10/04/2018
Smoke Detector	1st Hall by girls team rm E1148	Tested/Cleaned	10:21:02 AM	10/04/2018
Smoke Detector	1st Hall by girls team rm E1148	Tested/Cleaned	10:21:03 AM	10/04/2018
Smoke Detector	1st Hall by Gym 1142 lobby	Tested/Cleaned	10:20:28 AM	10/04/2018
Smoke Detector	1st Hall by gym main lobby vest	Tested/Cleaned	10:21:13 AM	10/04/2018
Smoke Detector	1st Hall by hallway by special education b114	Tested/Cleaned	10:20:07 AM	10/04/2018
Smoke Detector	1st hall by health F-1125	Tested/Cleaned	10:21:37 AM	10/04/2018
Smoke Detector	1st Hall by health F-1125	Tested/Cleaned	10:21:40 AM	10/04/2018
Smoke Detector	1st Hall by I TV room B1102	Tested/Cleaned	10:20:13 AM	10/04/2018
Smoke Detector	1st hall by IDF-7 rm F-140	Tested/Cleaned	10:21:38 AM	10/04/2018
Smoke Detector	1st Hall by IDF-8 rm H-102A	Tested/Cleaned	10:20:31 AM	10/04/2018
Smoke Detector	1st Hall by IDF6 room D115	Tested/Cleaned	10:20:27 AM	10/04/2018
Smoke Detector	1st Hall by instrument room A-1123	Tested/Cleaned	10:22:15 AM	10/04/2018
Smoke Detector	1st Hall by locker e1127	Tested/Cleaned	10:20:29 AM	10/04/2018
Smoke Detector	1st Hall By locker rms G116/124	Tested/Cleaned	10:20:34 AM	10/04/2018
Smoke Detector	1st Hall by mech rm AD-181	Tested/Cleaned	10:21:50 AM	10/04/2018
Smoke Detector	1st Hall by media passage C-106	Tested/Cleaned	10:21:45 AM	10/04/2018
Smoke Detector	1st Hall By men's locker rm G124	Tested/Cleaned	10:20:35 AM	10/04/2018
Smoke Detector	1st Hall by men's room A-112	Tested/Cleaned	10:22:13 AM	10/04/2018
Smoke Detector	1st Hall By men's room G132	Tested/Cleaned	10:20:36 AM	10/04/2018
Smoke Detector	1st Hall by Orchestra pit stair A1	Tested/Cleaned	10:22:10 AM	10/04/2018
Smoke Detector	1st Hall by Passage by make up room C111	Tested/Cleaned	10:20:15 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st hall by photo studio F-1132	Tested/Cleaned	10:21:37 AM	10/04/2018
Smoke Detector	1st Hall by records rm A-152	Tested/Cleaned	10:22:08 AM	10/04/2018
Smoke Detector	1st Hall by Resource room B1104	Tested/Cleaned	10:20:09 AM	10/04/2018
Smoke Detector	1st Hall by Resource room B1109	Tested/Cleaned	10:20:07 AM	10/04/2018
Smoke Detector	1st Hall by rm f153	Tested/Cleaned	10:21:51 AM	10/04/2018
Smoke Detector	1st Hall by room B1103	Tested/Cleaned	10:20:12 AM	10/04/2018
Smoke Detector	1st Hall by room B1108	Tested/Cleaned	10:20:04 AM	10/04/2018
Smoke Detector	1st Hall by room B1115	Tested/Cleaned	10:20:02 AM	10/04/2018
Smoke Detector	1st Hall by room B1123	Tested/Cleaned	10:19:51 AM	10/04/2018
Smoke Detector	1st Hall by snack bar e168	Tested/Cleaned	10:21:12 AM	10/04/2018
Smoke Detector	1st Hall by stair D3 vestibule	Tested/Cleaned	10:19:47 AM	10/04/2018
Smoke Detector	1st Hall by stairwell B1	Tested/Cleaned	10:20:11 AM	10/04/2018
Smoke Detector	1st Hall by stare b2	Tested/Cleaned	10:20:01 AM	10/04/2018
Smoke Detector	1st Hall by storage A-133	Tested/Cleaned	10:22:15 AM	10/04/2018
Smoke Detector	1st Hall by storage A-137	Tested/Cleaned	10:22:16 AM	10/04/2018
Smoke Detector	1st Hall by Storage B144	Tested/Cleaned	10:19:52 AM	10/04/2018
Smoke Detector	1st Hall by Storage B149	Tested/Cleaned	10:19:49 AM	10/04/2018
Smoke Detector	1st Hall by storage be 127	Tested/Cleaned	10:20:03 AM	10/04/2018
Smoke Detector	1st hall by Storage f-117 in aux gym	Tested/Cleaned	10:21:32 AM	10/04/2018
Smoke Detector	1st hall by storage F-126	Tested/Cleaned	10:21:36 AM	10/04/2018
Smoke Detector	1st Hall by tech dept f-164	Tested/Cleaned	10:21:49 AM	10/04/2018
Smoke Detector	1st Hall by trainer E1154	Tested/Cleaned	10:20:58 AM	10/04/2018
Smoke Detector	1st Hall by vestibule to aux gym f-1100	Tested/Cleaned	10:21:27 AM	10/04/2018
Smoke Detector	1st Hall By women's locker rm G116	Tested/Cleaned	10:20:34 AM	10/04/2018
Smoke Detector	1st Hall by work area A-1000	Tested/Cleaned	10:22:07 AM	10/04/2018
Smoke Detector	1st Hall by yearbook rm A-1137	Tested/Cleaned	10:22:17 AM	10/04/2018
Smoke Detector	1st Hall C116 by hall C114	Tested/Cleaned	10:21:46 AM	10/04/2018
Smoke Detector	1st Hall center between main & aux gym	Tested/Cleaned	10:21:05 AM	10/04/2018
Smoke Detector	1st Hall center between main & aux gym	Tested/Cleaned	10:21:06 AM	10/04/2018
Smoke Detector	1st Hall D102 center by Media Center	Tested/Cleaned	10:22:05 AM	10/04/2018
Smoke Detector	1st Hall D102 center by Media Center	Tested/Cleaned	10:22:06 AM	10/04/2018
Smoke Detector	1st Hall D102 west by Media Center	Tested/Cleaned	10:22:06 AM	10/04/2018
Smoke Detector	1st Hall E169 by gym E1142 North Corner	Tested/Cleaned	10:21:09 AM	10/04/2018
Smoke Detector	1st Hall E169 by gym E1142 North Vestibule	Tested/Cleaned	10:21:09 AM	10/04/2018
Smoke Detector	1st Hall east between main & aux gym	Tested/Cleaned	10:21:07 AM	10/04/2018
Smoke Detector	1st Hall East by Media Center	Tested/Cleaned	10:22:05 AM	10/04/2018
Smoke Detector	1st Hall end by fam scienced1129	Tested/Cleaned	10:19:45 AM	10/04/2018
Smoke Detector	1st Hall exit by family science d1129	Tested/Cleaned	10:19:46 AM	10/04/2018
Smoke Detector	1st Hall exit by stair d3	Tested/Cleaned	10:19:45 AM	10/04/2018
Smoke Detector	1st Hall F-1118 center By aux gym	Tested/Cleaned	10:21:27 AM	10/04/2018
Smoke Detector	1st Hall G112 by hall G121	Tested/Cleaned	10:20:33 AM	10/04/2018
Smoke Detector	1st Hall N.E. By aux gym f-1100	Tested/Cleaned	10:21:30 AM	10/04/2018
Smoke Detector	1st Hall ramp bottom to pool	Tested/Cleaned	10:20:32 AM	10/04/2018
Smoke Detector	1st Hall ramp top to pool	Tested/Cleaned	10:20:33 AM	10/04/2018
Smoke Detector	1st Hall S.E. By aux gym F-1100	Tested/Cleaned	10:21:26 AM	10/04/2018
Smoke Detector	1st Hall south by aux gym	Tested/Cleaned	10:20:57 AM	10/04/2018
Smoke Detector	1st Hall west between main & aux gym	Tested/Cleaned	10:21:04 AM	10/04/2018
Smoke Detector	1st Hall west between main & aux gym	Tested/Cleaned	10:21:05 AM	10/04/2018
Smoke Detector	1st Lobby by elevator 2	Tested/Cleaned	10:21:48 AM	10/04/2018
Smoke Detector	1st Lobby by main gym	Tested/Cleaned	10:21:14 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Lobby by Media Center entrance	Tested/Cleaned	10:22:03 AM	10/04/2018
Smoke Detector	1st Lobby C by display case A-100B	Tested/Cleaned	10:21:41 AM	10/04/2018
Smoke Detector	1st Lobby C by passage A106B	Tested/Cleaned	10:21:59 AM	10/04/2018
Smoke Detector	1st Lobby C by work area A-1001	Tested/Cleaned	10:22:00 AM	10/04/2018
Smoke Detector	1st Lobby C by work area A-1001	Tested/Cleaned	10:22:01 AM	10/04/2018
Smoke Detector	1st Lobby C center by auditorium	Tested/Cleaned	10:21:58 AM	10/04/2018
Smoke Detector	1st Lobby D101 by vending	Tested/Cleaned	10:22:03 AM	10/04/2018
Smoke Detector	1st N. Lobby by HS Admin A-1000	Tested/Cleaned	10:22:01 AM	10/04/2018
Smoke Detector	1st N. Vestibule by HS Admin A-1000	Tested/Cleaned	10:22:02 AM	10/04/2018
Smoke Detector	1st North vestibule to Cafe lobby e108	Tested/Cleaned	10:21:17 AM	10/04/2018
Smoke Detector	1st North Vestibule to main gym	Tested/Cleaned	10:21:10 AM	10/04/2018
Smoke Detector	1st Passage a-117 stage rear at exit	Tested/Cleaned	10:22:19 AM	10/04/2018
Smoke Detector	1st Passage by AV media room C107	Tested/Cleaned	10:20:24 AM	10/04/2018
Smoke Detector	1st Passage by B1112	Tested/Cleaned	10:19:54 AM	10/04/2018
Smoke Detector	1st Passage by B1116	Tested/Cleaned	10:19:50 AM	10/04/2018
Smoke Detector	1st Passage by C101	Tested/Cleaned	10:20:26 AM	10/04/2018
Smoke Detector	1st Passage by kitchen C106C	Tested/Cleaned	10:20:25 AM	10/04/2018
Smoke Detector	1st Pool lobby north g100	Tested/Cleaned	10:20:43 AM	10/04/2018
Smoke Detector	1st Pool lobby north g100a	Tested/Cleaned	10:20:42 AM	10/04/2018
Smoke Detector	1st South vestibule to main gym	Tested/Cleaned	10:21:12 AM	10/04/2018
Smoke Detector	1st Stage storage room A108C	Tested/Cleaned	10:22:19 AM	10/04/2018
Smoke Detector	1st Stair B2	Tested/Cleaned	10:21:47 AM	10/04/2018
Smoke Detector	1st Stair D1	Tested/Cleaned	10:22:02 AM	10/04/2018
Smoke Detector	1st Stair d3 vestibule	Tested/Cleaned	10:19:47 AM	10/04/2018
Smoke Detector	1st Stair e-1	Tested/Cleaned	10:21:20 AM	10/04/2018
Smoke Detector	1st Stair E153 to pool area	Tested/Cleaned	10:20:44 AM	10/04/2018
Smoke Detector	1st Stair E2	Tested/Cleaned	10:21:47 AM	10/04/2018
Smoke Detector	1st Stairwell b1	Tested/Cleaned	10:20:09 AM	10/04/2018
Smoke Detector	1st Storage f-117 in aux gym	Tested/Cleaned	10:21:31 AM	10/04/2018
Smoke Detector	1st Vestibule 174	Tested/Cleaned	10:24:11 AM	10/04/2018
Smoke Detector	1st Vestibule by art room a-1185	Tested/Cleaned	10:22:11 AM	10/04/2018
Smoke Detector	1st vestibule by aux gym f-1100	Tested/Cleaned	10:21:28 AM	10/04/2018
Smoke Detector	1st Vestibule by B1111	Tested/Cleaned	10:20:04 AM	10/04/2018
Smoke Detector	1st Vestibule by B1111	Tested/Cleaned	10:20:05 AM	10/04/2018
Smoke Detector	1st Vestibule by music A-1123	Tested/Cleaned	10:22:14 AM	10/04/2018
Smoke Detector	1st Vestibule by stair B1	Tested/Cleaned	10:20:10 AM	10/04/2018
Smoke Detector	1st Vestibule by stair B2	Tested/Cleaned	10:20:02 AM	10/04/2018
Smoke Detector	1st Vestibule to north loading dock	Tested/Cleaned	10:21:39 AM	10/04/2018
Smoke Detector	1st West lobby vestibule to aux gym	Tested/Cleaned	10:20:59 AM	10/04/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:22 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:25 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:26 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:34 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:39 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:49 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:37:53 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:38:00 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:38:10 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:38:16 PM	10/03/2018
Waterflow Switch	1st Room H104 boiler room	Tested	1:38:27 PM	10/03/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Waterflow Switch	1st Room H104 boiler room	Tested	1:38:32 PM	10/03/2018
<b>Supervisory</b>				
Tamper Switch	1st pipe 1 Room H104 boiler room	Tested	1:38:34 PM	10/03/2018
Tamper Switch	1st pipe 10 Room H104 boiler room	Tested	1:37:07 PM	10/03/2018
Tamper Switch	1st pipe 11 Room H104 boiler room	Tested	1:37:31 PM	10/03/2018
Tamper Switch	1st pipe 2 Room H104 boiler room	Tested	1:38:30 PM	10/03/2018
Tamper Switch	1st pipe 3 Room H104 boiler room	Tested	1:39:19 PM	10/03/2018
Tamper Switch	1st pipe 4 Room H104 boiler room	Tested	1:38:13 PM	10/03/2018
Tamper Switch	1st pipe 5 Room H104 boiler room	Tested	1:38:03 PM	10/03/2018
Tamper Switch	1st pipe 6 Room H104 boiler room	Tested	1:37:57 PM	10/03/2018
Tamper Switch	1st pipe 7 Room H104 boiler room	Tested	1:37:52 PM	10/03/2018
Tamper Switch	1st pipe 8 Room H104 boiler room	Tested	1:37:45 PM	10/03/2018
Tamper Switch	1st pipe 9 Room H104 boiler room	Tested	1:37:37 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:39 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:41 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:44 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:46 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:49 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:38:51 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:39:04 PM	10/03/2018
Tamper Switch	1st Room H104 boiler room	Tested	1:39:06 PM	10/03/2018
Device Type	Location	Service	Time	Date
<i>Failed/Other</i>				
<b>Control</b>				
Battery	1st Admin building Room D17 in FACP	Tested	2:24:08 PM	10/03/2018
Battery	1st Admin building Room D17 in FACP	Tested	2:24:19 PM	10/03/2018
Battery	1st H-101 in FACP	Tested	12:26:24 PM	10/03/2018
Battery	1st H-101 in FACP	Tested	12:26:33 PM	10/03/2018
Battery	1st Room A108C bottom BPS	Tested	1:13:43 PM	10/03/2018
Battery	1st Room A108C bottom BPS	Tested	1:13:57 PM	10/03/2018
Battery	1st Room A108C in FACP	Tested	1:12:12 PM	10/03/2018
Battery	1st Room A108C in FACP	Tested	1:12:25 PM	10/03/2018
Battery	1st Room A108C top BPS	Tested	1:14:58 PM	10/03/2018
Battery	1st Room A108C top BPS	Tested	1:15:08 PM	10/03/2018
Battery	1st Room A137 storage	Tested	12:58:43 PM	10/03/2018
Battery	1st Room A137 storage	Tested	12:58:56 PM	10/03/2018
Battery	1st Room B127 storage	Tested	12:52:03 PM	10/03/2018
Battery	1st Room B127 storage	Tested	12:52:46 PM	10/03/2018
Battery	1st Room E119 BPS	Tested	1:26:08 PM	10/03/2018
Battery	1st Room E119 BPS	Tested	1:26:22 PM	10/03/2018
Battery	1st Room F117 next to FACP	Tested	2:30:11 PM	10/03/2018
Battery	1st Room F117 next to FACP	Tested	2:30:20 PM	10/03/2018
Battery	1st Room H101 next to FACP	Tested	12:25:47 PM	10/03/2018
Battery	1st Room H101 next to FACP	Tested	12:26:02 PM	10/03/2018
Battery	2nd Room B212 BPS	Tested	12:36:03 PM	10/03/2018
Battery	2nd Room B212 BPS	Tested	12:37:39 PM	10/03/2018
Battery	2nd Room B258 bottom BPS	Tested	12:31:27 PM	10/03/2018
Battery	2nd Room B258 bottom BPS	Tested	12:31:40 PM	10/03/2018



Device Type	Location	Service	Time	Date
<b><i>Failed/Other</i></b>				
Battery	2nd Room B258 electrical closet in FACP	Tested	12:32:11 PM	10/03/2018
Battery	2nd Room B258 electrical closet in FACP	Tested	12:32:37 PM	10/03/2018
Device Type	Location	Service	Time	Date
<b><i>Untested</i></b>				
<b>Initiating</b>				
Heat Detector	1st Above Ceiling Admin 145 AD-120 Payroll			
Heat Detector	1st Above Ceiling Admin 146A Woman's Lav West Alcove			
Heat Detector	1st Above Ceiling Admin 150 AD-09 Exec. Sec. for BA			
Heat Detector	1st Above Ceiling Admin 151 AD-110 Bus. Admin			
Heat Detector	1st Above Ceiling Admin 152 AD-111 Asst. Bus. Admin			
Heat Detector	1st Above Ceiling Admin 153 AD-08 kitchen			
Heat Detector	1st Above Ceiling Admin 157 AD-09 Lunch			
Heat Detector	1st Above Ceiling Admin 160 AD-14 Men's Lav West			
Heat Detector	1st Above Ceiling Admin 167 AD-113 Purchasing WR			
Heat Detector	1st Above Ceiling Admin 168 AD-114 Purchasing			
Heat Detector	1st Above Ceiling Admin 169 AD-116 Transport Super			
Heat Detector	1st Above Ceiling Admin 171 AD-118 Grounds Sec.			
Heat Detector	1st Above Ceiling Admin 172 AD-117 Grounds Sec.			
Heat Detector	1st Above Ceiling Admin 173 AD-119 Custodial Sup.			
Heat Detector	1st Above Ceiling Admin 177L AD-16 MIF Distrib. Rm			
Heat Detector	1st Above Ceiling Admin 177R AD-16 MIF Distrib. Rm			
Heat Detector	1st Above Ceiling Admin Corr 121			
Heat Detector	1st Above Ceiling Admin Corr 122 at Office 108			
Heat Detector	1st Above Ceiling Admin Corr 122 at Storage 115			
Heat Detector	1st Above Ceiling Admin Corr 159 by 118 mens			
Heat Detector	1st Above Ceiling Admin Corr 159 by 148 Stor.			
Heat Detector	1st Above Ceiling Admin Corr 159 by 154 Stor.			
Heat Detector	1st Above Ceiling Admin Corr 174 AD Vestibule			
Heat Detector	1st Above Ceiling Admin Corr 175			
Heat Detector	1st Above Ceiling Admin Corr 176 by 165 Sec.			
Heat Detector	1st Above Ceiling Admin Corr 176 by 175 Sprink.			
Heat Detector	1st Above Ceiling Admin Corr 177 at T 159			
Heat Detector	1st Above Ceiling Admin Corridor 123			
Heat Detector	1st Above Ceiling Admin Corridor 178			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	1st Above Ceiling Admin Corridor 179			
Heat Detector	1st Above ceiling in B-103			
Heat Detector	1st Above ceiling in B-103A IDF-4			
Heat Detector	1st Above ceiling in B-1101			
Heat Detector	1st Above ceiling in B-1102			
Heat Detector	1st Above ceiling in B-1103			
Heat Detector	1st Above ceiling in B-1104			
Heat Detector	1st Above ceiling in B-1105			
Heat Detector	1st Above ceiling in B-1106			
Heat Detector	1st Above ceiling in B-1106 men's lav			
Heat Detector	1st Above ceiling in B-1106 women's lav			
Heat Detector	1st Above ceiling in B-1107			
Heat Detector	1st Above ceiling in B-1110			
Heat Detector	1st Above ceiling in B-1111			
Heat Detector	1st Above ceiling in B-1112			
Heat Detector	1st Above ceiling in B-1113			
Heat Detector	1st Above ceiling in B-1114			
Heat Detector	1st Above ceiling in B-1115			
Heat Detector	1st Above ceiling in B-1116			
Heat Detector	1st Above ceiling in B-1117			
Heat Detector	1st Above ceiling in B-1118			
Heat Detector	1st Above ceiling in B-1119			
Heat Detector	1st Above ceiling in B-1121			
Heat Detector	1st Above ceiling in B-1123			
Heat Detector	1st Above ceiling in B-1125			
Heat Detector	1st Above ceiling in C-102 IDF-5			
Heat Detector	1st Above ceiling in C-103			
Heat Detector	1st Above ceiling in C-104			
Heat Detector	1st Above ceiling in C-109			
Heat Detector	1st Above ceiling in C-1118			
Heat Detector	1st Above ceiling in C-1119			
Heat Detector	1st Above ceiling in C-113			
Heat Detector	1st Above ceiling in D-1127A			
Heat Detector	1st Above ceiling in D-1127B			
Heat Detector	1st Above ceiling in Eng dept. B1106 rm b120			
Heat Detector	1st Above ceiling in Eng dept. B1106 rm b121			
Heat Detector	2nd Above ceiling in B-2227			
Heat Detector	2nd Above ceiling in B-223			
Heat Detector	2nd Above ceiling in B-2232			
Heat Detector	2nd Above ceiling in B-2236			

Building: Montgomery High School		Control Panel: 2 - EST EST-3		
<p><i>The Inspection &amp; Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time &amp; date at which testing occurred.</i></p>				
Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Control Panel	1st Room F117	Tested	2:30:29 PM	10/03/2018

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Control Panel	1st Admin. building Room D17	Tested	1:53:06 PM	10/03/2018
Control Panel	1st on stage Room A108C storage	Tested	1:11:31 PM	10/03/2018
Control Panel	2nd Room B258 electrical room	Tested	12:31:47 PM	10/03/2018
<b>Initiating</b>				
Heat Detector	2nd ABV CLG Classroom E-2314	Tested	8:56:49 AM	12/10/2018
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2309	Tested	9:01:07 AM	12/10/2018
Pull Station	1st Exit Room H101 exit H20	Tested	8:47:30 AM	10/03/2018
Pull Station	1st Hall C114 By Control Rm C-113	Tested	12:26:44 PM	10/04/2018
Pull Station	1st At exit b15 in stairwell b2	Tested	12:21:52 PM	10/04/2018
Pull Station	1st At exit d53 stairwell d1	Tested	7:57:16 AM	12/17/2018
Pull Station	1st B133 passage by exit	Tested	12:19:53 PM	10/04/2018
Pull Station	1st B150 passage by exit	Tested	12:31:05 PM	10/04/2018
Pull Station	1st By exit b12	Tested	12:24:23 PM	10/04/2018
Pull Station	1st By exit b13	Tested	12:24:55 PM	10/04/2018
Pull Station	1st By exit b14	Tested	12:23:01 PM	10/04/2018
Pull Station	1st By exit b16	Tested	12:21:31 PM	10/04/2018
Pull Station	1st Cafe exit to hall by d-1120	Tested	12:32:24 PM	10/04/2018
Pull Station	1st Cafe exit to hall by d-115	Tested	1:14:39 PM	10/04/2018
Pull Station	1st Cafe exit to hall by e-1110	Tested	1:15:04 PM	10/04/2018
Pull Station	1st Cafe exit to hall by stairwell e-1	Tested	1:10:14 PM	10/04/2018
Pull Station	1st Cafe exit to parking lot d51	Tested	1:09:54 PM	10/04/2018
Pull Station	1st Cafe exit to parking lot d52	Tested	1:09:34 PM	10/04/2018
Pull Station	1st Cafe exit to stairwell d-1	Tested	1:09:12 PM	10/04/2018
Pull Station	1st Hall by b1117	Tested	12:21:11 PM	10/04/2018
Pull Station	1st Hall by b113	Tested	12:23:41 PM	10/04/2018
Pull Station	1st Hall by d121 serving kitchen	Tested	12:15:08 PM	10/04/2018
Pull Station	1st Hall by exit D19	Tested	12:15:30 PM	10/04/2018
Pull Station	1st Hall by h101	Tested	12:14:53 PM	10/04/2018
Pull Station	1st Hall exit D17	Tested	12:18:14 PM	10/04/2018
Pull Station	1st Hall exit D18	Tested	12:17:33 PM	10/04/2018
Pull Station	1st Hall outside d1129 by stair d3	Tested	12:17:51 PM	10/04/2018
Pull Station	1st In D1129 by exit	Tested	2:12:14 PM	10/04/2018
Pull Station	1st In D121 serving area exit to cafeteria	Tested	1:11:55 PM	10/04/2018
Pull Station	1st In D121 serving area exit to hall	Tested	1:13:23 PM	10/04/2018
Pull Station	1st In D121 serving kitchen by D116 custodian clst	Tested	2:09:42 PM	10/04/2018
Pull Station	1st In D121 serving kitchen by D119 storage	Tested	1:12:45 PM	10/04/2018
Pull Station	1st In D121 serving kitchen exit	Tested	12:15:57 PM	10/04/2018
Pull Station	1st Lobby by D134 entrance	Tested	1:08:25 PM	10/04/2018
Pull Station	1st Stair b1 landing	Tested	12:24:39 PM	10/04/2018
Pull Station	1st stairwell b2 landing	Tested	12:22:13 PM	10/04/2018
Smoke Detector	1st Hall by D1127B	Tested/Cleaned	10:19:48 AM	10/04/2018
Smoke Detector	1st By snack shack D-134A	Tested/Cleaned	10:22:33 AM	10/04/2018

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
Smoke Detector	1st Hall by ctr by D1129	Tested/Cleaned	10:19:44 AM	10/04/2018
Smoke Detector	1st Hall by kitchen passage	Tested/Cleaned	10:19:44 AM	10/04/2018
Smoke Detector	1st Hall D-129 by faculty dining D-1120	Tested/Cleaned	10:22:34 AM	10/04/2018
Smoke Detector	1st Hall D-129 by faculty dining D-1120	Tested/Cleaned	10:22:34 AM	10/04/2018
Smoke Detector	1st Hall D-138 by cafe front	Tested/Cleaned	10:22:29 AM	10/04/2018
Smoke Detector	1st Hall D-138 by cafe front	Tested/Cleaned	10:22:30 AM	10/04/2018
Smoke Detector	1st Hall D-138 by cafe front	Tested/Cleaned	10:22:31 AM	10/04/2018
Smoke Detector	1st Hall D-138 by cafe front	Tested/Cleaned	10:22:31 AM	10/04/2018
Smoke Detector	1st Hall D-138 by stair D-1	Tested/Cleaned	10:22:32 AM	10/04/2018
Smoke Detector	1st Hall D-139 by dishwashing D-140	Tested/Cleaned	10:22:28 AM	10/04/2018
Smoke Detector	1st Hall D-139 by stair E-1	Tested/Cleaned	10:22:29 AM	10/04/2018
Smoke Detector	1st Hall D-143 by serving D-121	Tested/Cleaned	10:22:20 AM	10/04/2018
Smoke Detector	1st Hall D-143 by serving D-121	Tested/Cleaned	10:22:21 AM	10/04/2018
Smoke Detector	1st Passage D142 by serving D-121	Tested/Cleaned	10:22:35 AM	10/04/2018
Smoke Detector	1st Passage D142 by serving D-121	Tested/Cleaned	10:22:36 AM	10/04/2018
Smoke Detector	1st Vending area D-136	Tested/Cleaned	10:22:32 AM	10/04/2018
Smoke Detector	1st Vending area D-141	Tested/Cleaned	10:22:21 AM	10/04/2018
Smoke Detector	1st Vending area D-141	Tested/Cleaned	10:22:27 AM	10/04/2018
Device Type	Location	Service	Time	Date
<b><i>Untested</i></b>				
<b>Initiating</b>				
Heat Detector	1st Above ceiling hall B132 by classroom B1108			
Heat Detector	1st Above ceiling hall B132 by classroom B1115			
Heat Detector	1st Above ceiling hall B132 by resource room B1109			
Heat Detector	1st Above ceiling hall B143 by classroom B1119			
Heat Detector	1st Above ceiling hall B143 by classroom B1121			
Heat Detector	1st Above ceiling hall B143 by classroom B1125			
Heat Detector	1st Above ceiling hall B143 by classroom D1127B			
Heat Detector	1st Above ceiling hall D102 by custodial closet D131			
Heat Detector	1st Above ceiling hall D102 by stair D3 vestibule			
Heat Detector	1st Above ceiling hall D102 center by media center			
Heat Detector	1st Above ceiling hall D102 west by media center			
Heat Detector	1st Above ceiling hall D104 by room D1129			
Heat Detector	1st Above ceiling hall D104 exit by stair D3			
Heat Detector	1st Above ceiling hall D105 by Kitchen passage D111			
Heat Detector	1st Above ceiling hall D105 center by room D1129			
Heat Detector	1st Above ceiling hall D144 by IDF6 room D115			
Heat Detector	1st Above ceiling vestibule B122A by classroom B1111			
Heat Detector	1st Above ceiling vestibule B122A hall by classroom B1111			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	1st Above ceiling vestibule B135A by stair B2			
Heat Detector	2nd ABV CLG Classroom E-2303			
Heat Detector	2nd ABV CLG Classroom E-2304			
Heat Detector	2nd ABV CLG Classroom E-2305			
Heat Detector	2nd ABV CLG Classroom E-2306			
Heat Detector	2nd ABV CLG Classroom E-2307			
Heat Detector	2nd ABV CLG Classroom E-2308			
Heat Detector	2nd ABV CLG Classroom E-2309			
Heat Detector	2nd ABV CLG Classroom E-2310			
Heat Detector	2nd ABV CLG Classroom E-2311			
Heat Detector	2nd ABV CLG Classroom E-2312			
Heat Detector	2nd ABV CLG Classroom E-2313			
Heat Detector	2nd ABV CLG Classroom E-2316			
Heat Detector	2nd ABV CLG Conference Rm E-2300			
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2305			
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2307			
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2309			
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2311			
Heat Detector	2nd ABV CLG Hall E-234 By Classroom E-2313			
Heat Detector	2nd ABV CLG Hall E-234 By Office E-2302			
Heat Detector	2nd ABV CLG Hall E-234 Elevator 2 Lobby			
Heat Detector	2nd ABV CLG Office E-2302			
Heat Detector	2nd ABV CLG Prep Room E-204			
Heat Detector	2nd ABV CLG Prep Room E-211			
Heat Detector	2nd ABV CLG Prep Room E-212			
Heat Detector	2nd ABV CLG Prep Room E-217			
Heat Detector	2nd ABV CLG Prep Room E-218			
Heat Detector	2nd ABV CLG Prep Room E-229			
Heat Detector	2nd ABV CLG Prep Room E-230			

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Initiating</b>				
Pull Station	1st Auditorium A104 main entrance center	Tested	12:54:00 PM	10/04/2018
Pull Station	1st Auditorium A104 north center exit	Tested	12:53:41 PM	10/04/2018
Pull Station	1st Auditorium A104 north exit by A2204	Tested	2:17:05 PM	10/04/2018
Pull Station	1st Auditorium A104 north ramp 109 by stage	Tested	12:52:32 PM	10/04/2018
Pull Station	1st Auditorium A104 south center exit	Tested	12:55:53 PM	10/04/2018
Pull Station	1st Auditorium A104 south exit by A2208	Tested	2:15:10 PM	10/04/2018
Pull Station	1st Auditorium A104 south ramp 105 by stage	Tested	2:20:07 PM	10/04/2018
Pull Station	1st Exit instrumental room A1123	Tested	2:28:23 PM	10/04/2018
Pull Station	1st Exit kiln room A1187	Tested	12:59:52 PM	10/04/2018
Pull Station	1st Exit vocal music Rm A1134	Tested	12:40:34 PM	10/04/2018
Pull Station	1st Hall A122 by music room A1123	Tested	12:37:57 PM	10/04/2018
Pull Station	1st Hall by a1193 at exit a5	Tested	1:00:37 PM	10/04/2018
Pull Station	1st Hall By a1194 at exit a2	Tested	12:59:11 PM	10/04/2018
Pull Station	1st In c109 TV room	Tested	2:32:36 PM	10/04/2018
Pull Station	1st In classroom c1100	Tested	12:27:08 PM	10/04/2018
Pull Station	1st In lobby By exit b11	Tested	12:26:14 PM	10/04/2018
Pull Station	1st In Main office at a-1000 admin entrance	Tested	1:04:18 PM	10/04/2018
Pull Station	1st In Main office at entrance	Tested	1:06:18 PM	10/04/2018
Pull Station	1st In Main office by a-183a	Tested	1:03:11 PM	10/04/2018
Pull Station	1st In passage c106	Tested	12:27:39 PM	10/04/2018
Pull Station	1st Lobby by work area a1001	Tested	1:05:45 PM	10/04/2018
Pull Station	1st Media center c1000	Tested	12:33:29 PM	10/04/2018
Pull Station	1st North lobby by a1000 exit a1	Tested	1:06:35 PM	10/04/2018
Pull Station	1st Orchestra pit by stair A1	Tested	2:25:35 PM	10/04/2018
Pull Station	1st Orchestra pit by stair A2	Tested	2:25:53 PM	10/04/2018
Pull Station	1st Painting drawing A1190 exit	Tested	1:01:30 PM	10/04/2018
Pull Station	1st Passage A117 stage rear exit	Tested	12:44:22 PM	10/04/2018
Pull Station	1st Passage A128 to music A1123	Tested	12:39:28 PM	10/04/2018
Pull Station	1st Passage by c101	Tested	12:35:59 PM	10/04/2018
Pull Station	1st Passage Instrumental Rm A1123	Tested	12:38:34 PM	10/04/2018
Pull Station	1st Passage vocal music Rm A1134	Tested	12:40:59 PM	10/04/2018
Pull Station	1st Practice area A130A	Tested	12:39:52 PM	10/04/2018
Pull Station	1st Scene shop A1121	Tested	12:43:17 PM	10/04/2018
Pull Station	1st Stage A108 north exit	Tested	12:51:40 PM	10/04/2018
Pull Station	1st Stage A108 south exit	Tested	12:41:39 PM	10/04/2018
Pull Station	1st Stage electric room A120	Tested	12:50:51 PM	10/04/2018
Smoke Detector	1st Orchestra pit by chair lift elev.	Tested/Cleaned	10:23:50 AM	10/04/2018
Smoke Detector	1st Orchestra pit by north stair A1	Tested/Cleaned	10:23:51 AM	10/04/2018
Smoke Detector	1st Orchestra pit top of north stair A1	Tested/Cleaned	10:23:51 AM	10/04/2018
Smoke Detector	1st Orchestra pit top of south stair A2	Tested/Cleaned	10:23:50 AM	10/04/2018
Smoke Detector	1st Passage by faculty men's Rm A131B	Tested/Cleaned	10:23:47 AM	10/04/2018
Smoke Detector	1st Passage by music office A124	Tested/Cleaned	10:23:44 AM	10/04/2018
Smoke Detector	1st Passage by music office A126	Tested/Cleaned	10:23:48 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Passage by practice rooms A130	Tested/Cleaned	10:23:46 AM	10/04/2018
Smoke Detector	1st Room A1134 practice area A130A	Tested/Cleaned	10:23:49 AM	10/04/2018
Smoke Detector	1st Room A1134 practice area A130A	Tested/Cleaned	10:23:49 AM	10/04/2018



*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Initiating</b>				
Pull Station	1st NE Hall Exit By Aux Gym	Tested	9:29:16 AM	10/03/2018
Pull Station	1st Vestibule F-149 By Aux Gym F1100	Tested	9:29:53 AM	10/03/2018
Pull Station	1st By exit e46	Tested	9:31:13 AM	10/03/2018
Pull Station	1st By exit e47	Tested	9:31:55 AM	10/03/2018
Pull Station	1st By exit e48	Tested	10:16:43 AM	10/03/2018
Pull Station	1st By exit e49	Tested	10:17:10 AM	10/03/2018
Pull Station	1st By exit e50 in lobby by stair e1	Tested	10:17:38 AM	10/03/2018
Pull Station	1st By exit e51 stairwell e1 landing	Tested	7:57:24 AM	12/17/2018
Pull Station	1st By exit f29	Tested	9:38:55 AM	10/03/2018
Pull Station	1st By exit g24	Tested	9:35:23 AM	10/03/2018
Pull Station	1st F1108 exit	Tested	9:57:00 AM	10/03/2018
Pull Station	1st H104 boiler room	Tested	10:07:47 AM	10/03/2018
Pull Station	1st H104 exit h23	Tested	10:08:33 AM	10/03/2018
Pull Station	1st H105 electric room inside h104	Tested	10:09:13 AM	10/03/2018
Pull Station	1st Hall by e1154	Tested	10:02:48 AM	10/03/2018
Pull Station	1st Hall by g135	Tested	9:37:00 AM	10/03/2018
Pull Station	1st Hall by h104	Tested	9:34:22 AM	10/03/2018
Pull Station	1st Hall by locker room e1127	Tested	9:32:57 AM	10/03/2018
Pull Station	1st Hall e169 to f148 by gym	Tested	9:30:38 AM	10/03/2018
Pull Station	1st Hall east between main and aux gym	Tested	9:45:56 AM	10/03/2018
Pull Station	1st Hall top of ramp to pool	Tested	9:34:53 AM	10/03/2018
Pull Station	1st Hall west between main and aux gym	Tested	9:46:53 AM	10/03/2018
Pull Station	1st In e168 snack bar	Tested	2:01:17 PM	10/04/2018
Pull Station	1st In f1108	Tested	9:57:39 AM	10/03/2018
Pull Station	1st In f1116 north	Tested	9:54:51 AM	10/03/2018
Pull Station	1st In f1116 south	Tested	9:56:01 AM	10/03/2018
Pull Station	1st In f1130 at exit	Tested	9:25:01 AM	10/03/2018
Pull Station	1st In f1154 by exit f34	Tested	9:53:34 AM	10/03/2018
Pull Station	1st In f133 b&w dark room	Tested	1:53:20 PM	10/04/2018
Pull Station	1st In f134 color dark room	Tested	1:52:17 PM	10/04/2018
Pull Station	1st In hall by exit f32	Tested	9:19:39 AM	10/03/2018
Pull Station	1st In hall by f1142	Tested	9:17:56 AM	10/03/2018
Pull Station	1st In hall by f153b boiler	Tested	1:40:38 PM	10/04/2018
Pull Station	1st In hall by f163	Tested	9:14:39 AM	10/03/2018
Pull Station	1st Lobby exit by elevator 2	Tested	9:13:39 AM	10/03/2018
Pull Station	1st Main gym E1142 N East center	Tested	10:13:52 AM	10/03/2018
Pull Station	1st Main gym E1142 N East corner	Tested	10:13:19 AM	10/03/2018
Pull Station	1st Main gym E1142 N West center	Tested	10:12:15 AM	10/03/2018
Pull Station	1st Main gym E1142 N West corner	Tested	10:12:39 AM	10/03/2018
Pull Station	1st Main gym E1142 S East center	Tested	10:14:25 AM	10/03/2018
Pull Station	1st Main gym E1142 S East corner	Tested	10:14:47 AM	10/03/2018
Pull Station	1st Main gym E1142 S West center	Tested	10:11:43 AM	10/03/2018
Pull Station	1st Main gym E1142 S West corner	Tested	10:10:43 AM	10/03/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st N East exit aux gym F1100	Tested	9:59:20 AM	10/03/2018
Pull Station	1st N West exit aux gym F1100	Tested	10:01:35 AM	10/03/2018
Pull Station	1st North exit aux gym F1100	Tested	9:59:52 AM	10/03/2018
Pull Station	1st Pool exit g25	澦 瑾 瓘 9:37:27	9:37:27 AM	10/03/2018
Pull Station	1st S East exit aux gym F1100	Tested	10:00:23 AM	10/03/2018
Pull Station	1st S West exit aux gym F1100	Tested	10:02:07 AM	10/03/2018
Pull Station	1st SE hall by aux gym f1100	Tested	1:56:35 PM	10/04/2018
Pull Station	1st Stair e153 to pool	Tested	9:36:31 AM	10/03/2018
Pull Station	1st Stairwell e2 landing by exit	Tested	9:13:08 AM	10/03/2018
Smoke Detector	1st Entry hall boys locker Rm E1135	Tested/Cleaned	10:23:53 AM	10/04/2018
Smoke Detector	1st Passage boys locker Rm E1135	Tested/Cleaned	10:23:52 AM	10/04/2018
Smoke Detector	1st Passage girls locker Rm E1127	Tested/Cleaned	10:23:52 AM	10/04/2018
Device Type	Location	Service	Time	Date
<i>Untested</i>				
<b>Initiating</b>				
Heat Detector	1st Above ceiling hall E124 by Storage room E122			

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Initiating</b>				
Heat Detector	2nd Above Ceiling Alcove Men's Rm C209	Tested	11:29:30 AM	12/11/2018
Heat Detector	2nd Above Ceiling Alcove Men's Rm E226	Tested	11:29:48 AM	12/11/2018
Heat Detector	2nd Above Ceiling Alcove Womens Rm E222	Tested	11:29:46 AM	12/11/2018
Heat Detector	2nd Above Ceiling Book Storage C210	Tested	11:29:30 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom B2211	Tested	11:28:30 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom B2212	Tested	11:28:28 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom B2213	Tested	11:28:34 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom B2214	Tested	11:28:32 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom B2216	Tested	11:28:35 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom C2207	Tested	11:29:28 AM	12/11/2018
Heat Detector	2nd Above Ceiling Classroom C2210	Tested	11:29:26 AM	12/11/2018
Heat Detector	2nd Above Ceiling Computer Lab C2209	Tested	11:29:25 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B202 By Small Group D2203	Tested	11:29:23 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Book Storage C210	Tested	11:29:29 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Classroom C2207	Tested	11:29:27 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D202	Tested	11:28:55 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D202	Tested	11:28:59 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D202	Tested	11:29:05 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D202 By Cust Rm B260	Tested	11:29:12 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D202 By Stair D3	Tested	11:29:11 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D208	Tested	11:29:41 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D208	Tested	11:29:42 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D208 Intersection To Area E	Tested	11:29:39 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D209	Tested	11:29:40 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D209	Tested	11:29:40 AM	12/11/2018
Heat Detector	2nd Above Ceiling IDF 11 Rm E201	Tested	11:29:44 AM	12/11/2018
Heat Detector	2nd Above Ceiling IDF 12 Rm E223	Tested	11:29:47 AM	12/11/2018
Heat Detector	2nd Above Ceiling Men's Rm B262	Tested	11:29:17 AM	12/11/2018
Heat Detector	2nd Above Ceiling Men's Rm C209	Tested	11:29:32 AM	12/11/2018
Heat Detector	2nd Above Ceiling Men's Rm E226	Tested	11:29:49 AM	12/11/2018
Heat Detector	2nd Above Ceiling Resource Rm A2202	Tested	11:28:23 AM	12/11/2018
Heat Detector	2nd Above Ceiling Staff Restroom E224	Tested	11:29:47 AM	12/11/2018
Heat Detector	2nd Above Ceiling Stair B1	Tested	11:28:40 AM	12/11/2018
Heat Detector	2nd Above Ceiling Stair D1	Tested	11:29:43 AM	12/11/2018
Heat Detector	2nd Above Ceiling Stair E1	Tested	11:29:43 AM	12/11/2018
Heat Detector	2nd Above Ceiling VP D20	Tested	11:28:25 AM	12/11/2018
Heat Detector	2nd Above Ceiling VP Secretary D21	Tested	11:28:24 AM	12/11/2018
Heat Detector	2nd Above Ceiling Womens Rm B259	Tested	11:29:15 AM	12/11/2018
Heat Detector	2nd Above Ceiling Womens Rm C207	Tested	11:29:33 AM	12/11/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	2nd Above Ceiling Womens Rm E222	Tested	11:29:45 AM	12/11/2018
Heat Detector	2nd Above Ceiling Alcove Men's Rm B262	Tested	11:29:16 AM	12/11/2018
Heat Detector	2nd Above Ceiling Alcove Womens Rm B259	Tested	11:29:14 AM	12/11/2018
Heat Detector	2nd Above Ceiling Foreign Language C2205 Alcove	Tested	11:29:36 AM	12/11/2018
Heat Detector	2nd Above Ceiling Foreign Language C2205 Conf Rm	Tested	11:29:37 AM	12/11/2018
Heat Detector	2nd Above Ceiling Foreign Language C2205 Men's Rm	Tested	11:29:35 AM	12/11/2018
Heat Detector	2nd Above Ceiling Foreign Language C2205 Office	Tested	11:29:36 AM	12/11/2018
Heat Detector	2nd Above Ceiling Foreign Language C2205 Womens Rm	Tested	11:29:33 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Classroom B2211	Tested	11:28:33 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Computer Lab C2209	Tested	11:28:26 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Projector Rm A203	Tested	11:29:18 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Resource Rm A2202	Tested	11:29:19 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B204 By Stair B1	Tested	11:28:37 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall B225 By Classroom B2216	Tested	11:28:41 AM	12/11/2018
Heat Detector	2nd Above Ceiling Hall D209 Intersection To Area C	Tested	11:28:27 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229 Conf Rm	Tested	11:28:45 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229 Kitchen	Tested	11:28:46 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229 Men's Rm	Tested	11:28:44 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229 Office	Tested	11:28:46 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229 Womens Rm	Tested	11:28:43 AM	12/11/2018
Heat Detector	2nd Above Ceiling Math Dept C2229	Tested	11:28:48 AM	12/11/2018
Pull Station	1st Landing lecture room A2204	Tested	2:17:41 PM	10/04/2018
Pull Station	1st Landing lecture room A2208	Tested	2:16:08 PM	10/04/2018
Pull Station	2nd in hall above cafe near c-221	Tested	9:07:38 AM	10/03/2018
Pull Station	2nd in hall above cafe near e-2300	Tested	9:06:31 AM	10/03/2018
Pull Station	2nd in hall above cafe near exit by stairwell d-1	Tested	9:04:06 AM	10/03/2018
Pull Station	2nd in hall by b-2238	Tested	2:35:49 PM	10/04/2018
Pull Station	2nd in hall by c-2207	Tested	8:59:55 AM	10/03/2018
Pull Station	2nd in hall by elevator 1	Tested	9:00:27 AM	10/03/2018
Pull Station	2nd in hall outside d-2203	Tested	9:01:10 AM	10/03/2018
Pull Station	2nd in hall outside stairwell b1	Tested	8:58:47 AM	10/03/2018
Pull Station	2nd in hall outside stairwell b1 near b-2213	Tested	8:59:06 AM	10/03/2018
Pull Station	2nd in hall outside stairwell b1 near lockers	Tested	8:58:09 AM	10/03/2018
Pull Station	2nd in hall outside stairwell b2	Tested	8:56:21 AM	10/03/2018
Pull Station	2nd in hall outside stairwell d-1	Tested	9:03:24 AM	10/03/2018
Pull Station	2nd in hall outside stairwell e-2	Tested	9:08:50 AM	10/03/2018
Pull Station	2nd in hall outside stairwell e-2 by e-234a	Tested	9:11:58 AM	10/03/2018
Pull Station	2nd Top of stairwell d-3 by roof access	Tested	8:53:29 AM	10/03/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	2nd Top of stairwell d-3 in hall	Tested	8:53:51 AM	10/03/2018
Smoke Detector	2nd Hall B204 at Stair B1	Tested/Cleaned	10:23:00 AM	10/04/2018
Smoke Detector	2nd Hall B204 by book storage C210	Tested/Cleaned	10:23:04 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom A2206	Tested/Cleaned	10:23:05 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom B2211	Tested/Cleaned	10:23:01 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom B2212	Tested/Cleaned	10:23:02 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom B2216	Tested/Cleaned	10:23:00 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom C2207	Tested/Cleaned	10:23:04 AM	10/04/2018
Smoke Detector	2nd Hall B204 by classroom C2210	Tested/Cleaned	10:23:03 AM	10/04/2018
Smoke Detector	2nd Hall B204 by computer lab C2209	Tested/Cleaned	10:23:02 AM	10/04/2018
Smoke Detector	2nd Hall B204 by projector room A203	Tested/Cleaned	10:23:05 AM	10/04/2018
Smoke Detector	2nd Hall B204 by stair B1	Tested/Cleaned	10:22:39 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2215	Tested/Cleaned	10:22:42 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2217	Tested/Cleaned	10:22:43 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2218	Tested/Cleaned	10:22:40 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2220	Tested/Cleaned	10:22:41 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2226	Tested/Cleaned	10:22:43 AM	10/04/2018
Smoke Detector	2nd Hall B225 by classroom B2228	Tested/Cleaned	10:22:44 AM	10/04/2018
Smoke Detector	2nd Hall B225 by stair B2	Tested/Cleaned	10:22:48 AM	10/04/2018
Smoke Detector	2nd Hall B225 by storage room B212	Tested/Cleaned	10:22:41 AM	10/04/2018
Smoke Detector	2nd Hall B249 by classroom B2221	Tested/Cleaned	10:22:50 AM	10/04/2018
Smoke Detector	2nd Hall B249 by classroom B2227	Tested/Cleaned	10:22:52 AM	10/04/2018
Smoke Detector	2nd Hall B249 by classroom B2230	Tested/Cleaned	10:22:51 AM	10/04/2018
Smoke Detector	2nd Hall B249 by classroom B2232	Tested/Cleaned	10:22:51 AM	10/04/2018
Smoke Detector	2nd Hall B249 by classroom B2238	Tested/Cleaned	10:22:38 AM	10/04/2018
Smoke Detector	2nd Hall B249 by IDF9 room B255	Tested/Cleaned	10:22:53 AM	10/04/2018
Smoke Detector	2nd Hall B249 by office B21	Tested/Cleaned	10:22:49 AM	10/04/2018
Smoke Detector	2nd Hall D202 at stair D1	Tested/Cleaned	10:23:09 AM	10/04/2018
Smoke Detector	2nd Hall D202 by court yard/ media center	Tested/Cleaned	10:23:17 AM	10/04/2018
Smoke Detector	2nd Hall D202 by court yard/ media center	Tested/Cleaned	10:23:18 AM	10/04/2018
Smoke Detector	2nd Hall D202 by court yard/ media center	Tested/Cleaned	10:23:19 AM	10/04/2018
Smoke Detector	2nd Hall D202 by court yard/ media center	Tested/Cleaned	10:23:20 AM	10/04/2018
Smoke Detector	2nd Hall D202 by custodial closet B260	Tested/Cleaned	10:23:16 AM	10/04/2018
Smoke Detector	2nd Hall D202 by math dept. room C2229	Tested/Cleaned	10:23:16 AM	10/04/2018
Smoke Detector	2nd Hall D202 by small group D2203	Tested/Cleaned	10:23:21 AM	10/04/2018
Smoke Detector	2nd Hall D202 by stair D3	Tested/Cleaned	10:22:38 AM	10/04/2018
Smoke Detector	2nd Hall D202 by V.P. Secretary Rm D21	Tested/Cleaned	10:23:08 AM	10/04/2018
Smoke Detector	2nd Hall D202 lobby by room A2202	Tested/Cleaned	10:23:07 AM	10/04/2018
Smoke Detector	2nd Hall D202 lobby by room A2205	Tested/Cleaned	10:23:07 AM	10/04/2018
Smoke Detector	2nd Hall D204 by resource room A2202	Tested/Cleaned	10:23:06 AM	10/04/2018
Smoke Detector	2nd Hall D208 by building front	Tested/Cleaned	10:23:10 AM	10/04/2018
Smoke Detector	2nd Hall D208 by building front	Tested/Cleaned	10:23:31 AM	10/04/2018
Smoke Detector	2nd Hall D208 by building front	Tested/Cleaned	10:23:32 AM	10/04/2018
Smoke Detector	2nd Hall D208 by stair E1	Tested/Cleaned	10:23:11 AM	10/04/2018
Smoke Detector	2nd Hall D209 by area E	Tested/Cleaned	10:23:12 AM	10/04/2018
Smoke Detector	2nd Hall D209 by building rear	Tested/Cleaned	10:23:12 AM	10/04/2018
Smoke Detector	2nd Hall D209 by building rear	Tested/Cleaned	10:23:13 AM	10/04/2018
Smoke Detector	2nd Hall D209 by building rear	Tested/Cleaned	10:23:14 AM	10/04/2018
Smoke Detector	2nd Hall D209 by building rear	Tested/Cleaned	10:23:14 AM	10/04/2018
Smoke Detector	2nd Hall D209 intersection to area C	Tested/Cleaned	10:23:15 AM	10/04/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	2nd Hall D209 intersection to area E	Tested/Cleaned	10:23:11 AM	10/04/2018
Smoke Detector	2nd Hall E234 by chem storage E205	Tested/Cleaned	10:23:36 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2303	Tested/Cleaned	10:23:36 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2307	Tested/Cleaned	10:23:38 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2310	Tested/Cleaned	10:23:39 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2311	Tested/Cleaned	10:23:40 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2312	Tested/Cleaned	10:23:39 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2314	Tested/Cleaned	10:23:41 AM	10/04/2018
Smoke Detector	2nd Hall E234 by classroom E2316	Tested/Cleaned	10:23:41 AM	10/04/2018
Smoke Detector	2nd Hall E234 by elevator 2 lobby	Tested/Cleaned	10:23:42 AM	10/04/2018
Smoke Detector	2nd Hall E234 by prep room E211	Tested/Cleaned	10:23:37 AM	10/04/2018
Smoke Detector	2nd Hall E234 by prep room E212	Tested/Cleaned	10:23:37 AM	10/04/2018
Smoke Detector	2nd Hall E234 by stair E1	Tested/Cleaned	10:23:32 AM	10/04/2018
Smoke Detector	2nd Hall E234 elevator 2 lobby	Tested/Cleaned	10:23:43 AM	10/04/2018
Smoke Detector	2nd Stair B1 open area	Tested/Cleaned	10:22:58 AM	10/04/2018
Smoke Detector	2nd Stair B1 over steps	Tested/Cleaned	10:22:58 AM	10/04/2018
Smoke Detector	2nd stair B2 open area	Tested/Cleaned	10:22:47 AM	10/04/2018
Smoke Detector	2nd stair B2 over stairs	Tested/Cleaned	10:22:44 AM	10/04/2018
Smoke Detector	2nd stair D1 over steps	Tested/Cleaned	10:23:23 AM	10/04/2018
Smoke Detector	2nd Stair D3 over steps	Tested/Cleaned	10:22:36 AM	10/04/2018
Smoke Detector	2nd stair E2 over steps	Tested/Cleaned	10:23:44 AM	10/04/2018
Smoke Detector	2nd Top of landing Stair B1	Tested/Cleaned	10:22:59 AM	10/04/2018
Smoke Detector	2nd Top of landing stair B2	Tested/Cleaned	10:22:47 AM	10/04/2018
Smoke Detector	2nd Top of landing stair D1	Tested/Cleaned	10:23:22 AM	10/04/2018
Smoke Detector	2nd Top of landing Stair D3	Tested/Cleaned	10:22:37 AM	10/04/2018
Smoke Detector	2nd Top of landing stair E2	Tested/Cleaned	10:23:43 AM	10/04/2018

# Service Summary

Generated by: BuildingReports.com

Building: Montgomery High School		
<p><i>The Service Summary section provides an overview of the services performed in this report.</i></p>		
Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Battery	Tested	26
Total		26
<b><i>Passed</i></b>		
Annunciator	Tested	8
Battery	Tested	7
Communicator	Tested	1
Control Panel	Tested	5
Duct Detector	Tested	31
Heat Detector	Tested	77
Power Supply	Tested	11
Pull Station	Tested	147
Smoke Detector	Tested/Cleaned	289
Tamper Switch	Tested	19
Waterflow Switch	Tested	12
Total		633
<b><i>Untested</i></b>		
Heat Detector		117
Total		750

# Auxiliary Functions Testing

Generated by: BuildingReports.com

Type	Location	Comment	ScanID	Simulated
<b>Passed</b>				
<b>Duct Detector</b>				
Air Duct	1st AHU2 in G116 test sw (F117)	Passed	33369068	<input type="checkbox"/>
Air Duct	1st MUA 1 kitchen prep D118 test sw (H101)	Passed	33369095	<input type="checkbox"/>
Air Duct	1st MUA 2 kitchen prep D118 test sw (H101)	Passed	33369096	<input type="checkbox"/>
Air Duct	1st RTU1 practice room A-130 test sw	Passed	33369076	<input type="checkbox"/>
Air Duct	1st RTU10 girls locker room test sw (F117)	Passed	33369070	<input type="checkbox"/>
Air Duct	1st RTU11 main lobby gym E-1142 test sw (F117)	Passed	33369071	<input type="checkbox"/>
Air Duct	1st RTU19 hall by aux. gym test sw (F117)	Passed	33369072	<input type="checkbox"/>
Air Duct	1st RTU2 scene shop A-1121 test sw	Passed	33369077	<input type="checkbox"/>
Air Duct	1st RTU23 hall by E2312 test sw (B258)	Passed	33369092	<input type="checkbox"/>
Air Duct	1st RTU24 main gym E-1142 test sw (F117)	Passed	33369073	<input type="checkbox"/>
Air Duct	1st RTU25 main gym east E-1142 test sw (F117)	Passed	33369074	<input type="checkbox"/>
Air Duct	1st RTU26 women's locker room G116 test sw (F117)	Passed	33369075	<input type="checkbox"/>
Air Duct	1st RTU27 admin return test sw	Passed	33369083	<input type="checkbox"/>
Air Duct	1st RTU27 admin supply test sw	Passed	33369082	<input type="checkbox"/>
Air Duct	1st RTU28 admin return test sw	Passed	33369085	<input type="checkbox"/>
Air Duct	1st RTU28 admin supply test sw	Passed	33369084	<input type="checkbox"/>
Air Duct	1st RTU3 hall A-122 by A-1137 test sw	Passed	33369078	<input type="checkbox"/>
Air Duct	1st RTU4 Hall by auditorium test sw	Passed	33369079	<input type="checkbox"/>
Air Duct	1st RTU5 H.S. Admin test sw	Passed	33369080	<input type="checkbox"/>
Air Duct	1st RTU6 Hall by stage test sw	Passed	33369081	<input type="checkbox"/>
Air Duct	1st RTU7 Family science D1129 test sw (H101)	Passed	33369097	<input type="checkbox"/>
Air Duct	1st RTU8 Prep/Serving D118/121 test sw (H101)	Passed	33369098	<input type="checkbox"/>
Air Duct	1st RTU9 trainers area test sw (F117)	Passed	33369069	<input type="checkbox"/>
Air Duct	2nd RTU12 hall B225 by B2228 test sw (B258)	Passed	33369086	<input type="checkbox"/>
Air Duct	2nd RTU13 hall by B2218 test sw (B258)	Passed	33369087	<input type="checkbox"/>
Air Duct	2nd RTU15 hall / media center test sw (B258)	Passed	33369088	<input type="checkbox"/>
Air Duct	2nd RTU16 hall by A2206 test sw (B258)	Passed	33369089	<input type="checkbox"/>
Air Duct	2nd RTU17 hall by C2207 test sw (B258)	Passed	33369090	<input type="checkbox"/>
Air Duct	2nd RTU18 hall by B2227 test sw (B258)	Passed	33369091	<input type="checkbox"/>
Air Duct	2nd RTU22 hall by E2308 test sw (B258)	Passed	33369093	<input type="checkbox"/>
Air Duct	2nd RTU23 hall by E2312 test sw (B258)	Passed	33369094	<input type="checkbox"/>



# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery High School Control Panel: 1 - EST EST-3

The Control & Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.

Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<b>Passed</b>							
<b>Battery</b>							
Sealed Lead Acid	1st Admin building Room D17 in BPS	7	12				
Sealed Lead Acid	1st Admin building Room D17 in BPS	7	12				
Sealed Lead Acid	1st Admin building Room D17 in communicator	4.5	12				
Sealed Lead Acid	1st Room F117 in FACP	18	12				
Sealed Lead Acid	1st Room F117 in FACP	18	12				
Sealed Lead Acid	2nd Room B258 top BPS	7	12				
Sealed Lead Acid	2nd Room B258 top BPS	7	12				
<b>Failed/Other</b>							
<b>Battery</b>							
Sealed Lead Acid	1st Admin building Room D17 in FACP	18	12				
Sealed Lead Acid	1st Admin building Room D17 in FACP	18	12				
Sealed Lead Acid	1st H-101 in FACP	18	12				
Sealed Lead Acid	1st H-101 in FACP	18	12				
Sealed Lead Acid	1st Room A108C bottom BPS	7	12				
Sealed Lead Acid	1st Room A108C bottom BPS	7	12				
Sealed Lead Acid	1st Room A108C in FACP	18	12				
Sealed Lead Acid	1st Room A108C in FACP	18	12				
Sealed Lead Acid	1st Room A108C top BPS	7	12				
Sealed Lead Acid	1st Room A108C top BPS	7	12				
Sealed Lead Acid	1st Room A137 storage	7	12				
Sealed Lead Acid	1st Room A137 storage	7	12				
Sealed Lead Acid	1st Room B127 storage	7	12				
Sealed Lead Acid	1st Room B127 storage	7	12				
Sealed Lead Acid	1st Room E119 BPS	7	12				
Sealed Lead Acid	1st Room E119 BPS	7	12				
Sealed Lead Acid	1st Room F117 next to FACP	7	12				
Sealed Lead Acid	1st Room F117 next to FACP	7	12				
Sealed Lead Acid	1st Room H101 next to FACP	7	12				
Sealed Lead Acid	1st Room H101 next to FACP	7	12				
Sealed Lead Acid	2nd Room B212 BPS	7	12				
Sealed Lead Acid	2nd Room B212 BPS	7	12				

Sealed Lead Acid	2nd Room B258 bottom BPS	7	12
Sealed Lead Acid	2nd Room B258 bottom BPS	7	12
Sealed Lead Acid	2nd Room B258 electrical closet in FACP	18	12
Sealed Lead Acid	2nd Room B258 electrical closet in FACP	18	12

# Inventory & Warranty Report

Generated by: [BuildingReports.com](http://BuildingReports.com)

Building: Montgomery High School		Control Panel: 1 - EST EST-3		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	25.87%	194	
Control Panel	Control	0.67%	5	
Pull Station	Initiating	19.60%	147	
Power Supply	Control	1.47%	11	
Battery	Control	4.40%	33	
Annunciator	Control	1.07%	8	
Tamper Switch	Supervisory	2.53%	19	
Waterflow Switch	Initiating	1.60%	12	
Communicator	Control	0.13%	1	
Smoke Detector	Initiating	38.53%	289	
Duct Detector	Initiating	4.13%	31	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 90 Days - 1 Year</i></b>				
<b>Interstate</b>				
Battery	2	SLA1116	Sealed Lead Acid	04/01/2018
<b><i>In Service - 1 Year to 2 Years</i></b>				
<b>Power Patrol</b>				
Battery	2	SEC1075	Sealed Lead Acid	04/27/2017
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Power Supply	10	BPS10		12/27/2016
Power Supply	1	BPS10A		12/27/2016
Duct Detector	31	SIGA PS	Photoelectric	08/24/2016
Heat Detector	84	SIGA HRS	Combination	08/24/2016
Smoke Detector	181	SIGA PS	Photoelectric	08/24/2016
Control Panel	1	EST-3		08/22/2016
Pull Station	7	sig a 278	Dual Action	08/22/2016
<b><i>In Service - 5 Years to 10 Years</i></b>				
<b>Honeywell</b>				
Communicator	1	IPGSM-4G	Digital Communicator	10/21/2011
<b>Power-Sonic</b>				
Battery	1	PS- 12180 F2	Sealed Lead Acid	10/21/2011
Battery	7	ps-12180 F2	Sealed Lead Acid	10/21/2011
<b>Ultra Tech</b>				
Battery	1	UT1240	Sealed Lead Acid	10/21/2011

<b>EST</b>				
Annunciator	2	LCD-3		06/21/2011
Annunciator	6	LCD-3	LCD Display	06/21/2011
<b>Kennedy Valve</b>				
Tamper Switch	14	butterfly valve		06/21/2011
<b>Potter Electric</b>				
Tamper Switch	5	OSYSU-2		06/21/2011
Waterflow Switch	12	PS10-2A		06/21/2011
<b>Ultra Tech</b>				
Battery	20	UT1270	Sealed Lead Acid	06/21/2011

Building: Montgomery High School		Control Panel: 2 - EST EST-3		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 5 Years to 10 Years</i></b>				
<b>EST</b>				
Control Panel	1	EST-3		06/21/2011

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Heat Detector	49	SIGA HRS	Combination	08/24/2016
Smoke Detector	20	SIGA PS	Photoelectric	08/24/2016
Pull Station	4	sig a 278	Dual Action	08/23/2016
Pull Station	22	sig a 278	Dual Action	08/22/2016
Pull Station	8	SIGA-278	Dual Action	08/22/2016
<b><i>In Service - 5 Years to 10 Years</i></b>				
<b>EST</b>				
Control Panel	3	EST-3		06/21/2011

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Smoke Detector	10	SIGA PS	Photoelectric	08/24/2016
Pull Station	6	sig 278	Dual Action	08/23/2016
Pull Station	27	sig 278	Dual Action	08/22/2016
Pull Station	3	SIGA-278	Dual Action	08/22/2016

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Heat Detector	1	SIGA HRS	Combination	08/24/2016
Smoke Detector	3	SIGA PS	Photoelectric	08/24/2016
Pull Station	52	sig a 278	Dual Action	08/22/2016



*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Heat Detector	60	SIGA HRS	Combination	08/24/2016
Smoke Detector	75	SIGA PS	Photoelectric	08/24/2016
Pull Station	16	sig a 278	Dual Action	08/23/2016
Pull Station	2	sig a 278	Dual Action	08/22/2016

# Zone Address Report

Generated by: BuildingReports.com

<b>Building: Montgomery High School</b>	<b>Control Panel: 1 - EST EST-3</b>
---	-------------------------------------

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 04</b>				
0006	Heat Detector	1st Above Ceiling Admin 138 AD137 Conf Rm Pupil Svc	Combination	49668569
0007	Heat Detector	1st Above Ceiling Admin Corr 122 at Office 108	Combination	46876295
0008	Heat Detector	1st Above Ceiling Admin Corr 122 at Storage 115	Combination	46876294
0009	Heat Detector	1st Above Ceiling Admin Corr 121	Combination	46876293
0010	Heat Detector	1st Above Ceiling Admin 115 AD03 Super Storage	Combination	49668570
0011	Heat Detector	1st Above Ceiling Admin 116 AD01 Lounge East	Combination	49668571
0012	Heat Detector	1st Above Ceiling Admin 117 AD02 Women's Lav East	Combination	49668572
0013	Heat Detector	1st Above Ceiling Admin 118 AD104 Men's Lav East	Combination	49668573
0014	Heat Detector	1st Above Ceiling Admin Corr 159 by 118 mens	Combination	46876292
0015	Heat Detector	1st Above Ceiling Admin Corridor 123	Combination	46876291
0016	Heat Detector	1st Above Ceiling Admin 114 AD107 Sm Conf Rm	Combination	46876319
0017	Heat Detector	1st Above Ceiling Admin Corr 159 by 148 Stor.	Combination	46876290
0018	Heat Detector	1st Above Ceiling Admin Corr 159 by 154 Stor.	Combination	46876289
0019	Heat Detector	1st Above Ceiling Admin Corr 177 at T 159	Combination	46876288
0020	Heat Detector	1st Above Ceiling Admin Corr 177 by 161 Mech Rm	Combination	46876318
0021	Heat Detector	1st Above Ceiling Admin Corr 176 by 165 Sec.	Combination	46876285
0022	Heat Detector	1st Above Ceiling Admin Corr 175	Combination	46876287
0023	Heat Detector	1st Above Ceiling Admin Corr 176 by 175 Sprink.	Combination	46876284
0024	Heat Detector	1st Above Ceiling Admin Corridor 178	Combination	46876283
0025	Heat Detector	1st Above Ceiling Admin 101 AD Lobby	Combination	46876317
0033	Heat Detector	1st Above Ceiling Admin 100 AD Vestibule	Combination	46876316
0037	Heat Detector	1st Above Ceiling Admin 110 AD108 Copy Rm	Combination	49668567
0050	Heat Detector	1st Above Ceiling Admin 145 AD-120	Combination	46876310

		Payroll		
0051	Heat Detector	1st Above Ceiling Admin 146 Woman's Lav West	Combination	46876312
0052	Heat Detector	1st Above Ceiling Admin 146A Woman's Lav West Alcove	Combination	46876311
0053	Heat Detector	1st Above Ceiling Admin 173 AD-119 Custodial Sup.	Combination	46876301
0054	Heat Detector	1st Above Ceiling Admin 172 AD-117 Grounds Sec.	Combination	46876302
0055	Heat Detector	1st Above Ceiling Admin 171 AD-118 Grounds Sec.	Combination	46876303
0056	Heat Detector	1st Above Ceiling Admin 169 AD-116 Transport Super	Combination	46876304
0057	Heat Detector	1st Above Ceiling Admin 168 AD-114 Purchasing	Combination	46876299
0058	Heat Detector	1st Above Ceiling Admin 167 AD-113 Purchasing WR	Combination	46876300
0059	Heat Detector	1st Above Ceiling Admin 177R AD-16 MIF Distrib. Rm	Combination	46876296
0060	Heat Detector	1st Above Ceiling Admin 177L AD-16 MIF Distrib. Rm	Combination	46876297
0061	Heat Detector	1st Above Ceiling Admin Corridor 179	Combination	46876282
0062	Heat Detector	1st Above Ceiling Admin 160 AD-14 Men's Lav West	Combination	46876298
0063	Heat Detector	1st Above Ceiling Admin 158 AD112 Meeting Rm	Combination	49668568
0064	Heat Detector	1st Above Ceiling Admin 162 AD12 Cust Clst West	Combination	46876315
0065	Heat Detector	1st Above Ceiling Admin 161 AD13 Mech Rm West	Combination	46876314
0066	Heat Detector	1st Above Ceiling Admin 157 AD-09 Lunch	Combination	46876306
0067	Heat Detector	1st Above Ceiling Admin 153 AD-08 kitchen	Combination	46876305
0068	Heat Detector	1st Above Ceiling Admin 152 AD-111 Asst. Bus. Admin	Combination	46876307
0069	Heat Detector	1st Above Ceiling Admin 151 AD-110 Bus. Admin	Combination	46876308
0070	Heat Detector	1st Above Ceiling Admin 150 AD-09 Exec. Sec. for BA	Combination	46876309
0071	Heat Detector	1st Above Ceiling Admin Corr 174 AD Vestibule	Combination	46876286
0101	Heat Detector	1st Above Ceiling Admin Corridor 124	Combination	46876313
0126	Pull Station	1st In f153b boiler room by exit ad35	Dual Action	33368990
<b>Zone/Circuit: 4</b>				
127	Pull Station	1st Admin corr. 179 by exit door	Dual Action	42626285
128	Pull Station	1st Admin transport 169 AD116 exit	Dual Action	42626283
129	Pull Station	1st Admin vestibule 174 exit	Dual Action	42626282
130	Pull Station	1st Admin corr. 177 by exit door	Dual Action	42626281
131	Pull Station	1st Admin vestibule 100 exit	Dual Action	42626280
149	Pull Station	1st Admin corr. 126	Dual Action	42626284

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
0007	Smoke Detector	1st Hall by D1127B	Photoelectric	33368882
0126	Pull Station	1st Hall by b1117	Dual Action	33368908
0127	Pull Station	1st B133 passage by exit	Dual Action	33368907
0128	Pull Station	1st By exit b16	Dual Action	33368909
0129	Pull Station	1st stairwell b2 landing	Dual Action	33369028
0130	Pull Station	1st At exit b15 in stairwell b2	Dual Action	33369029
0131	Pull Station	1st By exit b14	Dual Action	33368910
0132	Pull Station	1st Hall by b113	Dual Action	33368914
0133	Pull Station	1st By exit b13	Dual Action	33368916
0134	Pull Station	1st Stair b1 landing	Dual Action	33368917
0135	Pull Station	1st By exit b12	Dual Action	33368918
0136	Pull Station	1st Hall C114 By Control Rm C-113	Dual Action	33368922
0137	Pull Station	1st B150 passage by exit	Dual Action	33368906
0311	Smoke Detector	1st Hall by kitchen passage	Photoelectric	33368875
0312	Smoke Detector	1st Hall by ctr by D1129	Photoelectric	33368876
0376	Pull Station	1st Cafe exit to hall by stairwell e-1	Dual Action	42625867
0377	Pull Station	1st Cafe exit to hall by e-1110	Dual Action	42625865
0378	Pull Station	1st Cafe exit to hall by d-115	Dual Action	42625864
0379	Pull Station	1st Hall by h101	Dual Action	33368833
0380	Pull Station	1st Exit Room H101 exit H20	Dual Action	33368832
0397	Pull Station	1st Cafe exit to hall by d-1120	Dual Action	42625871
0398	Pull Station	1st Cafe exit to parking lot d51	Dual Action	42625868
0399	Pull Station	1st Cafe exit to parking lot d52	Dual Action	42625869
0401	Pull Station	1st At exit d53 stairwell d1	Dual Action	33369024
0402	Pull Station	1st Lobby by D134 entrance	Dual Action	33369023
0403	Pull Station	1st In D121 serving area exit to hall	Dual Action	33368839
0404	Pull Station	1st In D121 serving kitchen by D116 custodian clst	Dual Action	33368837
0406	Pull Station	1st In D121 serving area exit to cafeteria	Dual Action	33368840
0407	Pull Station	1st In D121 serving kitchen by D119 storage	Dual Action	33368838
0411	Pull Station	1st In D121 serving kitchen exit	Dual Action	33368836
0412	Pull Station	1st Hall by d121 serving kitchen	Dual Action	33368834
0413	Pull Station	1st Hall by exit D19	Dual Action	33368835
0414	Pull Station	1st In D1129 by exit	Dual Action	33368841
0417	Pull Station	1st Hall exit D18	Dual Action	33368842
0418	Pull Station	1st Hall outside d1129 by stair d3	Dual Action	33368843
0419	Pull Station	1st Hall exit D17	Dual Action	33368844
<b>Zone/Circuit: 2</b>				
0400	Pull Station	1st Cafe exit to stairwell d-1	Dual Action	42625870
252	Smoke Detector	1st Vending area D-141	Photoelectric	42625877
253	Smoke Detector	1st Vending area D-141	Photoelectric	42625876
254	Smoke Detector	1st Hall D-143 by serving D-121	Photoelectric	42625878
256	Smoke Detector	1st Hall D-143 by serving D-121	Photoelectric	42625879

257	Heat Detector	1st Above ceiling hall D144 by IDF6 room D115	Combination	33369138
263	Smoke Detector	1st Passage D142 by serving D-121	Photoelectric	42625890
265	Smoke Detector	1st Passage D142 by serving D-121	Photoelectric	42625891
267	Smoke Detector	1st Hall D-129 by faculty dining D-1120	Photoelectric	42625889
269	Smoke Detector	1st Hall D-129 by faculty dining D-1120	Photoelectric	42625888
276	Smoke Detector	1st Vending area D-136	Photoelectric	42625886
280	Smoke Detector	1st By snack shack D-134A	Photoelectric	42625887
282	Smoke Detector	1st Hall D-138 by stair D-1	Photoelectric	42625885
284	Smoke Detector	1st Hall D-138 by cafe front	Photoelectric	42625884
286	Smoke Detector	1st Hall D-138 by cafe front	Photoelectric	42625883
287	Smoke Detector	1st Hall D-138 by cafe front	Photoelectric	42625882
289	Smoke Detector	1st Hall D-138 by cafe front	Photoelectric	42625881
29	Heat Detector	1st Above ceiling hall B143 by classroom B1125	Combination	33369149
290	Smoke Detector	1st Hall D-139 by stair E-1	Photoelectric	42625880
292	Smoke Detector	1st Hall D-139 by dishwashing D-140	Photoelectric	42625875
310	Heat Detector	1st Above ceiling hall D105 by Kitchen passage D111	Combination	33369140
313	Heat Detector	1st Above ceiling hall D105 center by room D1129	Combination	33369141
32	Heat Detector	1st Above ceiling hall B143 by classroom B1121	Combination	33369150
320	Heat Detector	1st Above ceiling hall D104 exit by stair D3	Combination	33369142
323	Heat Detector	1st Above ceiling hall D102 by stair D3 vestibule	Combination	33369144
324	Heat Detector	1st Above ceiling hall D104 by room D1129	Combination	33369143
329	Heat Detector	1st Above ceiling hall D102 by custodial closet D131	Combination	33369145
331	Heat Detector	1st Above ceiling hall D102 west by media center	Combination	33369146
334	Heat Detector	1st Above ceiling hall D102 center by media center	Combination	33369147
34	Heat Detector	1st Above ceiling hall B143 by classroom B1119	Combination	33369151
38	Heat Detector	1st Above ceiling vestibule B135A by stair B2	Combination	33369152
4	Heat Detector	1st Above ceiling hall B143 by classroom D1127B	Combination	33369148
49	Heat Detector	1st Above ceiling hall B132 by classroom B1115	Combination	33369153
53	Heat Detector	1st Above ceiling hall B132 by classroom B1108	Combination	33369154
59	Heat Detector	1st Above ceiling vestibule B122A by classroom B1111	Combination	33369157
62	Heat Detector	1st Above ceiling vestibule B122A hall by classroom B1111	Combination	33369156
64	Heat Detector	1st Above ceiling hall B132 by resource room B1109	Combination	33369155

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
0126	Pull Station	1st In lobby By exit b11	Dual Action	33369027
0377	Pull Station	1st In c109 TV room	Dual Action	33368923
0378	Pull Station	1st In classroom c1100	Dual Action	33368919
0379	Pull Station	1st In passage c106	Dual Action	33368920
0382	Pull Station	1st Passage by c101	Dual Action	33368921
0383	Pull Station	1st Media center c1000	Dual Action	33369022
0388	Pull Station	1st Hall by a1193 at exit a5	Dual Action	33369020
0390	Pull Station	1st Hall By a1194 at exit a2	Dual Action	33369021
0391	Pull Station	1st In Main office by a-183a	Dual Action	42625874
0393	Pull Station	1st In Main office at a-1000 admin entrance	Dual Action	42625873
0395	Pull Station	1st In Main office at entrance	Dual Action	42625872
0400	Pull Station	1st North lobby by a1000 exit a1	Dual Action	33369025
0401	Pull Station	1st Lobby by work area a1001	Dual Action	33369026
129	Pull Station	1st Passage vocal music Rm A1134	Dual Action	42626226
130	Pull Station	1st Exit vocal music Rm A1134	Dual Action	42626225
131	Pull Station	1st Practice area A130A	Dual Action	42626224
132	Pull Station	1st Exit instrumental room A1123	Dual Action	42626222
133	Pull Station	1st Passage A128 to music A1123	Dual Action	42626223
136	Pull Station	1st Passage Instrumental Rm A1123	Dual Action	42626220
137	Pull Station	1st Hall A122 by music room A1123	Dual Action	42626221
138	Pull Station	1st Passage A117 stage rear exit	Dual Action	42626201
139	Pull Station	1st Stage A108 north exit	Dual Action	42626191
140	Pull Station	1st Stage A108 south exit	Dual Action	42626204
141	Pull Station	1st Auditorium A104 main entrance center	Dual Action	42626208
142	Pull Station	1st Auditorium A104 south ramp 105 by stage	Dual Action	42626229
143	Pull Station	1st Orchestra pit by stair A1	Dual Action	42626228
144	Pull Station	1st Orchestra pit by stair A2	Dual Action	42626227
145	Pull Station	1st Auditorium A104 south center exit	Dual Action	42626205
146	Pull Station	1st Auditorium A104 south exit by A2208	Dual Action	42626206
147	Pull Station	1st Scene shop A1121	Dual Action	42626203
148	Pull Station	1st Stage electric room A120	Dual Action	42626202
376	Pull Station	1st Auditorium A104 north exit by A2204	Dual Action	42626210
387	Pull Station	1st Painting drawing A1190 exit	Dual Action	42626189
389	Pull Station	1st Exit kiln room A1187	Dual Action	42626190
407	Pull Station	1st Auditorium A104 north center exit	Dual Action	42626211
408	Pull Station	1st Auditorium A104 north ramp 109 by stage	Dual Action	42626212
<b>Zone/Circuit: 2</b>				
31	Smoke Detector	1st Room A1134 practice area A130A	Photoelectric	42626234

36	Smoke Detector	1st Passage by music office A126	Photoelectric	42626233
361	Smoke Detector	1st Orchestra pit top of north stair A1	Photoelectric	42626239
42	Smoke Detector	1st Passage by music office A124	Photoelectric	42626230
47	Smoke Detector	1st Passage by practice rooms A130	Photoelectric	42626231
49	Smoke Detector	1st Passage by faculty men's Rm A131B	Photoelectric	42626232
82	Smoke Detector	1st Orchestra pit top of south stair A2	Photoelectric	42626236
85	Smoke Detector	1st Orchestra pit by north stair A1	Photoelectric	42626238
86	Smoke Detector	1st Orchestra pit by chair lift elev.	Photoelectric	42626237
89	Smoke Detector	1st Room A1134 practice area A130A	Photoelectric	42626235

The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 09</b>				
0132	Pull Station	1st By exit e47	Dual Action	33368972
0135	Pull Station	1st In e168 snack bar	Dual Action	33368977
0137	Pull Station	1st By exit e46	Dual Action	33368971
0139	Pull Station	1st Hall e169 to f148 by gym	Dual Action	33368970
0142	Pull Station	1st Hall by locker room e1127	Dual Action	33368924
0143	Pull Station	1st By exit e48	Dual Action	33368973
0144	Pull Station	1st By exit e49	Dual Action	33368974
0145	Pull Station	1st By exit e51 stairwell e1 landing	Dual Action	33368976
0146	Pull Station	1st By exit e50 in lobby by stair e1	Dual Action	33368975
0376	Pull Station	1st In hall by f153b boiler	Dual Action	33368989
0377	Pull Station	1st In hall by f1142	Dual Action	33368988
0378	Pull Station	1st In f1154 by exit f34	Dual Action	33368987
0379	Pull Station	1st In f133 b&w dark room	Dual Action	33368984
0381	Pull Station	1st In f1130 at exit	Dual Action	33368983
0381	Pull Station	1st In f134 color dark room	Dual Action	33368985
0382	Pull Station	1st In f1116 north	Dual Action	33368982
0383	Pull Station	1st In f1116 south	Dual Action	33368981
0387	Pull Station	1st Vestibule F-149 By Aux Gym F1100	Dual Action	33368979
0388	Pull Station	1st SE hall by aux gym f1100	Dual Action	33368978
0395	Pull Station	1st In hall by f163	Dual Action	33368991
0396	Pull Station	1st Stairwell e2 landing by exit	Dual Action	33368993
0404	Pull Station	1st Lobby exit by elevator 2	Dual Action	33368992
0405	Pull Station	1st In hall by exit f32	Dual Action	33368986
0409	Pull Station	1st NE Hall Exit By Aux Gym	Dual Action	33368980
<b>Zone/Circuit: 10</b>				
0128	Pull Station	1st Hall by e1154	Dual Action	33368934
0129	Pull Station	1st Hall east between main and aux gym	Dual Action	33368969
0130	Pull Station	1st Hall west between main and aux gym	Dual Action	33368968
0135	Pull Station	1st H104 boiler room	Dual Action	33368925
0136	Pull Station	1st H104 exit h23	Dual Action	33368927
0137	Pull Station	1st H105 electric room inside h104	Dual Action	33368926
0138	Pull Station	1st Hall by h104	Dual Action	33368928
0169	Pull Station	1st Pool exit g25	Dual Action	33368932
0170	Pull Station	1st Hall by g135	Dual Action	33368931
0172	Pull Station	1st By exit g24	Dual Action	33368930
0173	Pull Station	1st Hall top of ramp to pool	Dual Action	33368929
0174	Pull Station	1st Stair e153 to pool	Dual Action	33368933
131	Pull Station	1st Main gym E1142 N West corner	Dual Action	42626178
132	Pull Station	1st Main gym E1142 N West center	Dual Action	42626179
133	Pull Station	1st Main gym E1142 S West center	Dual Action	42626180
134	Pull Station	1st Main gym E1142 S West corner	Dual Action	42626181
<b>Zone/Circuit: 9</b>				
0386	Pull Station	1st F1108 exit	Dual Action	33368937
0394	Pull Station	1st In f1108	Dual Action	33368936



0406	Pull Station	1st By exit f29	Dual Action	33368935
133	Pull Station	1st Main gym E1142 S East corner	Dual Action	42626174
134	Pull Station	1st Main gym E1142 S East center	Dual Action	42626175
136	Pull Station	1st Main gym E1142 N East center	Dual Action	42626176
138	Pull Station	1st Main gym E1142 N East corner	Dual Action	42626177
28	Smoke Detector	1st Entry hall boys locker Rm E1135	Photoelectric	42626242
36	Smoke Detector	1st Passage boys locker Rm E1135	Photoelectric	42626241
37	Smoke Detector	1st Passage girls locker Rm E1127	Photoelectric	42626240
389	Pull Station	1st S East exit aux gym F1100	Dual Action	42626172
390	Pull Station	1st N East exit aux gym F1100	Dual Action	42626171
391	Pull Station	1st North exit aux gym F1100	Dual Action	42626170
392	Pull Station	1st N West exit aux gym F1100	Dual Action	42626168
393	Pull Station	1st S West exit aux gym F1100	Dual Action	42626169
47	Heat Detector	1st Above ceiling hall E124 by Storage room E122	Combination	33369139

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
0001	Heat Detector	2nd Above Ceiling Hall D202 By Stair D3	Combination	49668941
0002	Heat Detector	2nd Above Ceiling Hall D202 By Cust Rm B260	Combination	49668942
0003	Heat Detector	2nd Above Ceiling Alcove Womens Rm B259	Combination	49668943
0004	Heat Detector	2nd Above Ceiling Womens Rm B259	Combination	49668944
0005	Heat Detector	2nd Above Ceiling Alcove Men's Rm B262	Combination	49668945
0006	Heat Detector	2nd Above Ceiling Men's Rm B262	Combination	49668946
0007	Heat Detector	2nd Above Ceiling Math Dept C2229	Combination	49668937
0008	Heat Detector	2nd Above Ceiling Math Dept C2229 Office	Combination	49668936
0009	Heat Detector	2nd Above Ceiling Math Dept C2229 Kitchen	Combination	49668935
0010	Heat Detector	2nd Above Ceiling Math Dept C2229 Conf Rm	Combination	49668934
0011	Heat Detector	2nd Above Ceiling Math Dept C2229 Womens Rm	Combination	49668933
0012	Heat Detector	2nd Above Ceiling Math Dept C2229 Men's Rm	Combination	49668932
0013	Heat Detector	2nd Above Ceiling Hall D202	Combination	49668938
0015	Heat Detector	2nd Above Ceiling Hall D202	Combination	49668939
0016	Heat Detector	2nd Above Ceiling Hall D202	Combination	49668940
0017	Heat Detector	2nd Above Ceiling Hall B202 By Small Group D2203	Combination	49668931
0018	Heat Detector	2nd Above Ceiling Computer Lab C2209	Combination	49668930
0019	Heat Detector	2nd Above Ceiling Classroom C2210	Combination	49668929
0021	Heat Detector	2nd Above Ceiling Hall B204 By Classroom C2207	Combination	49668928
0023	Heat Detector	2nd Above Ceiling Classroom C2207	Combination	49668927
0024	Heat Detector	2nd Above Ceiling Hall B204 By Book Storage C210	Combination	49668926
0025	Heat Detector	2nd Above Ceiling Book Storage C210	Combination	49668925
0026	Heat Detector	2nd Above Ceiling Alcove Men's Rm C209	Combination	49668924
0027	Heat Detector	2nd Above Ceiling Men's Rm C209	Combination	49668923
0029	Heat Detector	2nd Above Ceiling Hall B204 By Projector Rm A203	Combination	49668947
0030	Heat Detector	2nd Above Ceiling Womens Rm C207	Combination	49668922
0032	Heat Detector	2nd Above Ceiling Hall B204 By Resource Rm A2202	Combination	49668948
0033	Heat Detector	2nd Above Ceiling Foreign Language C2205 Conf Rm	Combination	49668917
0035	Heat Detector	2nd Above Ceiling Foreign Language C2205 Alcove	Combination	49668918

0036	Heat Detector	2nd Above Ceiling Foreign Language C2205 Office	Combination	49668919
0037	Heat Detector	2nd Above Ceiling Foreign Language C2205 Men's Rm	Combination	49668920
0038	Heat Detector	2nd Above Ceiling Foreign Language C2205 Womens Rm	Combination	49668921
0039	Heat Detector	2nd Above Ceiling Resource Rm A2202	Combination	49668949
0040	Heat Detector	2nd Above Ceiling VP Secretary D21	Combination	49668950
0041	Heat Detector	2nd Above Ceiling VP D20	Combination	49668951
0126	Pull Station	2nd Top of stairwell d-3 by roof access	Dual Action	42625866
0130	Pull Station	2nd in hall by c-2207	Dual Action	42625852
0131	Pull Station	2nd in hall by elevator 1	Dual Action	42625851
0136	Pull Station	2nd in hall outside d-2203	Dual Action	42625850
0136	Pull Station	2nd Top of stairwell d-3 in hall	Dual Action	42625849
0282	Heat Detector	2nd Above Ceiling Men's Rm E226	Combination	49668907
0283	Heat Detector	2nd Above Ceiling Alcove Men's Rm E226	Combination	49668906
0284	Heat Detector	2nd Above Ceiling Staff Restroom E224	Combination	49668905
0285	Heat Detector	2nd Above Ceiling IDF 12 Rm E223	Combination	49668904
0286	Heat Detector	2nd Above Ceiling Alcove Womens Rm E222	Combination	49668903
0287	Heat Detector	2nd Above Ceiling Womens Rm E222	Combination	49668902
0292	Heat Detector	2nd Above Ceiling IDF 11 Rm E201	Combination	49668901
0305	Heat Detector	2nd Above Ceiling Hall D208 Intersection To Area E	Combination	49668916
0306	Heat Detector	2nd Above Ceiling Hall D208	Combination	49668912
0307	Heat Detector	2nd Above Ceiling Hall D208	Combination	49668913
0308	Heat Detector	2nd Above Ceiling Hall D209	Combination	49668914
0309	Heat Detector	2nd Above Ceiling Hall D209	Combination	49668915
0310	Heat Detector	2nd Above Ceiling Hall D209 Intersection To Area C	Combination	49668953
0328	Heat Detector	2nd Above Ceiling Stair E1	Combination	49668900
0339	Heat Detector	2nd Above Ceiling Stair D1	Combination	49668911
0378	Pull Station	2nd in hall outside stairwell e-2 by e-234a	Dual Action	42625863
0398	Pull Station	2nd in hall outside stairwell e-2	Dual Action	42625862
0402	Pull Station	2nd in hall above cafe near e-2300	Dual Action	42625859
0403	Pull Station	2nd in hall above cafe near exit by stairwell d-1	Dual Action	42625860
0404	Pull Station	2nd in hall above cafe near c-221	Dual Action	42625858
0405	Pull Station	2nd in hall outside stairwell d-1	Dual Action	42625861
138	Pull Station	1st Landing lecture room A2204	Dual Action	42626209
139	Pull Station	1st Landing lecture room A2208	Dual Action	42626207

**Zone/Circuit: 03**

0057	Heat Detector	2nd Above Ceiling Hall B225 By Classroom B2216	Combination	49668962
0058	Heat Detector	2nd Above Ceiling Stair B1	Combination	49668961
0059	Heat Detector	2nd Above Ceiling Hall B204 By Stair B1	Combination	49668960
0060	Heat Detector	2nd Above Ceiling Classroom B2216	Combination	49668959
0061	Heat Detector	2nd Above Ceiling Classroom B2213	Combination	49668958
0062	Heat Detector	2nd Above Ceiling Hall B204 By Classroom B2211	Combination	49668957
0063	Heat Detector	2nd Above Ceiling Classroom B2214	Combination	49668956

0064	Heat Detector	2nd Above Ceiling Classroom B2211	Combination	49668955
0065	Heat Detector	2nd Above Ceiling Classroom B2212	Combination	49668954
0066	Heat Detector	2nd Above Ceiling Hall B204 By Computer Lab C2209	Combination	49668952
0126	Pull Station	2nd in hall by b-2238	Dual Action	42625857
0129	Pull Station	2nd in hall outside stairwell b2	Dual Action	42625856
0134	Pull Station	2nd in hall outside stairwell b1 near lockers	Dual Action	42625855
0135	Pull Station	2nd in hall outside stairwell b1 near b-2213	Dual Action	42625854
0136	Pull Station	2nd in hall outside stairwell b1	Dual Action	42625853

### Zone/Circuit: 2

312	Smoke Detector	2nd stair E2 over steps	Photoelectric	42626126
313	Smoke Detector	2nd Top of landing stair E2	Photoelectric	42626125
314	Smoke Detector	2nd Hall E234 elevator 2 lobby	Photoelectric	42626124
315	Smoke Detector	2nd Hall E234 by elevator 2 lobby	Photoelectric	42626123
316	Smoke Detector	2nd Hall E234 by classroom E2316	Photoelectric	42626122
317	Smoke Detector	2nd Hall E234 by classroom E2314	Photoelectric	42626121
318	Smoke Detector	2nd Hall E234 by classroom E2311	Photoelectric	42626120
319	Smoke Detector	2nd Hall E234 by classroom E2312	Photoelectric	42626119
320	Smoke Detector	2nd Hall E234 by classroom E2310	Photoelectric	42626118
321	Smoke Detector	2nd Hall E234 by classroom E2307	Photoelectric	42626117
322	Smoke Detector	2nd Hall E234 by prep room E212	Photoelectric	42626116
323	Smoke Detector	2nd Hall E234 by prep room E211	Photoelectric	42626115
324	Smoke Detector	2nd Hall E234 by classroom E2303	Photoelectric	42626114
325	Smoke Detector	2nd Hall E234 by chem storage E205	Photoelectric	42626113
326	Smoke Detector	2nd Hall E234 by stair E1	Photoelectric	42626112
331	Smoke Detector	2nd Hall D209 intersection to area E	Photoelectric	42625947
332	Smoke Detector	2nd Hall D208 by stair E1	Photoelectric	42625948
333	Smoke Detector	2nd Hall D208 by building front	Photoelectric	42625949
334	Smoke Detector	2nd Hall D208 by building front	Photoelectric	42625950
335	Smoke Detector	2nd Hall D208 by building front	Photoelectric	42625951
336	Smoke Detector	2nd Hall D202 at stair D1	Photoelectric	42625931
337	Smoke Detector	2nd Hall D202 by V.P. Secretary Rm D21	Photoelectric	42625930
338	Smoke Detector	2nd Top of landing stair D1	Photoelectric	42625933
340	Smoke Detector	2nd stair D1 over steps	Photoelectric	42625932
341	Smoke Detector	2nd Hall D209 by area E	Photoelectric	42625946
342	Smoke Detector	2nd Hall D209 by building rear	Photoelectric	42625945
343	Smoke Detector	2nd Hall D209 by building rear	Photoelectric	42625944
344	Smoke Detector	2nd Hall D209 by building rear	Photoelectric	42625943
345	Smoke Detector	2nd Hall D209 by building rear	Photoelectric	42625942
346	Smoke Detector	2nd Hall D209 intersection to area C	Photoelectric	42625941
58	Smoke Detector	2nd Stair D3 over steps	Photoelectric	42625892
61	Smoke Detector	2nd Hall B204 by computer lab C2209	Photoelectric	42625921
62	Smoke Detector	2nd Hall B204 by classroom C2210	Photoelectric	42625922
63	Smoke Detector	2nd Hall B204 by classroom C2207	Photoelectric	42625923
64	Smoke Detector	2nd Hall B204 by book storage C210	Photoelectric	42625924
66	Smoke Detector	2nd Hall B204 by projector room A203	Photoelectric	42625925
67	Smoke Detector	2nd Hall B204 by classroom A2206	Photoelectric	42625926
68	Smoke Detector	2nd Hall D204 by resource room A2202	Photoelectric	42625927
69	Smoke Detector	2nd Hall D202 lobby by room A2205	Photoelectric	42625929
70	Smoke Detector	2nd Hall D202 lobby by room A2202	Photoelectric	42625928
75	Smoke Detector	2nd Hall D202 by small group D2203	Photoelectric	42625934

76	Smoke Detector	2nd Hall D202 by court yard/ media center	Photoelectric	42625935
77	Smoke Detector	2nd Hall D202 by court yard/ media center	Photoelectric	42625936
78	Smoke Detector	2nd Hall D202 by court yard/ media center	Photoelectric	42625937
79	Smoke Detector	2nd Hall D202 by court yard/ media center	Photoelectric	42625938
80	Smoke Detector	2nd Hall D202 by math dept. room C2229	Photoelectric	42625939
81	Smoke Detector	2nd Hall D202 by custodial closet B260	Photoelectric	42625940
82	Smoke Detector	2nd Hall D202 by stair D3	Photoelectric	42625894
83	Smoke Detector	2nd Top of landing Stair D3	Photoelectric	42625893

**Zone/Circuit: 3**

67	Smoke Detector	2nd Hall B249 by classroom B2238	Photoelectric	42625895
68	Smoke Detector	2nd Hall B249 by IDF9 room B255	Photoelectric	42625896
69	Smoke Detector	2nd Hall B249 by classroom B2227	Photoelectric	42625897
70	Smoke Detector	2nd Hall B249 by classroom B2232	Photoelectric	42625898
71	Smoke Detector	2nd Hall B249 by classroom B2230	Photoelectric	42625899
72	Smoke Detector	2nd Hall B249 by classroom B2221	Photoelectric	42625900
73	Smoke Detector	2nd Hall B249 by office B21	Photoelectric	42625901
74	Smoke Detector	2nd stair B2 open area	Photoelectric	42625904
75	Smoke Detector	2nd stair B2 over stairs	Photoelectric	42625905
76	Smoke Detector	2nd Hall B225 by stair B2	Photoelectric	42625902
77	Smoke Detector	2nd Top of landing stair B2	Photoelectric	42625903
78	Smoke Detector	2nd Hall B225 by classroom B2228	Photoelectric	42625906
79	Smoke Detector	2nd Hall B225 by classroom B2226	Photoelectric	42625907
80	Smoke Detector	2nd Hall B225 by classroom B2217	Photoelectric	42625908
81	Smoke Detector	2nd Hall B225 by classroom B2215	Photoelectric	42625909
82	Smoke Detector	2nd Hall B225 by classroom B2220	Photoelectric	42625910
83	Smoke Detector	2nd Hall B225 by storage room B212	Photoelectric	42625911
84	Smoke Detector	2nd Hall B225 by classroom B2218	Photoelectric	42625912
85	Smoke Detector	2nd Hall B204 at Stair B1	Photoelectric	42625917
86	Smoke Detector	2nd Hall B204 by stair B1	Photoelectric	42625913
87	Smoke Detector	2nd Stair B1 open area	Photoelectric	42625915
88	Smoke Detector	2nd Stair B1 over steps	Photoelectric	42625914
89	Smoke Detector	2nd Top of landing Stair B1	Photoelectric	42625916
90	Smoke Detector	2nd Hall B204 by classroom B2216	Photoelectric	42625918
91	Smoke Detector	2nd Hall B204 by classroom B2211	Photoelectric	42625919
92	Smoke Detector	2nd Hall B204 by classroom B2212	Photoelectric	42625920

# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery Upper Middle  
School  
375 Burnt Hill Rd  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
*Dec 11, 2018*

Building: Montgomery Upper Middle School  
Contact: Dave Klein  
Title: B&G Mgr.

Company: Alarm & Communication Technologies  
Contact: Michael Reyes  
Title: Technician

# Executive Summary

Generated by: BuildingReports.com

Building Information		
<b>Building:</b> Montgomery Upper Middle School	<b>Contact:</b> Dave Klein	
<b>Address:</b> 375 Burnt Hill Rd	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Michael Reyes	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 9732295959	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 9732295959	
<b>Country:</b> United States of America	<b>Email:</b> Miker@njact.com	
System Control Unit		
<b>Manufacturer:</b> EST	<b>Inspection Date:</b> 09/06/2018	<b>IDC Style:</b> B
<b>Model Number:</b> EST-3	<b>Install Date:</b> 08/26/2016	<b>SLC Style:</b> 4
<b>Software Version:</b> 13.11.18	<b>Version Date:</b> 08/26/2016	<b>NAC Style:</b> Y
<b>Location:</b> 1st Main office	<b>Current Protection:</b> Breaker	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b>	<b>Mfg:</b>	<b>Model #:</b>
<b>Test Time/Date:</b>	<b>Restore Time</b>	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	19	5.74%	19	100.00%	7	36.84%	12	63.16%
Initiating	310	93.66%	270	87.10%	270	100.00%	0	0%
Supervisory	2	0.60%	2	100.00%	2	100.00%	0	0%
<b>Totals</b>	<b>331</b>	<b>100%</b>	<b>291</b>	<b>87.92%</b>	<b>279</b>	<b>95.88%</b>	<b>12</b>	<b>4.12%</b>

Certification	
Company: Alarm & Communication Technologies	Building: Montgomery Upper Middle School
Inspector: Michael Reyes	Contact: Dave Klein
Signed:	Signed:



# Discrepancy Report

Generated by: BuildingReports.com

Building: Montgomery Upper Middle School		Control Panel: 2		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<i>Items listed for Recall by Manufacturer</i>				
No recalled items found during this inspection.				
🔍 ScanID	📍 Location	🔧 Problem	Address	📖 Reference
<i>Control</i>				
<b>Battery</b>				
42626314	1st In BPS in auditorium storage	Batteries installed 10/30/14	2	
42626313	1st In BPS in auditorium storage	batteries installed 10/30/14	2	
42626319	1st In BPS in electric room by gym boys side	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
42626320	1st In BPS in electric room by gym boys side	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
42626316	1st In BPS in room B100	batteries installed 10/30/14	2	
42626317	1st In BPS in room B100	Batteries installed 10/30/14	2	
42626309	1st In electric closet by gym	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
42626310	1st In electric closet by gym	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
33369366	1st Main office	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
33369367	1st Main office	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
42626323	2nd In BPS in room B200	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
42626322	2nd In BPS in room B200	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
<i>Code References</i>				
NFPA72 Table 14.4.3.2 (9a)(1)	Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations			

# Proposed Solutions Report

Generated by: *BuildingReports.com*

Building: Montgomery Upper Middle School					Control Panel: 2
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<b>Control</b>					
<b>Battery</b>					
42626314	1st In BPS in auditorium storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626313	1st In BPS in auditorium storage	Replace	UT1270	T/M	<input type="checkbox"/>
42626319	1st In BPS in electric room by gym boys side	Replace	UT1270	T/M	<input type="checkbox"/>
42626320	1st In BPS in electric room by gym boys side	Replace	UT1270	T/M	<input type="checkbox"/>
42626316	1st In BPS in room B100	Replace	UT1270	T/M	<input type="checkbox"/>
42626317	1st In BPS in room B100	Replace	UT1270	T/M	<input type="checkbox"/>
42626309	1st In electric closet by gym	Replace	UT1270	T/M	<input type="checkbox"/>
42626310	1st In electric closet by gym	Replace	UT1270	T/M	<input type="checkbox"/>
33369366	1st Main office	Replace	ps-12550	T/M	<input type="checkbox"/>
33369367	1st Main office	Replace	ps-12550	T/M	<input type="checkbox"/>
42626323	2nd In BPS in room B200	Replace	UT1270	T/M	<input type="checkbox"/>
42626322	2nd In BPS in room B200	Replace	UT1270	T/M	<input type="checkbox"/>
<b>PO #: (none)</b>				<b>T/M</b>	

# Notes & Recommendations

Generated by: *BuildingReports.com*

## Building: Montgomery Upper Middle School

*The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.*

### **General Note**

01-03-0381 Should Read Gym F16

01-03-0382 Should Read Rear Vest Girls Locker F17

01-03-0377 Should read Gym F15

01-03-0376 Should Read Rear Vest Boys Locker F14

Exit B7(vestibule between kitchen and electrical room) has no pull station or alarm device for coverage.

01-03-0134 Pull Station. Comes up on panel as Room F103A should be Room F104

## Building: Montgomery Upper Middle School      Control Panel: 1 - EST    EST-3

ScanID	Note	Device Type	Location	Comment
<b>Initiating</b>				
46876320	2	Smoke Detector	1st Inside Closet Room F-101	Passed
Multiple smokes on lower level in f-101 wood shop. Recommend replacing with heats and reprogramming. Customer is NOT in possession of program.				

# Inspection & Testing

Generated by: BuildingReports.com

**Building: Montgomery Upper Middle School      Control Panel: 1 - EST EST-3**

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Annunciator	1st In Main Lobby By Main Office	Tested	3:11:27 PM	09/06/2018
Control Panel	1st Main office	Tested	9:19:09 AM	09/06/2018
Power Supply	1st In auditorium storage	Tested	3:33:53 PM	10/24/2018
Power Supply	1st In electric closet next to gym	Tested	11:22:53 AM	09/06/2018
Power Supply	1st In electric closet next to gym boys side	Tested	3:17:34 PM	09/06/2018
Power Supply	1st In electric room B100	Tested	3:24:52 PM	10/24/2018
Power Supply	2nd In electric room B200	Tested	3:13:17 PM	09/06/2018
<b>Initiating</b>				
Duct Detector	RTU Auditorium F-1	Tested	7:23:59 AM	12/11/2018
Duct Detector	RTU Media Center C-1	Tested	7:24:03 AM	12/11/2018
Duct Detector	RTU Room E-102	Tested	1:57:18 PM	09/06/2018
Duct Detector	RTU Room E-104	Tested	1:57:55 PM	09/06/2018
Duct Detector	RTU Room E-105	Tested	10:00:42 AM	12/10/2018
Duct Detector	RTU Room E-107	Tested	1:59:11 PM	09/06/2018
Duct Detector	RTU Room E-108	Tested	7:24:13 AM	12/11/2018
Duct Detector	RTU1 Wood Shop	Tested	7:24:07 AM	12/11/2018
Duct Detector	RTU3 Boys side of Weight Room	Tested	2:04:36 PM	09/06/2018
Duct Detector	RTU4 Girls Side of Weight Room	Tested	2:04:21 PM	09/06/2018
Duct Detector	RTU5 Rooftop Return Side	Tested	2:04:01 PM	09/06/2018
Duct Detector	RTU6 Rooftop Return Side	Tested	9:23:06 AM	12/10/2018
Heat Detector	1st Boys Locker Room F-2	Tested	2:58:55 PM	09/06/2018
Heat Detector	1st Boys Locker Room F-2	Tested	2:59:47 PM	09/06/2018
Heat Detector	1st Boys Locker Room F-2	Tested	3:00:14 PM	09/06/2018
Heat Detector	1st By Shower Boys Locker Room F-2	Tested	3:00:27 PM	09/06/2018
Heat Detector	1st Hall C Custodial Office	Tested	2:51:10 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:51:52 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:52:19 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:52:30 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:52:42 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:52:56 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:53:56 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:54:09 PM	09/06/2018
Heat Detector	1st Kitchen	Tested	2:54:18 PM	09/06/2018
Heat Detector	1st Kitchen toilet	Tested	2:54:28 PM	09/06/2018
Heat Detector	1st Kitchen toilet	Tested	2:54:48 PM	09/06/2018
Heat Detector	1st Receiving	Tested	2:55:32 PM	09/06/2018
Heat Detector	1st Receiving/Wash Area	Tested	2:56:20 PM	09/06/2018
Heat Detector	1st Room F-101 Paint Booth	Tested	2:57:20 PM	09/06/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	1st Room F-103 Storage	Tested	2:56:44 PM	09/06/2018
Heat Detector	1st Storage Rm By Kitchen	Tested	2:55:00 PM	09/06/2018
Pull Station	1st Stage Auditorium F-1	Tested	10:04:58 AM	09/06/2018
Pull Station	1st Stage Auditorium F-1	Tested	10:07:46 AM	09/06/2018
Pull Station	1st Auditorium F-1	Tested	10:03:17 AM	09/06/2018
Pull Station	1st Cafeteria	Tested	10:00:27 AM	10/24/2018
Pull Station	1st Gym F4	Tested	10:43:54 AM	10/24/2018
Pull Station	1st Gym F4	Tested	10:47:22 AM	10/24/2018
Pull Station	1st Hall By Auditorium F1	Tested	9:59:43 AM	09/06/2018
Pull Station	1st Hall By Rm B111	Tested	9:44:11 AM	09/06/2018
Pull Station	1st Hall By Room B101	Tested	9:33:33 AM	09/06/2018
Pull Station	1st Hall By Room E106	Tested	9:57:33 AM	09/06/2018
Pull Station	1st Hall By Room E108	Tested	9:56:21 AM	09/06/2018
Pull Station	1st Hall By Room F102	Tested	10:25:55 AM	10/24/2018
Pull Station	1st Hall By Room F105	Tested	10:37:07 AM	10/24/2018
Pull Station	1st Hall Vest Boys Locker F2	Tested	10:41:59 AM	10/24/2018
Pull Station	1st Hall Vest Girls Locker F5	Tested	10:51:30 AM	10/24/2018
Pull Station	1st In Auditorium F-1	Tested	10:00:13 AM	09/06/2018
Pull Station	1st In Auditorium F-1	Tested	10:02:17 AM	09/06/2018
Pull Station	1st In Boiler Room By Entrance	Tested	10:59:04 AM	10/24/2018
Pull Station	1st In Boiler Room By Exit	Tested	10:58:30 AM	10/24/2018
Pull Station	1st Kitchen	Tested	10:03:48 AM	10/24/2018
Pull Station	1st Next to exit doors By Room E104	Tested	9:58:03 AM	09/06/2018
Pull Station	1st Rear Vest Boys Locker F2	Tested	10:42:54 AM	10/24/2018
Pull Station	1st Rear Vest Girls Locker F5	Tested	10:54:04 AM	10/24/2018
Pull Station	1st Stairs By Rm B107	Tested	9:46:38 AM	09/06/2018
Pull Station	1st Stairs By Rm B111	Tested	9:44:46 AM	09/06/2018
Pull Station	1st Stairs By RMS B10/B101 B stairwell near office at exit	Tested	9:34:18 AM	09/06/2018
Pull Station	1st Auditorium exit near c102	Tested	10:22:08 AM	10/24/2018
Pull Station	1st Cafeteria exit nearest breezeway	Tested	9:59:59 AM	10/24/2018
Pull Station	1st Hall by B107	Tested	9:46:02 AM	09/06/2018
Pull Station	1st Hall C North Breezeway	Tested	9:58:43 AM	10/24/2018
Pull Station	1st Hall C North Breezeway by Cafe	Tested	9:59:20 AM	10/24/2018
Pull Station	1st Hall C south Breezeway by media center	Tested	9:48:00 AM	09/06/2018
Pull Station	1st Hall C. Custodial Office	Tested	10:02:05 AM	10/24/2018
Pull Station	1st Main entrance by Office b3	Tested	9:31:58 AM	09/06/2018
Pull Station	1st Main Office by Safe	Tested	9:19:31 AM	09/06/2018
Pull Station	1st media center C-1	Tested	9:48:32 AM	09/06/2018
Pull Station	1st media center C-1	Tested	9:50:00 AM	09/06/2018
Pull Station	1st media center C-1	Tested	9:53:38 AM	09/06/2018
Pull Station	1st South Breezeway hall C	Tested	9:47:29 AM	09/06/2018
Pull Station	2nd In Hallway By Mech. Room/Roof Access	Tested	11:01:24 AM	10/24/2018
Pull Station	2nd In Hallway By Room B207	Tested	11:03:41 AM	10/24/2018
Pull Station	2nd In Hallway By Storage Room B200	Tested	11:02:51 AM	10/24/2018
Smoke Detector	1st Inside Closet Room F-101	Tested	3:07:15 PM	10/24/2018
Smoke Detector	1st Boys Rm By Rm E-108	Tested	11:54:16 AM	09/06/2018
Smoke Detector	1st Hall By Gym/ Girls Locker Rm	Tested	11:37:19 AM	09/06/2018
Smoke Detector	1st Hall By Rm E-108	Tested	11:49:53 AM	09/06/2018
Smoke Detector	1st Hall By Rm E-108	Tested	11:56:51 AM	09/06/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Hall By Rm E-108	Tested	12:00:46 PM	09/06/2018
Smoke Detector	1st Hall By Rm E-108A	Tested	12:08:35 PM	09/06/2018
Smoke Detector	1st Hall By Room E-106	Tested	12:15:59 PM	09/06/2018
Smoke Detector	1st Hall By Room E-107	Tested	12:15:13 PM	09/06/2018
Smoke Detector	1st Rm E-101 A	Tested	12:10:54 PM	09/06/2018
Smoke Detector	1st School Store F-5	Tested	11:47:18 AM	09/06/2018
Smoke Detector	1st Rm E-107	Tested	12:06:22 PM	09/06/2018
Smoke Detector	1st Rm E-108A	Tested	12:02:40 PM	09/06/2018
Smoke Detector	1st Boys Room by B-105	Tested	10:44:17 AM	09/06/2018
Smoke Detector	1st Boys Room by B-105	Tested	10:44:41 AM	09/06/2018
Smoke Detector	1st Cafeteria	Tested	11:56:54 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:03 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:11 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:17 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:24 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:30 AM	10/24/2018
Smoke Detector	1st Cafeteria	Tested	11:57:38 AM	10/24/2018
Smoke Detector	1st Elevator Lobby	Tested	10:47:17 AM	09/06/2018
Smoke Detector	1st Elevator Machine Room	Tested	12:47:24 PM	10/24/2018
Smoke Detector	1st Entry Auditorium F-1	Tested	12:28:40 PM	10/24/2018
Smoke Detector	1st Girls lav by room E-108	Tested/Cleaned	7:24:28 AM	12/11/2018
Smoke Detector	1st Girls Room by B-104	Tested/Cleaned	7:25:10 AM	12/11/2018
Smoke Detector	1st Girls Room by B-104	Tested/Cleaned	7:25:14 AM	12/11/2018
Smoke Detector	1st Hall B-3 to Main Office B-1	Tested	10:17:51 AM	09/06/2018
Smoke Detector	1st Hall by boiler room	Tested	12:39:50 PM	10/24/2018
Smoke Detector	1st Hall by boiler room	Tested	12:40:01 PM	10/24/2018
Smoke Detector	1st Hall by Cafeteria	Tested	12:10:00 PM	10/24/2018
Smoke Detector	1st Hall by Elevator Machine Room	Tested	10:47:46 AM	09/06/2018
Smoke Detector	1st Hall by Room B-1	Tested	10:33:14 AM	09/06/2018
Smoke Detector	1st Hall by Room B-10	Tested	10:35:36 AM	09/06/2018
Smoke Detector	1st Hall by Room B-101	Tested	10:36:46 AM	09/06/2018
Smoke Detector	1st Hall by room B-102	Tested	10:39:57 AM	09/06/2018
Smoke Detector	1st Hall by room B-103	Tested	10:40:56 AM	09/06/2018
Smoke Detector	1st Hall by room B-104	Tested	10:41:33 AM	09/06/2018
Smoke Detector	1st Hall by Room B-105	Tested	10:43:47 AM	09/06/2018
Smoke Detector	1st Hall by Room B-105	Tested	10:46:11 AM	09/06/2018
Smoke Detector	1st Hall by Room B-106	Tested	10:46:36 AM	09/06/2018
Smoke Detector	1st Hall by Room B-111	Tested	10:42:15 AM	09/06/2018
Smoke Detector	1st Hall by Room B-3	Tested	10:25:37 AM	09/06/2018
Smoke Detector	1st Hall by room C-101	Tested	10:54:21 AM	09/06/2018
Smoke Detector	1st Hall by room C-101	Tested	11:13:46 AM	09/06/2018
Smoke Detector	1st Hall by room C-102	Tested	11:16:38 AM	09/06/2018
Smoke Detector	1st Hall by room C-102	Tested	11:17:47 AM	09/06/2018
Smoke Detector	1st Hall by room C-102	Tested	11:19:41 AM	09/06/2018
Smoke Detector	1st Hall by room C-103	Tested	12:18:18 PM	10/24/2018
Smoke Detector	1st Hall by room C-103	Tested	12:19:27 PM	10/24/2018
Smoke Detector	1st Hall by room C-104	Tested	12:19:15 PM	10/24/2018
Smoke Detector	1st Hall by room C-104	Tested	12:41:55 PM	10/24/2018
Smoke Detector	1st Hall C by storage/sprinkler rm	Tested	11:26:44 AM	09/06/2018
Smoke Detector	1st Hall C Custodial Office	Tested	12:23:25 PM	10/24/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Hall C North Breezeway	Tested	12:12:10 PM	10/24/2018
Smoke Detector	1st Hall C North Breezeway	Tested	12:12:13 PM	10/24/2018
Smoke Detector	1st Hall C south breezeway	Tested	10:51:30 AM	09/06/2018
Smoke Detector	1st Hall C south breezeway	Tested	10:51:56 AM	09/06/2018
Smoke Detector	1st Hallway c custodial office	Tested	12:22:18 PM	10/24/2018
Smoke Detector	1st Kitchen Office	Tested	12:13:44 PM	10/24/2018
Smoke Detector	1st Main Office B-1	Tested	10:20:30 AM	09/06/2018
Smoke Detector	1st Media Center A/V storage	Tested	10:58:23 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	10:55:43 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	10:56:08 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	10:56:38 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	10:57:25 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	10:59:46 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:03:33 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:04:17 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:04:48 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:05:12 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:06:30 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:07:05 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:08:06 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:08:50 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:09:28 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:10:10 AM	09/06/2018
Smoke Detector	1st Media Center C-1	Tested	11:10:51 AM	09/06/2018
Smoke Detector	1st Media Center C-2	Tested	11:01:17 AM	09/06/2018
Smoke Detector	1st Media Center C-3	Tested	11:03:04 AM	09/06/2018
Smoke Detector	1st Media Center computer storage	Tested	11:00:25 AM	09/06/2018
Smoke Detector	1st Passage by Cafeteria	Tested	12:11:15 PM	10/24/2018
Smoke Detector	1st Projector Booth Auditorium F-1	Tested	11:40:35 AM	09/06/2018
Smoke Detector	1st Projector Booth Auditorium F-1	Tested	11:41:06 AM	09/06/2018
Smoke Detector	1st Projector Booth Auditorium F-1	Tested	11:41:41 AM	09/06/2018
Smoke Detector	1st Records Main Office B-1	Tested	11:46:29 AM	10/24/2018
Smoke Detector	1st Room B-10	Tested	10:22:39 AM	09/06/2018
Smoke Detector	1st Room B-101	Tested	2:59:34 PM	10/24/2018
Smoke Detector	1st Room B-102	Tested	3:00:35 PM	10/24/2018
Smoke Detector	1st Room B-103	Tested	3:00:48 PM	10/24/2018
Smoke Detector	1st Room B-104	Tested	3:00:57 PM	10/24/2018
Smoke Detector	1st Room B-104A	Tested	3:01:08 PM	10/24/2018
Smoke Detector	1st Room B-105	Tested/Cleaned	7:25:05 AM	12/11/2018
Smoke Detector	1st Room B-106	Tested	10:49:43 AM	09/06/2018
Smoke Detector	1st Room B-107	Tested	2:57:26 PM	10/24/2018
Smoke Detector	1st Room B-108	Tested	2:56:58 PM	10/24/2018
Smoke Detector	1st Room B-108A	Tested	10:48:11 AM	09/06/2018
Smoke Detector	1st Room B-109	Tested	3:02:06 PM	10/24/2018
Smoke Detector	1st Room B-109A	Tested	3:01:47 PM	10/24/2018
Smoke Detector	1st Room B-109A	Tested	3:01:57 PM	10/24/2018
Smoke Detector	1st Room B-11	Tested	10:24:31 AM	09/06/2018
Smoke Detector	1st Room B-11	Tested	10:25:08 AM	09/06/2018
Smoke Detector	1st Room B-110	Tested	3:01:34 PM	10/24/2018
Smoke Detector	1st Room B-111	Tested	3:01:23 PM	10/24/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Room B-112	Tested	2:59:56 PM	10/24/2018
Smoke Detector	1st Room B-114	Tested	10:38:46 AM	09/06/2018
Smoke Detector	1st Room B-114	Tested	10:39:10 AM	09/06/2018
Smoke Detector	1st Room B-115	Tested	10:38:21 AM	09/06/2018
Smoke Detector	1st Room B-12	Tested	10:31:19 AM	09/06/2018
Smoke Detector	1st Room B-12 Private Toilet	Tested	10:31:47 AM	09/06/2018
Smoke Detector	1st Room B-12 Student Toilet	Tested	10:32:40 AM	09/06/2018
Smoke Detector	1st Room B-13	Tested	10:33:45 AM	09/06/2018
Smoke Detector	1st Room B-13 Toilet	Tested	10:34:12 AM	09/06/2018
Smoke Detector	1st Room B-14	Tested/Cleaned	7:25:25 AM	12/11/2018
Smoke Detector	1st Room B-15	Tested	10:36:08 AM	09/06/2018
Smoke Detector	1st Room B-16	Tested/Cleaned	7:25:20 AM	12/11/2018
Smoke Detector	1st Room B-2	Tested	3:13:23 PM	10/24/2018
Smoke Detector	1st Room B-3	Tested	10:16:29 AM	09/06/2018
Smoke Detector	1st Room B-3	Tested	11:40:21 AM	10/24/2018
Smoke Detector	1st Room B-3 Safe/Vault	Tested	11:40:30 AM	10/24/2018
Smoke Detector	1st Room B-4	Tested	10:18:25 AM	09/06/2018
Smoke Detector	1st Room B-5	Tested	11:44:13 AM	10/24/2018
Smoke Detector	1st Room B-6	Tested	10:21:02 AM	09/06/2018
Smoke Detector	1st Room B-7	Tested	11:46:48 AM	10/24/2018
Smoke Detector	1st Room B-8	Tested	10:21:44 AM	09/06/2018
Smoke Detector	1st Room B-9	Tested	11:47:03 AM	10/24/2018
Smoke Detector	1st room C-101	Tested	11:14:35 AM	09/06/2018
Smoke Detector	1st Room C-102	Tested	11:18:37 AM	09/06/2018
Smoke Detector	1st room C-103	Tested/Cleaned	7:24:36 AM	12/11/2018
Smoke Detector	1st room C-103	Tested/Cleaned	7:24:41 AM	12/11/2018
Smoke Detector	1st room C-103	Tested/Cleaned	7:24:45 AM	12/11/2018
Smoke Detector	1st room C-103	Tested/Cleaned	7:24:49 AM	12/11/2018
Smoke Detector	1st room C-103	Tested/Cleaned	7:24:54 AM	12/11/2018
Smoke Detector	1st room C-104	Tested/Cleaned	10:58:41 AM	12/10/2018
Smoke Detector	1st room C-104	Tested/Cleaned	10:58:58 AM	12/10/2018
Smoke Detector	1st room C-104	Tested/Cleaned	10:59:45 AM	12/10/2018
Smoke Detector	1st room C-104A Office	Tested	3:02:52 PM	10/24/2018
Smoke Detector	1st room C-104A Recording	Tested	3:03:01 PM	10/24/2018
Smoke Detector	1st room C-104B	Tested/Cleaned	11:01:25 AM	12/10/2018
Smoke Detector	1st room C-104C	Tested	3:02:40 PM	10/24/2018
Smoke Detector	1st Side Entry Auditorium F-1	Tested	12:28:52 PM	10/24/2018
Smoke Detector	1st Stage Auditorium F-1	Tested	12:30:14 PM	10/24/2018
Smoke Detector	1st Stage Auditorium F-1	Tested	12:31:51 PM	10/24/2018
Smoke Detector	1st Stage Auditorium F-1	Tested	12:33:34 PM	10/24/2018
Smoke Detector	1st Stage Auditorium F-1	Tested	12:36:07 PM	10/24/2018
Smoke Detector	1st Stair by B-111	Tested	10:43:07 AM	09/06/2018
Smoke Detector	1st Stairs by Room B-101	Tested	10:37:01 AM	09/06/2018
Smoke Detector	1st Stairs by room B-107	Tested	10:48:54 AM	09/06/2018
Smoke Detector	1st Storage by room C-102	Tested	11:19:08 AM	09/06/2018
Smoke Detector	1st Storage by room C-102	Tested	11:20:23 AM	09/06/2018
Smoke Detector	1st Storage by room C-102	Tested	12:23:59 PM	10/24/2018
Smoke Detector	1st Storage Main Office B-1	Tested	10:19:59 AM	09/06/2018
Smoke Detector	1st Toilet by Main Office B-1	Tested	10:35:03 AM	09/06/2018
Smoke Detector	1st Toilet Main Office B-1	Tested	11:43:39 AM	10/24/2018



Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st Toilet Main Office B-1	Tested	11:44:29 AM	10/24/2018
Smoke Detector	2nd Elevator Lobby	Tested	3:05:45 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-201	Tested	3:06:18 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-202	Tested	3:06:14 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-203	Tested	3:06:10 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-204	Tested	3:06:04 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-206	Tested	3:05:54 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-207	Tested	3:05:49 PM	10/24/2018
Smoke Detector	2nd Hall By Room B-208A	Tested	3:05:40 PM	10/24/2018
Smoke Detector	2nd Rm B-202A	Tested	3:08:25 PM	10/24/2018
Smoke Detector	2nd Rm B-204A	Tested/Cleaned	7:25:43 AM	12/11/2018
Smoke Detector	2nd Rm B-205A	Tested	3:04:25 PM	10/24/2018
Smoke Detector	2nd Rm B-205A	Tested	3:04:32 PM	10/24/2018
Smoke Detector	2nd Rm B-208A	Tested	3:05:18 PM	10/24/2018
Smoke Detector	2nd Rm B-209A	Tested	3:04:08 PM	10/24/2018
Smoke Detector	2nd Rm B-209A	Tested	3:04:17 PM	10/24/2018
Smoke Detector	2nd Rm B-213A	Tested	3:08:06 PM	10/24/2018
Smoke Detector	2nd Rm B-213A	Tested	3:08:13 PM	10/24/2018
Smoke Detector	2nd Rm B-215A	Tested/Cleaned	7:25:57 AM	12/11/2018
Smoke Detector	2nd Room B-201	Tested/Cleaned	10:42:39 AM	12/10/2018
Smoke Detector	2nd Room B-202	Tested	3:07:55 PM	10/24/2018
Smoke Detector	2nd Room B-202A	Tested	3:08:19 PM	10/24/2018
Smoke Detector	2nd Room B-203	Tested/Cleaned	10:42:56 AM	12/10/2018
Smoke Detector	2nd Room B-204	Tested/Cleaned	7:25:40 AM	12/11/2018
Smoke Detector	2nd Room B-205	Tested	3:03:57 PM	10/24/2018
Smoke Detector	2nd Room B-206	Tested	3:04:43 PM	10/24/2018
Smoke Detector	2nd Room B-207	Tested	3:05:05 PM	10/24/2018
Smoke Detector	2nd Room B-208	Tested	3:05:12 PM	10/24/2018
Smoke Detector	2nd Room B-209	Tested/Cleaned	7:25:34 AM	12/11/2018
Smoke Detector	2nd Room B-210	Tested	3:03:46 PM	10/24/2018
Smoke Detector	2nd Room B-211	Tested	3:08:44 PM	10/24/2018
Smoke Detector	2nd Room B-212	Tested/Cleaned	7:25:47 AM	12/11/2018
Smoke Detector	2nd Room B-213	Tested	3:08:34 PM	10/24/2018
Smoke Detector	2nd Room B-214	Tested	3:07:23 PM	10/24/2018
Smoke Detector	2nd Room B-215	Tested/Cleaned	7:25:53 AM	12/11/2018
Smoke Detector	2nd Stairs By Room B-201	Tested	3:06:23 PM	10/24/2018
Smoke Detector	2nd Stairs By Room B-207	Tested	3:05:34 PM	10/24/2018
Smoke Detector	2nd Stairs By Room B-212	Tested	3:05:58 PM	10/24/2018
Waterflow Switch	1st Above Ceiling in Chem Storage by E-104	Tested	7:26:08 AM	12/11/2018
Waterflow Switch	1st Hall C Sprinklers/Storage Room	Tested	11:25:15 AM	09/06/2018
Waterflow Switch	1st Storage in Girls Locker Rm F5	Tested	7:26:04 AM	12/11/2018
<b>Supervisory</b>				
Tamper Switch	1st Hall C Sprinkler Storage Room left	Tested	11:25:30 AM	09/06/2018
Tamper Switch	1st Hall C Sprinkler Storage Room right	Tested	11:25:23 AM	09/06/2018
Device Type	Location	Service	Time	Date
<i>Untested</i>				
<b>Initiating</b>				
Heat Detector	1st Above Ceiling in B-103			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	1st Above Ceiling in B-104			
Heat Detector	1st Above Ceiling in B-105			
Heat Detector	1st Above Ceiling in B-106			
Heat Detector	1st Above Ceiling in B-107			
Heat Detector	1st Above Ceiling in B-108			
Heat Detector	1st Above Ceiling in B-108A			
Heat Detector	1st Above Ceiling in B-109			
Heat Detector	1st Above Ceiling in B-109A			
Heat Detector	1st Above Ceiling in B-110			
Heat Detector	1st Above Ceiling in B-111			
Heat Detector	1st Above Ceiling in B-112			
Heat Detector	1st Above Ceiling in B-114			
Heat Detector	1st Above Ceiling in B-114			
Heat Detector	1st Above Ceiling in B-115			
Heat Detector	1st Above Ceiling in B-14			
Heat Detector	1st Above Ceiling in B-15			
Heat Detector	1st Above Ceiling in room B-13			
Heat Detector	1st elevator machine room			
Heat Detector	1st Storage by room B-13			
Heat Detector	2nd Hall By Room B-201 A/C			
Heat Detector	2nd Hall By Room B-203 Above Ceiling			
Heat Detector	2nd Hall By Room B-204 Above Ceiling			
Heat Detector	2nd Room B-201 Above Ceiling			
Heat Detector	2nd Room B-202 Above Ceiling			
Heat Detector	2nd Room B-202A Above Ceiling			
Heat Detector	2nd Room B-202A Above Ceiling			
Heat Detector	2nd Room B-203 Above Ceiling			
Heat Detector	2nd Room B-204 Above Ceiling			
Heat Detector	2nd Room B-204A Above Ceiling			
Heat Detector	2nd Room B-210 Above Ceiling			
Heat Detector	2nd Room B-211 Above Ceiling			
Heat Detector	2nd Room B-212 Above Ceiling			
Heat Detector	2nd Room B-213 Above Ceiling			
Heat Detector	2nd Room B-213A Above Ceiling			
Heat Detector	2nd Room B-213A Above Ceiling			
Heat Detector	2nd Room B-214 Above Ceiling			
Heat Detector	2nd Room B-215 Above Ceiling			
Heat Detector	2nd Room B-215A Above Ceiling			
Heat Detector	2nd Storage By Room B-215			

**Building: Montgomery Upper Middle School      Control Panel: 2**

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Failed/Other</i></b>				
<b>Control</b>				
Battery	1st In BPS in auditorium storage	Inspected	3:34:52 PM	10/24/2018
Battery	1st In BPS in auditorium storage	Inspected	3:35:45 PM	10/24/2018
Battery	1st In BPS in electric room by gym boys side	Checked	3:17:53 PM	09/06/2018
Battery	1st In BPS in electric room by gym boys side	Checked	3:18:07 PM	09/06/2018
Battery	1st In BPS in room B100	Tested	3:29:26 PM	10/24/2018
Battery	1st In BPS in room B100	Inspected	3:31:07 PM	10/24/2018
Battery	1st In electric closet by gym	Checked	11:23:38 AM	09/06/2018
Battery	1st In electric closet by gym	Checked	11:24:00 AM	09/06/2018
Battery	1st Main office	Checked	9:16:16 AM	09/06/2018
Battery	1st Main office	Checked	3:51:12 PM	10/24/2018
Battery	2nd In BPS in room B200	Checked	3:13:36 PM	09/06/2018
Battery	2nd In BPS in room B200	Checked	3:13:49 PM	09/06/2018

# Service Summary

Generated by: BuildingReports.com

Building: Montgomery Upper Middle School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Battery	Checked	8
Battery	Inspected	3
Battery	Tested	1
Total		12
<b><i>Passed</i></b>		
Annunciator	Tested	1
Control Panel	Tested	1
Duct Detector	Tested	12
Heat Detector	Tested	20
Power Supply	Tested	5
Pull Station	Tested	42
Smoke Detector	Tested	170
Smoke Detector	Tested/Cleaned	23
Tamper Switch	Tested	2
Waterflow Switch	Tested	3
Total		291
<b><i>Untested</i></b>		
Heat Detector		40
Total		331

# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery Upper Middle School		Control Panel: 2					
<p><i>The Control &amp; Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i></p>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<b><i>Failed/Other</i></b>							
<b>Battery</b>							
Sealed Lead Acid	1st In BPS in auditorium storage	7	12				
Sealed Lead Acid	1st In BPS in auditorium storage	7	12				
Sealed Lead Acid	1st In BPS in electric room by gym boys side	7	12				
Sealed Lead Acid	1st In BPS in electric room by gym boys side	7	12				
Sealed Lead Acid	1st In BPS in room B100	7	12				
Sealed Lead Acid	1st In BPS in room B100	7	12				
Sealed Lead Acid	1st In electric closet by gym	7	12				
Sealed Lead Acid	1st In electric closet by gym	7	12				
Sealed Lead Acid	1st Main office	55	12				
Sealed Lead Acid	1st Main office	55	12				
Sealed Lead Acid	2nd In BPS in room B200	7	12				
Sealed Lead Acid	2nd In BPS in room B200	7	12				

# Inventory & Warranty Report

Generated by: [BuildingReports.com](http://BuildingReports.com)

Building: Montgomery Upper Middle School		Control Panel: 1 - EST EST-3		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	18.13%	60	
Battery	Control	3.63%	12	
Control Panel	Control	0.30%	1	
Pull Station	Initiating	12.69%	42	
Smoke Detector	Initiating	58.31%	193	
Power Supply	Control	1.51%	5	
Waterflow Switch	Initiating	0.91%	3	
Tamper Switch	Supervisory	0.60%	2	
Duct Detector	Initiating	3.63%	12	
Annunciator	Control	0.30%	1	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Control Panel	1	EST-3		08/26/2016
Heat Detector	60	SIGA HRS	Combination	08/26/2016
Smoke Detector	1	SIGA PD	Photoelectric	08/26/2016
Smoke Detector	192	SIGA PS	Photoelectric	08/26/2016
<b>Potter Electric</b>				
Tamper Switch	2			08/26/2016
Waterflow Switch	3			08/26/2016
<b>EST</b>				
Annunciator	1	LCD-4	LCD Display	08/25/2016
Duct Detector	12	SIGA SD		08/25/2016
Power Supply	5	BPS10A		08/25/2016
Pull Station	1	EST-3		08/25/2016
Pull Station	4	EST-3	Dual Action	08/25/2016
Pull Station	1	SIGA 270		08/25/2016
Pull Station	1	SIGA 278		08/25/2016
Pull Station	34	SIGA 278	Dual Action	08/25/2016
Pull Station	1	SIGA-278	Dual Action	08/25/2016

**Building: Montgomery Upper Middle School      Control Panel: 2**

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

<b>Type</b>	<b>Qty</b>	<b>Model #</b>	<b>Description</b>	<b>Install Date</b>
<b><i>In Service - 3 Years to 5 Years</i></b>				
<b>Power-Sonic</b>				
Battery	2	ps-12550	Sealed Lead Acid	10/30/2014
<b>Ultra Tech</b>				
Battery	10	UT1270	Sealed Lead Acid	10/30/2014

# Zone Address Report

Generated by: BuildingReports.com

**Building: Montgomery Upper Middle School      Control Panel: 1 - EST   EST-3**

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 03</b>				
0002	Smoke Detector	1st Passage by Cafeteria	Photoelectric	33369282
0003	Smoke Detector	1st Hall by Cafeteria	Photoelectric	33369281
0004	Smoke Detector	1st Cafeteria	Photoelectric	33369279
0005	Smoke Detector	1st Cafeteria	Photoelectric	33369278
0006	Smoke Detector	1st Cafeteria	Photoelectric	33369277
0008	Smoke Detector	1st Cafeteria	Photoelectric	33369276
0009	Smoke Detector	1st Cafeteria	Photoelectric	33369275
0011	Smoke Detector	1st Cafeteria	Photoelectric	33369274
0013	Smoke Detector	1st Cafeteria	Photoelectric	33369280
0014	Smoke Detector	1st Hall C Custodial Office	Photoelectric	33369206
0015	Heat Detector	1st Hall C Custodial Office	Combination	49668557
0016	Smoke Detector	1st Hallway c custodial office	Photoelectric	33369273
0018	Heat Detector	1st Kitchen	Combination	49668556
0020	Heat Detector	1st Kitchen	Combination	49668555
0021	Heat Detector	1st Kitchen	Combination	49668554
0023	Heat Detector	1st Kitchen	Combination	49668553
0024	Duct Detector	RTU1 Wood Shop		33369353
0025	Heat Detector	1st Storage Rm By Kitchen	Combination	49668546
0027	Heat Detector	1st Kitchen toilet	Combination	49668548
0028	Heat Detector	1st Kitchen toilet	Combination	49668547
0030	Heat Detector	1st Kitchen	Combination	49668552
0032	Heat Detector	1st Kitchen	Combination	49668551
0033	Heat Detector	1st Kitchen	Combination	49668550
0034	Heat Detector	1st Kitchen	Combination	49668549
0037	Smoke Detector	1st Kitchen Office	Photoelectric	33369272
0038	Heat Detector	1st Receiving	Combination	49668545
0039	Heat Detector	1st Receiving/Wash Area	Combination	49668544
0042	Smoke Detector	1st Hall by boiler room	Photoelectric	33369205
0043	Smoke Detector	1st Hall by boiler room	Photoelectric	33369204
0057	Heat Detector	1st Room F-103 Storage	Combination	49668543
0067	Smoke Detector	1st Inside Closet Room F-101	Photoelectric	46876320
0093	Smoke Detector	1st Hall C North Breezeway	Photoelectric	33369283
0126	Pull Station	1st Hall C North Breezeway by Cafe	Dual Action	33369168
0127	Pull Station	1st Cafeteria exit nearest breezeway	Dual Action	33369169
0128	Pull Station	1st Cafeteria	Dual Action	33369170
0129	Pull Station	1st Hall C. Custodial Office	Dual Action	33369171
0130	Pull Station	1st Kitchen	Dual Action	33369172
0139	Heat Detector	1st Room F-101 Paint Booth	Combination	49668542
0251	Duct Detector	RTU5 Rooftop Return Side		33369355
0253	Duct Detector	RTU3 Boys side of Weight Room		33369354



0255	Heat Detector	1st Boys Locker Room F-2	Combination	49668541
0256	Heat Detector	1st Boys Locker Room F-2	Combination	49668540
0257	Heat Detector	1st Boys Locker Room F-2	Combination	49668539
0265	Heat Detector	1st By Shower Boys Locker Room F-2	Combination	49668538
0273	Duct Detector	RTU4 Girls Side of Weight Room		33369357
0275	Duct Detector	RTU6 Rooftop Return Side		33369356
0306	Smoke Detector	1st School Store F-5	Photoelectric	49668527
0309	Smoke Detector	1st Hall By Rm E-108	Photoelectric	49668530
0312	Smoke Detector	1st Rm E-101 A	Photoelectric	49668535
0324	Duct Detector	RTU Room E-102		33369184
0325	Duct Detector	RTU Room E-104		33369360
0376	Pull Station	1st Rear Vest Boys Locker F2	Dual Action	42626326
0377	Pull Station	1st Gym F4	Dual Action	42626325
0381	Pull Station	1st Gym F4	Dual Action	42626327
0382	Pull Station	1st Rear Vest Girls Locker F5	Dual Action	42626328
0392	Waterflow Switch	1st Storage in Girls Locker Rm F5		33369363
0394	Waterflow Switch	1st Above Ceiling in Chem Storage by E-104		33369364

### Zone/Circuit: 04

0001	Smoke Detector	1st room C-104	Photoelectric	33369258
0003	Smoke Detector	1st room C-104	Photoelectric	33369259
0004	Smoke Detector	1st room C-104	Photoelectric	33369257
0005	Smoke Detector	1st room C-104B	Photoelectric	33369260
0007	Smoke Detector	1st room C-104A Office	Photoelectric	33369264
0009	Smoke Detector	1st room C-104A Recording	Photoelectric	33369263
0011	Smoke Detector	1st room C-104C	Photoelectric	33369265
0013	Smoke Detector	1st room C-103	Photoelectric	33369269
0015	Smoke Detector	1st room C-103	Photoelectric	33369270
0017	Smoke Detector	1st room C-103	Photoelectric	33369266
0018	Smoke Detector	1st room C-103	Photoelectric	33369267
0020	Smoke Detector	1st room C-103	Photoelectric	33369268
0022	Smoke Detector	1st Hall by room C-103	Photoelectric	33369271
0023	Smoke Detector	1st Hall by room C-103	Photoelectric	33369262
0025	Smoke Detector	1st Hall by room C-104	Photoelectric	33369261
0026	Smoke Detector	1st Hall by room C-104	Photoelectric	33369256
0029	Smoke Detector	1st Stage Auditorium F-1	Photoelectric	33369211
0030	Smoke Detector	1st Entry Auditorium F-1	Photoelectric	33369210
0032	Smoke Detector	1st Stage Auditorium F-1	Photoelectric	33369209
0033	Smoke Detector	1st Stage Auditorium F-1	Photoelectric	33369208
0034	Smoke Detector	1st Stage Auditorium F-1	Photoelectric	33369207
0037	Smoke Detector	1st Side Entry Auditorium F-1	Photoelectric	33369212
0049	Smoke Detector	1st Projector Booth Auditorium F-1	Photoelectric	33369217
0053	Smoke Detector	1st Projector Booth Auditorium F-1	Photoelectric	33369222
0060	Smoke Detector	1st Hall By Rm E-108	Photoelectric	49668528
0062	Smoke Detector	1st Boys Rm By Rm E-108	Photoelectric	49668529
0064	Smoke Detector	1st Hall C by storage/sprinkler rm	Photoelectric	33369225
0066	Smoke Detector	1st Girls lav by room E-108	Photoelectric	33369218
0069	Smoke Detector	1st Storage by room C-102	Photoelectric	33369223
0071	Smoke Detector	1st Storage by room C-102	Photoelectric	33369220
0072	Smoke Detector	1st Room C-102	Photoelectric	33369224
0074	Smoke Detector	1st Hall by room C-102	Photoelectric	33369226
0077	Smoke Detector	1st Hall By Rm E-108	Photoelectric	49668531
0079	Smoke Detector	1st Hall By Rm E-108A	Photoelectric	49668534

0080	Smoke Detector	1st Rm E-108A	Photoelectric	49668532
0082	Smoke Detector	1st Rm E-107	Photoelectric	49668533
0084	Smoke Detector	1st Hall By Room E-107	Photoelectric	49668536
0086	Smoke Detector	1st Hall By Room E-106	Photoelectric	49668537
0102	Smoke Detector	1st Hall By Gym/ Girls Locker Rm	Photoelectric	49668526
0103	Smoke Detector	1st Projector Booth Auditorium F-1	Photoelectric	33369213
0104	Duct Detector	RTU Auditorium F-1		33369219
0105	Duct Detector	RTU Room E-105		33369361
0106	Duct Detector	RTU Room E-107		33369359
0107	Duct Detector	RTU Room E-108		33369358
0126	Pull Station	1st Auditorium exit near c102	Dual Action	33369181
0127	Pull Station	1st Stage Auditorium F-1	Dual Action	33369180
0128	Pull Station	1st Stage Auditorium F-1	Dual Action	33369179
0132	Waterflow Switch	1st Hall C Sprinklers/Storage Room		33369362
0133	Tamper Switch	1st Hall C Sprinkler Storage Room left		33369215
0133	Tamper Switch	1st Hall C Sprinkler Storage Room right		33369221
0139	Pull Station	1st Auditorium F-1	Dual Action	33369178
0251	Smoke Detector	1st Room B-4	Photoelectric	33369347
0254	Smoke Detector	1st Room B-2	Photoelectric	33369349
0256	Smoke Detector	1st Toilet Main Office B-1	Photoelectric	33369345
0257	Smoke Detector	1st Storage Main Office B-1	Photoelectric	33369341
0259	Duct Detector	RTU Media Center C-1		33369253
0260	Smoke Detector	1st Hall B-3 to Main Office B-1	Photoelectric	33369348
0261	Pull Station	1st Main entrance by Office b3	Dual Action	33369160
0261	Smoke Detector	1st Toilet Main Office B-1	Photoelectric	33369344
0264	Smoke Detector	1st Room B-5	Photoelectric	33369346
0265	Smoke Detector	1st Room B-6	Photoelectric	33369343
0267	Smoke Detector	1st Room B-7	Photoelectric	33369340
0269	Smoke Detector	1st Room B-8	Photoelectric	33369337
0271	Smoke Detector	1st Room B-9	Photoelectric	33369338
0274	Smoke Detector	1st Main Office B-1	Photoelectric	33369342
0275	Smoke Detector	1st Records Main Office B-1	Photoelectric	33369339
0277	Smoke Detector	1st Room B-10	Photoelectric	33369336
0280	Smoke Detector	1st Stairs by Room B-101	Photoelectric	33369322
0281	Smoke Detector	1st Room B-101	Photoelectric	33369320
0283	Smoke Detector	1st Room B-102	Photoelectric	33369314
0285	Smoke Detector	1st Hall C North Breezeway	Photoelectric	33369284
0287	Smoke Detector	1st Room B-103	Photoelectric	33369311
0288	Heat Detector	1st Above Ceiling in B-103	Combination	33369195
0289	Smoke Detector	1st Room B-104	Photoelectric	33369310
0290	Heat Detector	1st Above Ceiling in B-104	Combination	33369194
0291	Smoke Detector	1st Room B-104A	Photoelectric	33369309
0296	Smoke Detector	1st Girls Room by B-104	Photoelectric	33369304
0297	Smoke Detector	1st Girls Room by B-104	Photoelectric	33369305
0300	Smoke Detector	1st Boys Room by B-105	Photoelectric	33369302
0301	Smoke Detector	1st Boys Room by B-105	Photoelectric	33369303
0303	Smoke Detector	1st Room B-105	Photoelectric	33369298
0304	Heat Detector	1st Above Ceiling in B-105	Combination	33369192
0306	Smoke Detector	1st Hall C south breezeway	Photoelectric	33369249
0308	Smoke Detector	1st Hall C south breezeway	Photoelectric	33369250
0310	Smoke Detector	1st Hall by room C-101	Photoelectric	33369251
0312	Smoke Detector	1st Hall by room C-101	Photoelectric	33369252
0313	Smoke Detector	1st Hall by room C-102	Photoelectric	33369255

0315	Smoke Detector	1st Hall by room C-102	Photoelectric	33369227
0316	Smoke Detector	1st Storage by room C-102	Photoelectric	33369228
0318	Smoke Detector	1st Media Center C-3	Photoelectric	33369239
0320	Smoke Detector	1st Media Center computer storage	Photoelectric	33369246
0322	Smoke Detector	1st room C-101	Photoelectric	33369254
0324	Smoke Detector	1st Media Center C-2	Photoelectric	33369240
0326	Smoke Detector	1st Media Center A/V storage	Photoelectric	33369247
0328	Smoke Detector	1st Media Center C-1	Photoelectric	33369248
0330	Smoke Detector	1st Media Center C-1	Photoelectric	33369245
0332	Smoke Detector	1st Media Center C-1	Photoelectric	33369244
0333	Smoke Detector	1st Media Center C-1	Photoelectric	33369243
0335	Smoke Detector	1st Media Center C-1	Photoelectric	33369242
0336	Smoke Detector	1st Media Center C-1	Photoelectric	33369241
0338	Smoke Detector	1st Media Center C-1	Photoelectric	33369238
0339	Smoke Detector	1st Media Center C-1	Photoelectric	33369237
0341	Smoke Detector	1st Media Center C-1	Photoelectric	33369236
0343	Smoke Detector	1st Media Center C-1	Photoelectric	33369235
0344	Smoke Detector	1st Media Center C-1	Photoelectric	33369234
0346	Smoke Detector	1st Media Center C-1	Photoelectric	33369233
0348	Smoke Detector	1st Media Center C-1	Photoelectric	33369232
0350	Smoke Detector	1st Media Center C-1	Photoelectric	33369231
0352	Smoke Detector	1st Media Center C-1	Photoelectric	33369229
0353	Smoke Detector	1st Media Center C-1	Photoelectric	33369230
0376	Pull Station	1st Stairs By RMS B10/B101 B stairwell near office at exit	Dual Action	33369161
0377	Pull Station	1st Hall By Room B101	Dual Action	33369162
0378	Pull Station	1st Hall C North Breezeway	Dual Action	33369167
0379	Pull Station	1st South Breezeway hall C	Dual Action	33369174
0380	Pull Station	1st Hall C south Breezeway by media center	Dual Action	33369173
0381	Pull Station	1st media center C-1	Dual Action	33369175
0382	Pull Station	1st media center C-1	Dual Action	33369176
0383	Pull Station	1st media center C-1	Dual Action	33369177

**Zone/Circuit: 05**

0001	Smoke Detector	1st Room B-3	Photoelectric	33369350
0003	Smoke Detector	1st Room B-3	Photoelectric	33369351
0004	Smoke Detector	1st Room B-3 Safe/Vault	Photoelectric	33369352
0009	Smoke Detector	1st Hall by Room B-3	Photoelectric	33369335
0011	Smoke Detector	1st Hall by Room B-1	Photoelectric	33369329
0013	Smoke Detector	1st Hall by Room B-10	Photoelectric	33369323
0014	Smoke Detector	1st Hall by Room B-101	Photoelectric	33369321
0016	Smoke Detector	1st Hall by room B-102	Photoelectric	33369315
0017	Smoke Detector	1st Hall by room B-103	Photoelectric	33369312
0019	Smoke Detector	1st Hall by room B-104	Photoelectric	33369308
0020	Smoke Detector	1st Hall by Room B-111	Photoelectric	33369306
0022	Smoke Detector	1st Hall by Room B-105	Photoelectric	33369300
0023	Smoke Detector	1st Hall by Room B-105	Photoelectric	33369297
0025	Smoke Detector	1st Hall by Room B-106	Photoelectric	33369293
0026	Smoke Detector	1st Elevator Lobby	Photoelectric	33369287
0028	Smoke Detector	1st Room B-106	Photoelectric	33369292
0029	Heat Detector	1st Above Ceiling in B-106	Combination	33369189
0030	Smoke Detector	1st Room B-107	Photoelectric	33369291
0031	Heat Detector	1st Above Ceiling in B-107	Combination	33369187

0033	Smoke Detector	1st Stairs by room B-107	Photoelectric	33369286
0036	Smoke Detector	1st Hall by Elevator Machine Room	Photoelectric	33369288
0038	Smoke Detector	1st Elevator Machine Room	Photoelectric	33369285
0039	Heat Detector	1st elevator machine room	Combination	33369186
0040	Smoke Detector	1st Room B-108A	Photoelectric	33369289
0041	Heat Detector	1st Above Ceiling in B-108A	Combination	33369185
0042	Heat Detector	1st Above Ceiling in B-108	Combination	33369188
0043	Smoke Detector	1st Room B-108	Photoelectric	33369290
0044	Heat Detector	1st Above Ceiling in B-109	Combination	33369191
0045	Smoke Detector	1st Room B-109	Photoelectric	33369294
0046	Heat Detector	1st Above Ceiling in B-109A	Combination	33369190
0047	Smoke Detector	1st Room B-109A	Photoelectric	33369295
0049	Smoke Detector	1st Room B-109A	Photoelectric	33369296
0050	Heat Detector	1st Above Ceiling in B-110	Combination	33369214
0051	Smoke Detector	1st Room B-110	Photoelectric	33369299
0052	Heat Detector	1st Above Ceiling in B-111	Combination	33369193
0053	Smoke Detector	1st Room B-111	Photoelectric	33369301
0054	Smoke Detector	1st Stair by B-111	Photoelectric	33369307
0056	Heat Detector	1st Above Ceiling in B-112	Combination	33369196
0057	Smoke Detector	1st Room B-112	Photoelectric	33369316
0058	Heat Detector	1st Above Ceiling in B-114	Combination	33369197
0059	Smoke Detector	1st Room B-114	Photoelectric	33369317
0060	Smoke Detector	1st Room B-16	Photoelectric	33369313
0062	Heat Detector	1st Above Ceiling in B-114	Combination	33369198
0063	Smoke Detector	1st Room B-114	Photoelectric	33369318
0064	Heat Detector	1st Above Ceiling in B-115	Combination	33369199
0065	Smoke Detector	1st Room B-115	Photoelectric	33369319
0066	Heat Detector	1st Above Ceiling in B-15	Combination	33369200
0067	Smoke Detector	1st Room B-15	Photoelectric	33369324
0068	Heat Detector	1st Above Ceiling in B-14	Combination	33369201
0069	Smoke Detector	1st Room B-11	Photoelectric	33369334
0071	Smoke Detector	1st Toilet by Main Office B-1	Photoelectric	33369326
0072	Heat Detector	1st Storage by room B-13	Combination	33369202
0073	Smoke Detector	1st Room B-13 Toilet	Photoelectric	33369327
0075	Heat Detector	1st Above Ceiling in room B-13	Combination	33369203
0076	Smoke Detector	1st Room B-13	Photoelectric	33369328
0077	Smoke Detector	1st Room B-12 Private Toilet	Photoelectric	33369330
0079	Smoke Detector	1st Room B-12 Student Toilet	Photoelectric	33369332
0082	Smoke Detector	1st Room B-12	Photoelectric	33369331
0084	Smoke Detector	1st Room B-14	Photoelectric	33369325
0086	Smoke Detector	1st Room B-11	Photoelectric	33369333
0126	Pull Station	1st Main Office by Safe	Dual Action	33369159
0128	Pull Station	1st Stairs By Rm B107	Dual Action	33369166
0129	Pull Station	1st Hall by B107	Dual Action	33369165
0130	Pull Station	1st Stairs By Rm B111	Dual Action	33369164
0131	Pull Station	1st Hall By Rm B111	Dual Action	33369163
0251	Smoke Detector	2nd Stairs By Room B-201	Photoelectric	46875812
0253	Smoke Detector	2nd Hall By Room B-201	Photoelectric	46875813
0254	Heat Detector	2nd Hall By Room B-201 A/C	Combination	46875852
0255	Heat Detector	2nd Storage By Room B-215	Combination	46875849
0256	Smoke Detector	2nd Rm B-215A	Photoelectric	46875848
0257	Heat Detector	2nd Room B-215A Above Ceiling	Combination	46875851
0258	Smoke Detector	2nd Room B-215	Photoelectric	46875847

0259	Heat Detector	2nd Room B-215 Above Ceiling	Combination	46875850
0260	Smoke Detector	2nd Room B-214	Photoelectric	46875845
0261	Heat Detector	2nd Room B-214 Above Ceiling	Combination	46875854
0262	Smoke Detector	2nd Rm B-213A	Photoelectric	46875843
0263	Heat Detector	2nd Room B-213A Above Ceiling	Combination	46875857
0264	Smoke Detector	2nd Rm B-213A	Photoelectric	46875842
0265	Heat Detector	2nd Room B-213A Above Ceiling	Combination	46875856
0266	Smoke Detector	2nd Room B-213	Photoelectric	46875839
0267	Heat Detector	2nd Room B-213 Above Ceiling	Combination	46875861
0268	Smoke Detector	2nd Room B-212	Photoelectric	46875837
0269	Heat Detector	2nd Room B-212 Above Ceiling	Combination	46875863
0270	Smoke Detector	2nd Stairs By Room B-212	Photoelectric	46875817
0272	Smoke Detector	2nd Room B-211	Photoelectric	46875834
0273	Heat Detector	2nd Room B-211 Above Ceiling	Combination	46875866
0274	Smoke Detector	2nd Room B-210	Photoelectric	46875833
0275	Heat Detector	2nd Room B-210 Above Ceiling	Combination	46875868
0276	Smoke Detector	2nd Rm B-209A	Photoelectric	46875830
0278	Smoke Detector	2nd Rm B-209A	Photoelectric	46875831
0280	Smoke Detector	2nd Room B-209	Photoelectric	46875827
0282	Smoke Detector	2nd Room B-208	Photoelectric	46875824
0287	Smoke Detector	2nd Rm B-208A	Photoelectric	46875823
0289	Smoke Detector	2nd Hall By Room B-208A	Photoelectric	46875821
0292	Smoke Detector	2nd Elevator Lobby	Photoelectric	46875820
0294	Smoke Detector	2nd Stairs By Room B-207	Photoelectric	46875822
0297	Smoke Detector	2nd Room B-207	Photoelectric	46875825
0298	Smoke Detector	2nd Hall By Room B-207	Photoelectric	46875819
0300	Smoke Detector	2nd Room B-206	Photoelectric	46875826
0302	Smoke Detector	2nd Hall By Room B-206	Photoelectric	46875818
0304	Smoke Detector	2nd Rm B-205A	Photoelectric	46875829
0306	Smoke Detector	2nd Rm B-205A	Photoelectric	46875828
0307	Smoke Detector	2nd Room B-205	Photoelectric	46875832
0318	Heat Detector	2nd Hall By Room B-204 Above Ceiling	Combination	46875867
0322	Smoke Detector	2nd Rm B-204A	Photoelectric	46875836
0323	Heat Detector	2nd Room B-204A Above Ceiling	Combination	46875865
0324	Heat Detector	2nd Room B-204 Above Ceiling	Combination	46875864
0325	Smoke Detector	2nd Room B-204	Photoelectric	46875835
0326	Smoke Detector	2nd Hall By Room B-204	Photoelectric	46875816
0327	Heat Detector	2nd Hall By Room B-203 Above Ceiling	Combination	46875860
0328	Smoke Detector	2nd Hall By Room B-203	Photoelectric	46875815
0329	Heat Detector	2nd Room B-203 Above Ceiling	Combination	46875862
0330	Smoke Detector	2nd Room B-203	Photoelectric	46875838
0331	Smoke Detector	2nd Rm B-202A	Photoelectric	46875840
0332	Heat Detector	2nd Room B-202A Above Ceiling	Combination	46875859
0333	Smoke Detector	2nd Room B-202A	Photoelectric	46875841
0334	Heat Detector	2nd Room B-202A Above Ceiling	Combination	46875858
0335	Heat Detector	2nd Room B-202 Above Ceiling	Combination	46875855
0336	Smoke Detector	2nd Room B-202	Photoelectric	46875844
0337	Smoke Detector	2nd Hall By Room B-202	Photoelectric	46875814
0338	Heat Detector	2nd Room B-201 Above Ceiling	Combination	46875853
0339	Smoke Detector	2nd Room B-201	Photoelectric	46875846

**Zone/Circuit: 3**

131	Pull Station	1st In Boiler Room By Exit	42626307
132	Pull Station	1st In Boiler Room By Entrance	42626306

133	Pull Station	1st Hall By Room F102	Dual Action	42626304
135	Pull Station	1st Hall By Room F105	Dual Action	42626305
378	Pull Station	1st Hall Vest Boys Locker F2		42626324
379	Pull Station	1st Hall Vest Girls Locker F5	Dual Action	42626329
391	Pull Station	1st Hall By Room E108	Dual Action	42626300
<b>Zone/Circuit: 4</b>				
129	Pull Station	1st In Auditorium F-1	Dual Action	42626302
130	Pull Station	1st In Auditorium F-1	Dual Action	42626303
131	Pull Station	1st Hall By Auditorium F1	Dual Action	42626301
134	Pull Station	1st Hall By Room E106	Dual Action	42626299
135	Pull Station	1st Next to exit doors By Room E104	Dual Action	42626287
<b>Zone/Circuit: 5</b>				
376	Pull Station	2nd In Hallway By Mech. Room/Roof Access	Dual Action	42626298
377	Pull Station	2nd In Hallway By Storage Room B200	Dual Action	42626297
378	Pull Station	2nd In Hallway By Room B207	Dual Action	42626286

# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery Lower Middle  
School  
373 Burnt Hill Rd  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
*Dec 18, 2018*

Building: Montgomery Lower Middle School  
Contact: Dave Klein  
Title: B&G Mgr.

Company: Alarm & Communication Technologies  
Contact: Robert Kilcher  
Title: Inspector

# Executive Summary

Generated by: BuildingReports.com

Building Information		
<b>Building:</b> Montgomery Lower Middle School	<b>Contact:</b> Dave Klein	
<b>Address:</b> 373 Burnt Hill Rd	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Robert Kilcher	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 2018416983	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 2018416983	
<b>Country:</b> United States of America	<b>Email:</b> RobertK@njact.com	
System Control Unit		
<b>Manufacturer:</b> EST	<b>Inspection Date:</b> 12/12/2018	<b>IDC Style:</b> B
<b>Model Number:</b> EST 3	<b>Install Date:</b> 11/09/2018	<b>SLC Style:</b> 4
<b>Software Version:</b> 5.30.00	<b>Version Date:</b> 11/09/2018	<b>NAC Style:</b> Y
<b>Location:</b> Exterior boiler room	<b>Current Protection:</b> Breaker	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b>	<b>Mfg:</b>	<b>Model #:</b>
<b>Test Time/Date:</b>	<b>Restore Time</b>	



Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	4	2.58%	4	100.00%	4	100.00%	0	0%
Initiating	150	96.77%	137	91.33%	136	99.27%	1	0.73%
Supervisory	1	0.65%	1	100.00%	1	100.00%	0	0%
<b>Totals</b>	<b>155</b>	<b>100%</b>	<b>142</b>	<b>91.61%</b>	<b>141</b>	<b>99.30%</b>	<b>1</b>	<b>0.70%</b>
Certification								
Company: Alarm & Communication Technologies				Building: Montgomery Lower Middle School				
Inspector: Robert Kilcher				Contact: Dave Klein				
Signed:				Signed:				

# Discrepancy Report

Generated by: BuildingReports.com

<b>Building: Montgomery Lower Middle School      Control Panel: 1 - EST    EST 3</b>				
<i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i>				
<b>Device Type</b>	<b>Manufacturer</b>	<b>ModelNumber</b>	<b>Date</b>	<b>Qty</b>
<b><i>Items listed for Recall by Manufacturer</i></b>				
No recalled items found during this inspection.				
<b>ScanID</b>	<b>Location</b>	<b>Problem</b>	<b>Address</b>	<b>Reference</b>
<b><i>Initiating</i></b>				
<b>Pull Station</b>				
44323068	Cafeteria E 2	Damaged/Worn	1-0612	NFPA72 14.2.2.2.2
<b><i>Code References</i></b>				
NFPA72 14.2.2.2.2	System deficiencies shall be corrected.			

# *Proposed Solutions Report*

*Generated by: BuildingReports.com*

Building: Montgomery Lower Middle School			Control Panel: 1 - EST EST 3		
<i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i>					
ScanID	Location	Solution	Model #	Cost	Fix
<b><i>Initiating</i></b>					
<b>Pull Station</b>					
44323068	Cafeteria E 2	Replace	SIGA 278	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

# Notes & Recommendations

Generated by: BuildingReports.com

## Building: Montgomery Lower Middle School

The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.

### General Note

0631- Should Read "Gym"

0630- Should Read "Gym"

0632- Should Read "Gym"

0633- Should Read "Gym"

0605- Should Read "Gym"

0607- Should Read "Hall in Gym By Offices"

01-02-0087 Should Read " Main Office By Principals Office"

0207- Should Read D Block By D-4

0202- Should Read "On Ramp By Rm B-1"

01-03-0091 should read, " Media Center HVAC-3C"

01-04-0101 Pull Station Should Read, " F-Block Vestibule" also pull station is damaged(siga 278)

01-02-0043 Smoke Detector Should Read, " A4 Vestibule"

01-02-0110 Pull Station is not at ADA height- A4 Vestibule(marked with orange tape)

01-02-0110 Pull Station should read, "A4 Vestibule"

01-02-0103 Pull Station is not at ADA height- On Ramp to B-block(marked with orange tape)

01-02-0103 Pull Station should read, " On Ramp to B-block"

01-04-0071 Duct Should Read, " E Block Rm E-1 band orchestra"

01-04-0123 Pull Station in faculty dining is not at ADA height

01-04-0052 Heat Detector should read, " Hall outside kitchen office"

#### \*\*\*\* NOTE\*\*\*\*

7 troubles on panel upon arrival

- Ground Fault Detection
- Ground Fault
- Network Panel 02 Communication Fault
- Network Panel 04 Communication Fault
- C-Block booster 2 trouble mech rm
- Central Station
- Receiver Test Line 1

- Untested duct detectors are because of classes going on

# Inspection & Testing

Generated by: BuildingReports.com

**Building: Montgomery Lower Middle School      Control Panel: 1 - EST EST 3**

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Annunciator	A4 Vestibule	Tested	2:16:30 PM	12/12/2018
Battery	Battery Cabinet next to FACP	Tested	8:48:33 AM	12/12/2018
Battery	Battery Cabinet next to FACP	Tested	8:50:58 AM	12/12/2018
Control Panel	Exterior boiler room	Tested	8:53:02 AM	12/12/2018
<b>Initiating</b>				
Duct Detector	1st E Block Rm E-1 Band Orchresta E block ensemble rm e24	Tested	11:23:50 AM	12/12/2018
Duct Detector	1st Media Center D block work rm d38	Tested	10:33:38 AM	12/12/2018
Duct Detector	1st D block prep by rm d7	Tested	9:44:41 AM	12/12/2018
Heat Detector	1st E- Block Janitors Closet E-11	Tested	1:55:42 PM	12/12/2018
Heat Detector	1st E-Block Storage BTWN Kit./Recv Rm	Tested	1:53:29 PM	12/12/2018
Heat Detector	1st E-Block Faculty Dining E-16	Tested	2:07:52 PM	12/12/2018
Heat Detector	1st E-Block Kitchen Dishwasher E-06	Tested	2:05:08 PM	12/12/2018
Heat Detector	1st E-Block Kitchen Office E-08	Tested	1:58:05 PM	12/12/2018
Heat Detector	1st E-Block Receiving/ Cust E-20	Tested	2:09:21 PM	12/12/2018
Heat Detector	1st E block kitchen E05	Tested	2:02:58 PM	12/12/2018
Heat Detector	1st E block kitchen E05	Tested	2:03:28 PM	12/12/2018
Heat Detector	1st E block kitchen E05	Tested	2:04:19 PM	12/12/2018
Heat Detector	1st E block toilet e10	Tested	2:06:34 PM	12/12/2018
Heat Detector	1st E block vestibule	Tested	8:56:32 AM	12/12/2018
Pull Station	Corr. ADJ Courtyard	Tested	9:27:11 AM	08/11/2017
Pull Station	A Block Interior Court	Tested	9:25:06 AM	08/11/2017
Pull Station	B Block Corr Near Teams B-1	Tested	9:32:52 AM	08/11/2017
Pull Station	B Block Interior Court	Tested	9:29:06 AM	08/11/2017
Pull Station	C Block Interior Court	Tested	9:45:14 AM	08/11/2017
Pull Station	C Block Mech Rm C-1	Tested	9:47:58 AM	08/11/2017
Pull Station	C Block Mech Room C-1 ATC Interface	Tested	7:28:31 AM	08/11/2017
Pull Station	Cafeteria E 02	Tested	8:16:05 AM	08/11/2017
Pull Station	D Block Corr Adj Art Class D-9	Tested	9:54:20 AM	08/11/2017
Pull Station	D Block Corr. Adj. Girls B25	Tested	9:35:36 AM	08/11/2017
Pull Station	D Block Corr. to C Block	Tested	9:50:22 AM	08/11/2017
Pull Station	D Block Corridor to C Block	Tested	9:39:56 AM	08/11/2017
Pull Station	D Block Corridor to C Block	Tested	9:41:24 AM	08/11/2017
Pull Station	D Block Ind Arts Prod D-12	Tested	9:57:09 AM	08/11/2017
Pull Station	D Block Lounge	Tested	9:51:03 AM	08/11/2017
Pull Station	D Block Vestibule D01	Tested	9:20:32 AM	08/11/2017
Pull Station	E Block Band/ Orchestra E2	Tested	8:02:57 AM	08/11/2017
Pull Station	E Block Cafeteria E 02	Tested	8:22:01 AM	08/11/2017

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	E Block Cafeteria E 2	Tested	8:19:42 AM	08/11/2017
Pull Station	E Block Corr. ADJ recv/Cust E-20	Tested	7:33:16 AM	08/11/2017
Pull Station	E Block Faculty Dining E16	Tested	9:02:02 AM	08/11/2017
Pull Station	E Block Mech Room E17	Tested	10:00:13 AM	08/11/2017
Pull Station	F Block Admin F 03	Tested	9:10:15 AM	08/11/2017
Pull Station	F Block Cabbage Adj Sub F 20 Main office f20 exit by principals office	Tested	9:12:57 AM	08/11/2017
Pull Station	F Block Common F42	Tested	8:10:34 AM	08/11/2017
Pull Station	F Block Commons F42	Tested	8:13:19 AM	08/11/2017
Pull Station	F Block Corridor ADJ Gym	Tested	8:52:31 AM	08/11/2017
Pull Station	F Block Gym	Tested	8:41:26 AM	08/11/2017
Pull Station	F Block Passage ABJ Gym Office	Tested	8:38:37 AM	08/11/2017
Pull Station	F Block Vestibule 02	Tested	8:31:28 AM	08/11/2017
Pull Station	Gym	Tested	8:34:33 AM	08/11/2017
Pull Station	Gym	Tested	8:46:58 AM	08/11/2017
Pull Station	Gym	Tested	8:48:25 AM	08/11/2017
Pull Station	Gym F Block	Tested	8:43:19 AM	08/11/2017
Pull Station	Gym F Block	Tested	8:46:06 AM	08/11/2017
Pull Station	Gym F Block	Tested	8:49:34 AM	08/11/2017
Pull Station	Gym F Block	Tested	8:50:49 AM	08/11/2017
Pull Station	Boiler room e17 exit by FACP	Tested	7:17:05 AM	08/11/2017
Pull Station	D block by d-4	Tested	9:17:38 AM	08/11/2017
Pull Station	E block Band/ Orchestra E-1	Tested	8:06:22 AM	08/11/2017
Smoke Detector	1st A Block Corr ADJ. Girls	Tested	12:40:00 PM	08/11/2017
Smoke Detector	1st A Block Corridor ADJ Team Rm A-14	Tested	12:40:45 PM	08/11/2017
Smoke Detector	1st A Block- Interior Court	Tested	12:41:45 PM	08/11/2017
Smoke Detector	1st A Block- Interior Court	Tested	12:42:33 PM	08/11/2017
Smoke Detector	1st A Block- Interior Court	Tested	12:42:44 PM	08/11/2017
Smoke Detector	1st A Block- Vestibule	Tested	12:42:58 PM	08/11/2017
Smoke Detector	1st B Block- Corr ADJ Classroom B-14	Tested	12:50:43 PM	08/11/2017
Smoke Detector	1st B Block- Corr ADJ Classroom B-2	Tested	12:49:12 PM	08/11/2017
Smoke Detector	1st B Block- Corridor ADJ Team Rm B-1	Tested	12:49:57 PM	08/11/2017
Smoke Detector	1st B Block- Interior Court ADJ B-10	Tested	12:48:27 PM	08/11/2017
Smoke Detector	1st B Block- Interior Court ADJ B-12	Tested	12:48:49 PM	08/11/2017
Smoke Detector	1st B Block- Interior Court ADJ B-7	Tested	12:47:39 PM	08/11/2017
Smoke Detector	1st B Block- Vestibule	Tested	12:46:44 PM	08/11/2017
Smoke Detector	1st C Block- Corr ADJ Class C-2	Tested	12:55:18 PM	08/11/2017
Smoke Detector	1st C Block- Corr ADJ Mech Rm C-1	Tested	12:54:39 PM	08/11/2017
Smoke Detector	1st C Block- Corridor to C Block	Tested	12:52:22 PM	08/11/2017
Smoke Detector	1st C Block- Interior Court	Tested	12:55:52 PM	08/11/2017
Smoke Detector	1st C Block- Interior Court	Tested	12:56:23 PM	08/11/2017
Smoke Detector	1st C Block- Interior Court	Tested	12:56:42 PM	08/11/2017
Smoke Detector	1st C Block- Vestibule	Tested	12:57:00 PM	08/11/2017
Smoke Detector	1st D Block Corr ADJ Team Room B-1	Tested	12:44:53 PM	08/11/2017
Smoke Detector	1st D Block Corridor ADJ Courtyard	Tested	12:44:23 PM	08/11/2017
Smoke Detector	1st D Block Corridor ADJ Girls D-18	Tested	12:43:23 PM	08/11/2017
Smoke Detector	1st D Block Corridor to Commons D02	Tested	12:38:15 PM	08/11/2017
Smoke Detector	1st D Block- Commons D-2	Tested	12:39:29 PM	08/11/2017
Smoke Detector	1st D Block- Lounge	Tested	12:35:59 PM	08/11/2017
Smoke Detector	1st D Block- Lounge	Tested	12:36:26 PM	08/11/2017

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	1st D Block- Lounge	Tested	12:36:56 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:31:20 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:32:03 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:32:27 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:32:47 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:33:06 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:33:30 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:37:13 PM	08/11/2017
Smoke Detector	1st D Block- Media Center D35	Tested	12:37:51 PM	08/11/2017
Smoke Detector	1st D Block- Vestibule D01	Tested	12:38:56 PM	08/11/2017
Smoke Detector	1st F Block- Passage F08	Tested	11:37:46 AM	12/18/2018
Smoke Detector	1st F Block- Passage F09	Tested	12:30:58 PM	08/11/2017
Smoke Detector	1st D block corr adj to boys d23	Tested	12:28:37 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d1 home ec	Tested	12:28:36 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d10	Tested	12:28:22 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d11	Tested	12:28:21 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d2	Tested	12:28:34 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d2	Tested	12:28:35 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d4	Tested	12:28:33 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d6	Tested	12:28:31 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d7	Tested	12:28:26 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d8	Tested	12:28:25 PM	08/11/2017
Smoke Detector	1st D block corr adj to class d9	Tested	12:28:23 PM	08/11/2017
Smoke Detector	1st D block corr adj to d block lounge	Tested	12:28:27 PM	08/11/2017
Smoke Detector	1st D block corr adj to girls d25	Tested	12:28:38 PM	08/11/2017
Smoke Detector	1st D block corr adj to girls d33	Tested	12:28:36 PM	08/11/2017
Smoke Detector	1st D block corr adj to ind arts d12	Tested	12:28:21 PM	08/11/2017
Smoke Detector	1st D block corr adj to prep rm C27	Tested	12:28:32 PM	08/11/2017
Smoke Detector	1st D block corr adj to stor d35	Tested	12:28:20 PM	08/11/2017
Smoke Detector	1st D block corr adj to work d38	Tested	12:28:26 PM	08/11/2017
Smoke Detector	1st D block gallery d01	Tested	12:28:08 PM	08/11/2017
Smoke Detector	1st D block gallery d01	Tested	12:28:09 PM	08/11/2017
Smoke Detector	1st D block gallery d01	Tested	12:28:09 PM	08/11/2017
Smoke Detector	1st D block gallery d01	Tested	12:28:10 PM	08/11/2017
Smoke Detector	1st D block ramp	Tested	12:28:18 PM	08/11/2017
Smoke Detector	1st D block vestibule	Tested	12:28:24 PM	08/11/2017
Smoke Detector	1st E block corr adj to band/orchestra	Tested	12:28:05 PM	08/11/2017
Smoke Detector	1st E block corr adj to caf	Tested	12:28:07 PM	08/11/2017
Smoke Detector	1st E block corr adj to receiving e20	Tested	12:28:02 PM	08/11/2017
Smoke Detector	1st E block corr to kitchen e05	Tested	12:28:44 PM	08/11/2017
Smoke Detector	1st E block corr to kitchen e05	Tested	12:28:45 PM	08/11/2017
Smoke Detector	1st E block corr to kitchen e05	Tested	12:28:45 PM	08/11/2017
Smoke Detector	1st F block commons f42	Tested	12:28:39 PM	08/11/2017
Smoke Detector	1st F block commons f42	Tested	12:28:40 PM	08/11/2017
Smoke Detector	1st F block commons f42	Tested	12:28:40 PM	08/11/2017
Smoke Detector	1st F block commons f42	Tested	12:28:42 PM	08/11/2017
Smoke Detector	1st F block corr adj to gym	Tested	12:28:13 PM	08/11/2017
Smoke Detector	1st F block corr adj to gym	Tested	12:28:14 PM	08/11/2017
Smoke Detector	1st F block corr adj to gym	Tested	12:28:16 PM	08/11/2017
Smoke Detector	1st F block corr to gym adj to gym office	Tested	12:28:43 PM	08/11/2017



Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
Smoke Detector	1st F block gallery f01	Tested	12:28:11 PM	08/11/2017
Smoke Detector	1st F block gallery f01	Tested	12:28:12 PM	08/11/2017
Smoke Detector	1st F block vestibule	Tested	12:28:17 PM	08/11/2017
Smoke Detector	1st F block vestibule f43	Tested	12:28:41 PM	08/11/2017
Waterflow Switch	Boiler rm e17	Tested	11:37:59 AM	12/18/2018
<b>Supervisory</b>				
Tamper Switch	Boiler room e17	Tested	11:37:55 AM	12/18/2018
Device Type	Location	Service	Time	Date
<b><i>Failed/Other</i></b>				
<b>Initiating</b>				
Pull Station	Cafeteria E 2	Tested	8:19:05 AM	08/11/2017
Device Type	Location	Service	Time	Date
<b><i>Untested</i></b>				
<b>Initiating</b>				
Duct Detector	1st D block home ec rm d1			
Duct Detector	1st E block kitchen e05			
Duct Detector	1st E block practice rm e23			
Heat Detector	1st E block band/orchestra			
Heat Detector	1st E block band/orchestra			
Heat Detector	1st E block choral music e2			
Heat Detector	1st E block choral music e2			
Heat Detector	1st E block elec rm in receiving			
Heat Detector	1st E block ensemble rm e24			
Heat Detector	1st E block practice e23			
Heat Detector	1st E block rm adj to practice e23			
Heat Detector	1st E block stage storage E04			
Heat Detector	1st E block vestibule			

# Service Summary

Generated by: BuildingReports.com

Building: Montgomery Lower Middle School		
<p><i>The Service Summary section provides an overview of the services performed in this report.</i></p>		
Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Pull Station	Tested	1
Total		1
<b><i>Passed</i></b>		
Annunciator	Tested	1
Battery	Tested	2
Control Panel	Tested	1
Duct Detector	Tested	3
Heat Detector	Tested	11
Pull Station	Tested	40
Smoke Detector	Tested	81
Tamper Switch	Tested	1
Waterflow Switch	Tested	1
Total		142
<b><i>Untested</i></b>		
Duct Detector		3
Heat Detector		10
Total		155

# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery Lower Middle School		Control Panel: 1 - EST EST 3					
<p><i>The Control &amp; Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i></p>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<b><i>Passed</i></b>							
<b>Battery</b>							
Sealed Lead Acid	Battery Cabinet next to FACP	44	12				
Sealed Lead Acid	Battery Cabinet next to FACP	44	12				

# Inventory & Warranty Report

Generated by: *BuildingReports.com*

Building: Montgomery Lower Middle School		Control Panel: 1 - EST EST 3		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	13.55%	21	
Duct Detector	Initiating	3.87%	6	
Pull Station	Initiating	26.45%	41	
Smoke Detector	Initiating	52.26%	81	
Battery	Control	1.29%	2	
Control Panel	Control	0.65%	1	
Annunciator	Control	0.65%	1	
Tamper Switch	Supervisory	0.65%	1	
Waterflow Switch	Initiating	0.65%	1	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 90 Days - 1 Year</i></b>				
<b>EST</b>				
Control Panel	1	EST 3		11/09/2018
<b>Interstate Batteries</b>				
Battery	2	SLA1161	Sealed Lead Acid	11/01/2018
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Duct Detector	6		Photoelectric	08/31/2016
Heat Detector	10	5551	Fixed Temperature	08/31/2016
Heat Detector	10	5551	Rate-of-Rise	08/31/2016
<b>System Sensor</b>				
Heat Detector	1	2251		08/31/2016
Smoke Detector	81	2251	Photoelectric	08/31/2016
<b>EST</b>				
Annunciator	1	LCD-3	LCD Display	08/29/2016
Pull Station	41	SIGA 278	Dual Action	08/29/2016
<b>Potter Electric</b>				
Tamper Switch	1			08/29/2016
Waterflow Switch	1			08/29/2016

# Zone Address Report

Generated by: BuildingReports.com

**Building: Montgomery Lower Middle School      Control Panel: 1 - EST   EST 3**

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
01-02-0113	Duct Detector	1st D block prep by rm d7	Photoelectric	33369573
0117	Smoke Detector	1st B Block- Vestibule	Photoelectric	46875897
0118	Smoke Detector	1st B Block- Interior Court ADJ B-7	Photoelectric	46875898
0119	Smoke Detector	1st B Block- Interior Court ADJ B-10	Photoelectric	46875899
0120	Smoke Detector	1st B Block- Interior Court ADJ B-12	Photoelectric	46875900
0121	Smoke Detector	1st B Block- Corr ADJ Classroom B-2	Photoelectric	46875901
0122	Smoke Detector	1st B Block- Corridor ADJ Team Rm B-1	Photoelectric	46875902
0123	Smoke Detector	1st B Block- Corr ADJ Classroom B-14	Photoelectric	46875903
0128	Smoke Detector	1st D block corr adj to girls d25	Photoelectric	33369538
0129	Smoke Detector	1st D block corr adj to boys d23	Photoelectric	33369537
0130	Smoke Detector	1st D block corr adj to d block lounge	Photoelectric	33369529
0131	Smoke Detector	1st D block corr adj to class d6	Photoelectric	33369530
0132	Smoke Detector	1st D block corr adj to prep rm C27	Photoelectric	33369531
0133	Smoke Detector	1st D block corr adj to class d4	Photoelectric	33369532
0134	Smoke Detector	1st D Block Corr ADJ Team Room B-1	Photoelectric	46875896
0135	Smoke Detector	1st D Block Corridor ADJ Courtyard	Photoelectric	46875895
0136	Smoke Detector	1st D Block Corridor ADJ Girls D-18	Photoelectric	46875894
0141	Smoke Detector	1st D block corr adj to class d2	Photoelectric	33369533
0142	Smoke Detector	1st D block corr adj to class d2	Photoelectric	33369534
0143	Smoke Detector	1st D Block- Vestibule D01	Photoelectric	46875886
0144	Smoke Detector	1st D Block- Commons D-2	Photoelectric	46875887
0145	Smoke Detector	1st D Block Corridor to Commons D02	Photoelectric	46875885
0146	Smoke Detector	1st A Block Corr ADJ. Girls	Photoelectric	46875888
0147	Smoke Detector	1st A Block Corridor ADJ Team Rm A-14	Photoelectric	46875889
0148	Smoke Detector	1st A Block- Interior Court	Photoelectric	46875890
0149	Smoke Detector	1st A Block- Interior Court	Photoelectric	46875891
0150	Smoke Detector	1st A Block- Interior Court	Photoelectric	46875892
0151	Smoke Detector	1st A Block- Vestibule	Photoelectric	46875893
0185	Smoke Detector	1st F Block- Passage F09	Photoelectric	46875873
0187	Smoke Detector	1st F Block- Passage F08	Photoelectric	46875872
0192	Smoke Detector	1st F block gallery f01	Photoelectric	33369514
0193	Smoke Detector	1st F block gallery f01	Photoelectric	33369513
0201	Pull Station	B Block Interior Court	Dual Action	33369401
0202	Pull Station	B Block Corr Near Teams B-1	Dual Action	33369402
0203	Pull Station	D Block Corr. Adj. Girls B25	Dual Action	44323081
0204	Pull Station	D Block Corr. to C Block	Dual Action	33369403
0206	Pull Station	Corr. ADJ Courtyard	Dual Action	33369400
0207	Pull Station	D block by d-4	Dual Action	33369396
0208	Pull Station	F Block Vestibule 02	Dual Action	33369395
0210	Pull Station	D Block Vestibule D01	Dual Action	33369398
0211	Pull Station	A Block Interior Court	Dual Action	33369399
0212	Pull Station	F Block Cabbage Adj Sub F 20 Main	Dual Action	33369394

		office f20 exit by principals office		
0213	Pull Station	F Block Admin F 03	Dual Action	33369393
0319	Smoke Detector	1st C Block- Vestibule	Photoelectric	46875910
0320	Smoke Detector	1st C Block- Interior Court	Photoelectric	46875909
0321	Smoke Detector	1st C Block- Interior Court	Photoelectric	46875908
0322	Smoke Detector	1st C Block- Interior Court	Photoelectric	46875907
0323	Smoke Detector	1st C Block- Corr ADJ Class C-2	Photoelectric	46875906
0324	Smoke Detector	1st C Block- Corr ADJ Mech Rm C-1	Photoelectric	46875905
0325	Smoke Detector	1st C Block- Corridor to C Block	Photoelectric	46875904
0326	Smoke Detector	1st D block corr adj to class d7	Photoelectric	33369528
0327	Smoke Detector	1st D block corr adj to work d38	Photoelectric	33369527
0328	Smoke Detector	1st D block corr adj to class d8	Photoelectric	33369526
0329	Smoke Detector	1st D block vestibule	Photoelectric	33369525
0330	Smoke Detector	1st D block corr adj to class d9	Photoelectric	33369524
0331	Smoke Detector	1st D block corr adj to class d10	Photoelectric	33369523
0332	Smoke Detector	1st D block corr adj to class d11	Photoelectric	33369522
0333	Smoke Detector	1st D block corr adj to ind arts d12	Photoelectric	33369521
0361	Smoke Detector	1st D Block- Lounge	Photoelectric	46875881
0362	Smoke Detector	1st D Block- Lounge	Photoelectric	46875882
0363	Smoke Detector	1st D Block- Lounge	Photoelectric	46875880
0364	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875878
0365	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875877
0366	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875876
0367	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875879
0369	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875875
0370	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875874
0371	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875883
0372	Smoke Detector	1st D Block- Media Center D35	Photoelectric	46875884
0373	Smoke Detector	1st D block corr adj to class d1 home ec	Photoelectric	33369535
0374	Smoke Detector	1st D block corr adj to girls d33	Photoelectric	33369536
0375	Smoke Detector	1st D block corr adj to stor d35	Photoelectric	33369520
0376	Smoke Detector	1st D block ramp	Photoelectric	33369519
0377	Smoke Detector	1st D block gallery d01	Photoelectric	33369512
0383	Smoke Detector	1st D block gallery d01	Photoelectric	33369510
0384	Smoke Detector	1st D block gallery d01	Photoelectric	33369509
0385	Smoke Detector	1st D block gallery d01	Photoelectric	33369511
0386	Duct Detector	1st D block home ec rm d1	Photoelectric	33369571
0401	Pull Station	C Block Interior Court	Dual Action	33369406
0402	Pull Station	C Block Mech Rm C-1	Dual Action	46875871
0403	Pull Station	D Block Corridor to C Block	Dual Action	33369404
0404	Pull Station	D Block Corridor to C Block	Dual Action	33369405
0407	Pull Station	C Block Mech Room C-1 ATC Interface	Dual Action	44323066
0408	Pull Station	D Block Corr Adj Art Class D-9	Dual Action	33369407
0409	Pull Station	D Block Lounge	Dual Action	33369397
0410	Pull Station	D Block Ind Arts Prod D-12	Dual Action	33369408
0501	Smoke Detector	1st F block vestibule	Photoelectric	33369518
0502	Smoke Detector	1st F block corr adj to gym	Photoelectric	33369517
0503	Smoke Detector	1st F block corr adj to gym	Photoelectric	33369516
0504	Smoke Detector	1st F block corr adj to gym	Photoelectric	33369515
0515	Smoke Detector	1st F block corr to gym adj to gym office	Photoelectric	33369544
0523	Smoke Detector	1st F block vestibule f43	Photoelectric	33369542
0524	Smoke Detector	1st F block commons f42	Photoelectric	33369543
0525	Smoke Detector	1st F block commons f42	Photoelectric	33369540

0526	Smoke Detector	1st F block commons f42	Photoelectric	33369539
0528	Smoke Detector	1st E block corr to kitchen e05	Photoelectric	33369547
0529	Smoke Detector	1st E block corr to kitchen e05	Photoelectric	33369545
0530	Smoke Detector	1st E block corr to kitchen e05	Photoelectric	33369546
0533	Heat Detector	1st E block band/orchestra	Fixed Temperature	33369566
0534	Heat Detector	1st E block band/orchestra	Fixed Temperature	33369567
0535	Heat Detector	1st E block choral music e2	Fixed Temperature	33369564
0536	Heat Detector	1st E block choral music e2	Fixed Temperature	33369565
0537	Heat Detector	1st E block ensemble rm e24	Fixed Temperature	33369563
0538	Heat Detector	1st E block practice e23	Fixed Temperature	33369562
0539	Heat Detector	1st E block rm adj to practice e23	Fixed Temperature	33369561
0540	Heat Detector	1st E block vestibule	Fixed Temperature	33369560
0540	Heat Detector	1st E block vestibule	Fixed Temperature	33369505
0541	Smoke Detector	1st E block corr adj to receiving e20	Photoelectric	33369506
0542	Smoke Detector	1st E block corr adj to band/orchestra	Photoelectric	33369507
0543	Smoke Detector	1st E block corr adj to caf	Photoelectric	33369508
0544	Heat Detector	1st E block elec rm in receiving	Fixed Temperature	33369559
0550	Heat Detector	1st E block stage storage E04	Fixed Temperature	33369548
0567	Duct Detector	휘 휴 흠 흥 혼 ↑ □ ÚPhotoelectr	Photoelectric	33369570
0570	Duct Detector	1st E block practice rm e23	Photoelectric	33369568
0572	Smoke Detector	1st F block commons f42	Photoelectric	33369541
0601	Pull Station	F Block Corridor ADJ Gym	Dual Action	33369392
0602	Pull Station	Gym	Dual Action	44323076
0603	Pull Station	Gym	Dual Action	44323073
0604	Pull Station	Gym	Dual Action	44323077
0605	Pull Station	F Block Gym	Dual Action	44323080
0607	Pull Station	F Block Passage ABJ Gym Office	Dual Action	44323072
0608	Pull Station	F Block Common F42	Dual Action	46875869
0609	Pull Station	F Block Commons F42	Dual Action	44323071
0610	Pull Station	Cafeteria E 02	Dual Action	44323069
0612	Pull Station	Cafeteria E 2	Dual Action	44323068
0612	Pull Station	E Block Cafeteria E 2	Dual Action	44323070
0613	Pull Station	E Block Cafeteria E 02	Dual Action	44323067
0618	Pull Station	Boiler room e17 exit by FACP	Dual Action	33369390
0619	Pull Station	E Block Corr. ADJ recv/Cust E-20	Dual Action	44323064
0620	Pull Station	E Block Mech Room E17	Dual Action	33369391
0621	Waterflow Switch	Boiler rm e17		33369411
0622	Tamper Switch	Boiler room e17		33369410
0623	Pull Station	E Block Faculty Dining E16	Dual Action	46875870
0625	Pull Station	E block Band/ Orchestra E-1	Dual Action	33369409
0626	Pull Station	E Block Band/ Orchestra E2	Dual Action	44323065
0630	Pull Station	Gym F Block	Dual Action	44323075
0631	Pull Station	Gym F Block	Dual Action	44323074
0632	Pull Station	Gym F Block	Dual Action	44323078
0633	Pull Station	Gym F Block	Dual Action	44323079

**Zone/Circuit: 03**

0091	Duct Detector	1st Media Center D block work rm d38	Photoelectric	33369572
------	---------------	--------------------------------------	---------------	----------

**Zone/Circuit: 04**

0045	Heat Detector	1st E-Block Receiving/ Cust E-20	Rate-of-Rise	33369558
0051	Heat Detector	1st E block toilet e10	Rate-of-Rise	33369555
0052	Heat Detector	1st E-Block Storage BTWN Kit./Recv Rm	Rate-of-Rise	33369553
0053	Heat Detector	1st E-Block Kitchen Office E-08	Rate-of-Rise	33369554

0054	Heat Detector	1st E- Block Janitors Closet E-11	Rate-of-Rise	33369556
0058	Heat Detector	1st E-Block Faculty Dining E-16	Rate-of-Rise	33369557
0059	Heat Detector	1st E-Block Kitchen Dishwasher E-06	Rate-of-Rise	33369551
0060	Heat Detector	1st E block kitchen E05	Rate-of-Rise	33369550
0061	Heat Detector	1st E block kitchen E05	Rate-of-Rise	33369552
0062	Heat Detector	1st E block kitchen E05	Rate-of-Rise	33369549
0071	Duct Detector	1st E Block Rm E-1 Band Orchresta E block ensemble rm e24	Photoelectric	33369569



# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery Village Elem. School  
100 Main Blvd  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
Dec 20, 2018

Building: Montgomery Village Elem. School  
Contact: Dave Klein  
Title: B&G Mgr.

Company: Alarm & Communication Technologies  
Contact: Robert Kilcher  
Title: Inspector

# Executive Summary

Generated by: *BuildingReports.com*

Building Information		
<b>Building:</b> Montgomery Village Elem. School	<b>Contact:</b> Dave Klein	
<b>Address:</b> 100 Main Blvd	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Robert Kilcher	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 2018416983	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 2018416983	
<b>Country:</b> United States of America	<b>Email:</b> RobertK@njact.com	
System Control Unit		
<b>Manufacturer:</b> SimplexGrinnell	<b>Inspection Date:</b> 12/18/2018	<b>IDC Style:</b> B
<b>Model Number:</b> 4020	<b>Install Date:</b> 08/30/2016	<b>SLC Style:</b> 4
<b>Software Version:</b> 8.06	<b>Version Date:</b> 08/30/2016	<b>NAC Style:</b> Y
<b>Location:</b> Boiler room	<b>Current Protection:</b> Breaker	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b>	<b>Mfg:</b>	<b>Model #:</b>
<b>Test Time/Date:</b>	<b>Restore Time</b>	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	17	7.26%	17	100.00%	17	100.00%	0	0%
Initiating	214	91.45%	146	68.22%	146	100.00%	0	0%
Supervisory	3	1.28%	3	100.00%	3	100.00%	0	0%
<b>Totals</b>	<b>234</b>	<b>100%</b>	<b>166</b>	<b>70.94%</b>	<b>166</b>	<b>100.00%</b>	<b>0</b>	<b>0%</b>
Certification								
Company: Alarm & Communication Technologies				Building: Montgomery Village Elem. School				
Inspector: Robert Kilcher				Contact: Dave Klein				
Signed:				Signed:				

# *Notes & Recommendations*

Generated by: *BuildingReports.com*

## **Building: Montgomery Village Elem. School**

*The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.*

### ***General Note***

Both signal expander panels by FACP have "SIG4" trouble light flashing. There is no trouble on FACP.

Device M1-12 needs to have "above ceiling" removed from description.

Strongly recommend having smoke detector descriptions changed

# Inspection & Testing

Generated by: BuildingReports.com

Building: Montgomery Village Elem. School	Control Panel: 1 - SimplexGrinnell 4020
---	--

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Annunciator	In Main Lobby Entrance	Tested	1:45:57 PM	12/18/2018
Annunciator	In Main Office	Tested	1:46:02 PM	12/18/2018
Battery	In BPS Above Main FACP	Tested	2:11:18 PM	12/18/2018
Battery	In BPS Above Main FACP	Tested	2:11:22 PM	12/18/2018
Battery	In BPS Next to Main FACP	Tested	2:11:27 PM	12/18/2018
Battery	In BPS Next to Main FACP	Tested	2:11:36 PM	12/18/2018
Battery	In BPS In Room 003	Tested	2:11:08 PM	12/18/2018
Battery	In BPS In Room 003	Tested	2:11:12 PM	12/18/2018
Battery	In Main FACP	Tested	1:30:51 PM	08/15/2018
Battery	In Main FACP	Tested	1:30:53 PM	08/15/2018
Battery	In Main FACP	Tested	2:11:32 PM	12/18/2018
Battery	In Main FACP	Tested	2:11:40 PM	12/18/2018
Control Panel	Boiler room	Tested	2:10:58 PM	12/18/2018
Power Supply	In Fire Control Room Above Main FACP	Tested	2:10:03 PM	12/18/2018
Power Supply	In Room 003	Tested	2:09:58 PM	12/18/2018
Power Supply	In Room Fire Control Room Next to Main FACP	Tested	2:10:08 PM	12/18/2018
<b>Initiating</b>				
Duct Detector	AHU-9 A Wing	Tested	2:10:22 PM	12/18/2018
Duct Detector	Art room mechanical loft AHU 1 115	Tested	2:10:47 PM	12/18/2018
Duct Detector	B-Wing hall by 304 AHU 1	Tested	2:10:28 PM	12/18/2018
Duct Detector	B-Wing hall by 306 AHU 2	Tested	2:10:32 PM	12/18/2018
Duct Detector	D-Wing hall by 203 AHU 4	Tested	2:10:43 PM	12/18/2018
Duct Detector	D-Wing hall by 207 AHU 3	Tested	2:10:37 PM	12/18/2018
Heat Detector	Closet #1	Tested	7:18:51 AM	12/20/2018
Heat Detector	Electric Room 002	Tested	7:18:26 AM	12/20/2018
Heat Detector	Girls Toilet D-Wing	Tested	7:19:36 AM	12/20/2018
Heat Detector	Men's Faculty Toilet	Tested	7:18:42 AM	12/20/2018
Heat Detector	Men's Toilet D-Wing	Tested	7:19:27 AM	12/20/2018
Heat Detector	Room 106 Office 1	Tested	7:18:02 AM	12/20/2018
Heat Detector	Room 106 Office 2	Tested	7:17:58 AM	12/20/2018
Heat Detector	Room 106 Office 3	Tested	7:18:06 AM	12/20/2018
Heat Detector	Room 106	Tested	7:18:10 AM	12/20/2018
Heat Detector	Room 106	Tested	7:18:18 AM	12/20/2018
Heat Detector	Room 109 Bathroom	Tested	7:17:48 AM	12/20/2018
Heat Detector	Room 109	Tested	7:17:53 AM	12/20/2018
Heat Detector	Room 201	Tested	7:20:06 AM	12/20/2018
Heat Detector	Room 202	Tested	7:20:02 AM	12/20/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Heat Detector	Room 203	Tested	7:19:58 AM	12/20/2018
Heat Detector	Room 204	Tested	7:19:52 AM	12/20/2018
Heat Detector	Room 205	Tested	7:19:48 AM	12/20/2018
Heat Detector	Room 206	Tested	7:19:44 AM	12/20/2018
Heat Detector	Room 207	Tested	7:19:23 AM	12/20/2018
Heat Detector	Room 208	Tested	7:19:40 AM	12/20/2018
Heat Detector	Room 209	Tested	7:19:10 AM	12/20/2018
Heat Detector	Room 210	Tested	7:19:19 AM	12/20/2018
Heat Detector	Room 211	Tested	7:18:59 AM	12/20/2018
Heat Detector	Room 212	Tested	7:19:14 AM	12/20/2018
Heat Detector	Room 214	Tested	7:19:03 AM	12/20/2018
Heat Detector	Room 216	Tested	7:18:55 AM	12/20/2018
Heat Detector	Room 310	Tested	7:20:16 AM	12/20/2018
Heat Detector	Room 315	Tested	7:20:10 AM	12/20/2018
Heat Detector	Storage Room 10	Tested	7:18:35 AM	12/20/2018
Heat Detector	Storage Room 11	Tested	7:18:21 AM	12/20/2018
Heat Detector	Storage Room 12	Tested	7:19:31 AM	12/20/2018
Heat Detector	Tech Room 01	Tested	7:18:30 AM	12/20/2018
Heat Detector	Women's Fac Bath D-Wing	Tested	7:18:46 AM	12/20/2018
Pull Station	B/D Link Corridor	Tested	2:18:25 PM	08/15/2018
Pull Station	In Cafe Left Exit Door	Tested	2:09:10 PM	12/18/2018
Pull Station	In Cafe Right Exit Door	Tested	2:09:06 PM	12/18/2018
Pull Station	In Hallway By Room 1 Tech Closet	Tested	2:17:47 PM	08/15/2018
Pull Station	In Hallway By Room 104	Tested	1:12:20 PM	08/15/2018
Pull Station	In Hallway By Room 2 Custodial Closet	Tested	2:18:56 PM	08/15/2018
Pull Station	In Hallway By Room 216	Tested	2:08:44 PM	12/18/2018
Pull Station	In Hallway By Room 316	Tested	2:19:56 PM	08/15/2018
Pull Station	In Kitchen By Exit Door	Tested	2:09:00 PM	12/18/2018
Pull Station	In Library By Left Exit Door	Tested	2:08:55 PM	12/18/2018
Pull Station	In Library By Right Exit Door	Tested	2:08:51 PM	12/18/2018
Pull Station	In Main Office	Tested	2:08:34 PM	12/18/2018
Pull Station	In Room 115	Tested	2:08:39 PM	12/18/2018
Pull Station	On Stage Left	Tested	1:55:11 PM	12/18/2018
Pull Station	On Stage Right	Tested	1:55:07 PM	12/18/2018
Pull Station	Storage Rm 01	Tested	1:28:01 PM	08/15/2018
Pull Station	A wing commons Exit by cafe	Tested	2:09:43 PM	12/18/2018
Pull Station	A wing vestibule	Tested	2:21:44 PM	08/15/2018
Pull Station	Boiler room	Tested	1:07:26 PM	08/15/2018
Pull Station	C Wing Ramp Exit	Tested	2:16:29 PM	08/15/2018
Pull Station	East Corridor Vestibule	Tested	2:09:48 PM	12/18/2018
Pull Station	Gym exit to commons by nurse	Tested	2:09:29 PM	12/18/2018
Pull Station	Gym exit to commons by office	Tested	2:09:25 PM	12/18/2018
Pull Station	Gym exit to north corridor by band room	Tested	2:09:20 PM	12/18/2018
Pull Station	Gym exit to north corridor by mech room	Tested	2:09:15 PM	12/18/2018
Pull Station	Gym Office at Exit	Tested	2:09:34 PM	12/18/2018
Pull Station	Main entrance	Tested	1:10:11 PM	08/15/2018
Pull Station	Mech room by Boiler room	Tested	1:04:17 PM	08/15/2018
Pull Station	NE Corridor by storage room 01	Tested	2:09:52 PM	12/18/2018
Pull Station	North Corridor Exit	Tested	2:16:08 PM	08/15/2018
Pull Station	NW corridor Exit rear gym by stage	Tested	2:09:38 PM	12/18/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	West Entry by Nurse	Tested	1:11:12 PM	08/15/2018
Smoke Detector	B Wing Corridor By Room 316	Tested	1:50:23 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:18 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:27 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:31 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:35 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:41 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:45 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:49 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:54 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:50:58 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:51:04 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:51:08 PM	12/18/2018
Smoke Detector	B Wing Corridor	Tested	1:51:13 PM	12/18/2018
Smoke Detector	B Wing Skylight	Tested	1:49:08 PM	12/18/2018
Smoke Detector	B/D Link Corridor	Tested	1:50:08 PM	12/18/2018
Smoke Detector	B/D Link Corridor	Tested	1:50:13 PM	12/18/2018
Smoke Detector	D Wing Corridor By Skylight	Tested	1:49:04 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:12 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:18 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:22 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:27 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:31 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:36 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:41 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:45 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:50 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:49:56 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:50:00 PM	12/18/2018
Smoke Detector	D Wing Corridor	Tested	1:50:04 PM	12/18/2018
Smoke Detector	North Corridor	Tested	1:51:17 PM	12/18/2018
Smoke Detector	North Corridor	Tested	1:51:22 PM	12/18/2018
Smoke Detector	North Corridor	Tested	1:51:26 PM	12/18/2018
Smoke Detector	South Corridor	Tested	1:51:31 PM	12/18/2018
Smoke Detector	South Corridor	Tested	1:51:36 PM	12/18/2018
Smoke Detector	South Corridor	Tested	1:51:41 PM	12/18/2018
Smoke Detector	South Corridor	Tested	1:51:47 PM	12/18/2018
Smoke Detector	South Corridor	Tested	1:51:52 PM	12/18/2018
Smoke Detector	A-Wing Commons	Tested	1:52:57 PM	12/18/2018
Smoke Detector	A-Wing Commons	Tested	1:53:02 PM	12/18/2018
Smoke Detector	A-Wing Vestibule	Tested	1:52:53 PM	12/18/2018
Smoke Detector	A/C Link	Tested	1:53:13 PM	12/18/2018
Smoke Detector	A/C Link	Tested	1:54:57 PM	12/18/2018
Smoke Detector	A/C Wing Ramp	Tested	1:53:09 PM	12/18/2018
Smoke Detector	A/C Wing Ramp	Tested	1:54:53 PM	12/18/2018
Smoke Detector	C-Wing Commons	Tested	1:54:44 PM	12/18/2018
Smoke Detector	C-Wing Commons	Tested	1:54:49 PM	12/18/2018
Smoke Detector	C-Wing Ramp	Tested	1:54:29 PM	12/18/2018
Smoke Detector	C-Wing Ramp	Tested	1:54:34 PM	12/18/2018
Smoke Detector	C-Wing Ramp	Tested	1:54:38 PM	12/18/2018

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
Smoke Detector	Commons	Tested	1:52:10 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:14 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:19 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:23 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:28 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:33 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:39 PM	12/18/2018
Smoke Detector	Commons	Tested	1:52:44 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:53:38 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:53:42 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:53:46 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:53:51 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:54:00 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:54:07 PM	12/18/2018
Smoke Detector	East Corridor	Tested	1:54:11 PM	12/18/2018
Smoke Detector	East Vestibule	Tested	1:54:15 PM	12/18/2018
Smoke Detector	Front Vestibule	Tested	1:52:48 PM	12/18/2018
Smoke Detector	North Corridor	Tested	1:53:30 PM	12/18/2018
Smoke Detector	North Corridor	Tested	1:53:34 PM	12/18/2018
Smoke Detector	NorthEast Corridor	Tested	1:53:56 PM	12/18/2018
Smoke Detector	West Entry	Tested	1:52:00 PM	12/18/2018
Smoke Detector	West Entry	Tested	1:52:04 PM	12/18/2018
Smoke Detector	West Vestibule	Tested	1:51:56 PM	12/18/2018
Waterflow Switch	boiler room	Tested	1:48:37 PM	12/18/2018
Waterflow Switch	boiler room	Tested	1:48:41 PM	12/18/2018
Waterflow Switch	Mech room by boiler room	Tested	1:48:45 PM	12/18/2018
<b>Supervisory</b>				
Tamper Switch	boiler rm control valve	Tested	1:48:55 PM	12/18/2018
Tamper Switch	boiler room main control	Tested	1:48:51 PM	12/18/2018
Tamper Switch	Mech rm by boiler rm	Tested	1:48:59 PM	12/18/2018
Device Type	Location	Service	Time	Date
<b><i>Untested</i></b>				
<b>Initiating</b>				
Heat Detector	Boys Toilet B Wing			
Heat Detector	Central Office			
Heat Detector	Closet 003			
Heat Detector	Girls Toilet B			
Heat Detector	Room 101 Bathroom			
Heat Detector	Room 101			
Heat Detector	Room 101			
Heat Detector	Room 101			
Heat Detector	Room 103			
Heat Detector	Room 103			
Heat Detector	Room 103			
Heat Detector	Room 104 Bathroom			
Heat Detector	Room 104			
Heat Detector	Room 105 Bathroom			
Heat Detector	Room 105			



Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	Room 110 Bathroom			
Heat Detector	Room 110			
Heat Detector	Room 110			
Heat Detector	Room 110			
Heat Detector	Room 111 Bathroom			
Heat Detector	Room 111			
Heat Detector	Room 111			
Heat Detector	Room 111			
Heat Detector	Room 113 Bathroom			
Heat Detector	Room 113			
Heat Detector	Room 113			
Heat Detector	Room 113			
Heat Detector	Room 300			
Heat Detector	Room 301			
Heat Detector	Room 302			
Heat Detector	Room 303			
Heat Detector	Room 304			
Heat Detector	Room 305			
Heat Detector	Room 306			
Heat Detector	Room 307			
Heat Detector	Room 308			
Heat Detector	Room 309			
Heat Detector	Room 311			
Heat Detector	Room 313			
Heat Detector	Storage Room 13			
Heat Detector	Storage Room 15			
Heat Detector	A-Wing Office			
Heat Detector	Cafeteria			
Heat Detector	Cafeteria			
Heat Detector	Cafeteria			
Heat Detector	Closet 2			
Heat Detector	Computer Room			
Heat Detector	Computer Room			
Heat Detector	Computer Room closet			
Heat Detector	Computer Room work room			
Heat Detector	Faculty lav			
Heat Detector	Faculty work rm			
Heat Detector	Kitchen Food Storage			
Heat Detector	Kitchen Prep			
Heat Detector	Media Center			
Heat Detector	Media Center			
Heat Detector	Media Center			
Heat Detector	Media Center			
Heat Detector	Room 115			
Heat Detector	Room 115			
Heat Detector	Room 115			
Heat Detector	Room 115			
Heat Detector	Room 115 lav			
Heat Detector	Room 115 mezz			
Heat Detector	Room 115 storage rm 2			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	Room 200			
Heat Detector	Storage room 7			
Heat Detector	VP Office			

Building: Montgomery Village Elem. School

Control Panel: 2 - SimplexGrinnell  
4020

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Control Panel	Boiler room	Tested	2:10:53 PM	12/18/2018

# Service Summary

Generated by: *BuildingReports.com*

**Building: Montgomery Village Elem. School**

*The Service Summary section provides an overview of the services performed in this report.*

Device Type	Service	Quantity
<b><i>Passed</i></b>		
Annunciator	Tested	2
Battery	Tested	10
Control Panel	Tested	2
Duct Detector	Tested	6
Heat Detector	Tested	33
Power Supply	Tested	3
Pull Station	Tested	32
Smoke Detector	Tested	72
Tamper Switch	Tested	3
Waterflow Switch	Tested	3
<b>Total</b>		<b>166</b>
<b><i>Untested</i></b>		
Heat Detector		68
<b>Total</b>		<b>234</b>

# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery Village Elem. School		Control Panel: 1 - SimplexGrinnell 4020					
<p><i>The Control &amp; Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i></p>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<b><i>Passed</i></b>							
<b>Battery</b>							
Sealed Lead Acid	In BPS Above Main FACP	7	12				
Sealed Lead Acid	In BPS Above Main FACP	7	12				
	In BPS Next to Main FACP	7	12				
Sealed Lead Acid	In BPS Next to Main FACP	7	12				
Sealed Lead Acid	In BPS In Room 003	7	12				
Sealed Lead Acid	In BPS In Room 003	7	12				
Sealed Lead Acid	In Main FACP	18	12				
Sealed Lead Acid	In Main FACP	18	12				
Sealed Lead Acid	In Main FACP	18	12				
Sealed Lead Acid	In Main FACP	18	12				

# Inventory & Warranty Report

Generated by: BuildingReports.com

Building: Montgomery Village Elem. School		Control Panel: 1 - SimplexGrinnell 4020		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	43.16%	101	
Pull Station	Initiating	13.68%	32	
Battery	Control	4.27%	10	
Annunciator	Control	0.85%	2	
Waterflow Switch	Initiating	1.28%	3	
Tamper Switch	Supervisory	1.28%	3	
Smoke Detector	Initiating	30.77%	72	
Power Supply	Control	1.28%	3	
Duct Detector	Initiating	2.56%	6	
Control Panel	Control	0.85%	2	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>Honeywell</b>				
Power Supply	1	HPFF12		08/30/2016
<b>Notifier</b>				
Waterflow Switch	1	WFD-4		08/30/2016
<b>Potter Electric</b>				
Tamper Switch	1	OSYSU-2		08/30/2016
<b>SimplexGrinnell</b>				
Annunciator	2	4603-9101	LCD Display	08/30/2016
Control Panel	1	4020		08/30/2016
Duct Detector	6	4098-9714	Photoelectric	08/30/2016
Heat Detector	101	4098-9733	Combination	08/30/2016
Pull Station	2	2099-9761	Dual Action	08/30/2016
Pull Station	30	2099-9761	Single Action	08/30/2016
Smoke Detector	72	4098-9714	Photoelectric	08/30/2016
<b>System Sensor</b>				
Tamper Switch	2	OSY2		08/30/2016
Waterflow Switch	1	WFD20		08/30/2016
Waterflow Switch	1	WFD30		08/30/2016
<b><i>In Service - 3 Years to 5 Years</i></b>				
<b>Honeywell</b>				
Power Supply	2	HPFF12		10/29/2015
<b>Power-Sonic</b>				
Battery	2	PS-12180	Sealed Lead Acid	10/29/2015

**Ultra Tech**

Battery	2	UT12180	Sealed Lead Acid	10/29/2015
Battery	1	UT1270		08/31/2015
Battery	5	UT1270	Sealed Lead Acid	08/31/2015

Building: Montgomery Village Elem. School

Control Panel: 2 - SimplexGrinnell  
4020

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>SimplexGrinnell</b>				
Control Panel	1	4020		08/30/2016



# Zone Address Report

Generated by: BuildingReports.com

<b>Building: Montgomery Village Elem. School</b>	<b>Control Panel: 1 - SimplexGrinnell 4020</b>
--	--

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
m1-1	Heat Detector	Faculty work rm	Combination	33369493
M1-10	Heat Detector	Storage Room 10	Combination	46876336
m1-102	Duct Detector	D-Wing hall by 203 AHU 4	Photoelectric	33369468
m1-102	Heat Detector	Storage room 7	Combination	33369488
m1-103	Duct Detector	D-Wing hall by 207 AHU 3	Photoelectric	33369469
m1-103	Heat Detector	Media Center	Combination	33369487
M1-104	Smoke Detector	B Wing Corridor	Photoelectric	42626454
m1-105	Heat Detector	Media Center	Combination	33369499
M1-106	Smoke Detector	B Wing Corridor	Photoelectric	42626455
m1-107	Duct Detector	B-Wing hall by 306 AHU 2	Photoelectric	33369470
m1-107	Heat Detector	Media Center	Combination	33369485
m1-109	Heat Detector	Computer Room closet	Combination	33369484
M1-109	Smoke Detector	B Wing Corridor	Photoelectric	42626456
M1-110	Smoke Detector	B Wing Corridor	Photoelectric	42626457
M1-112	Smoke Detector	B Wing Corridor	Photoelectric	42626458
M1-114	Smoke Detector	B Wing Corridor By Room 316	Photoelectric	42626459
M1-12	Heat Detector	Room 106 Office 2	Combination	46876344
M1-12	Heat Detector	Women's Fac Bath D-Wing	Combination	46876334
m1-13	Pull Station	NE Corridor by storage room 01	Single Action	33369416
m1-14	Smoke Detector	NorthEast Corridor	Photoelectric	33369436
M1-14	Heat Detector	Closet #1	Combination	46876333
m1-15	Pull Station	In Hallway By Room 1 Tech Closet	Single Action	42626421
m1-16	Pull Station	Storage Rm 01	Dual Action	49668428
M1-17	Smoke Detector	D Wing Corridor	Photoelectric	42626469
M1-19	Heat Detector	Storage Room 11	Combination	46876338
M1-2	Heat Detector	Room 201	Combination	46875934
M1-21	Heat Detector	Men's Faculty Toilet	Combination	46876335
M1-23	Heat Detector	Tech Room 01	Combination	46876337
M1-25	Heat Detector	Men's Toilet D-Wing	Combination	46876325
M1-27	Heat Detector	Room 207	Combination	46876326
M1-28	Heat Detector	Room 110 Bathroom	Combination	42626492
M1-29	Heat Detector	Room 110	Combination	42626490
M1-29	Heat Detector	Room 209	Combination	46876329
M1-3		Room 106	Combination	46876340
M1-31	Heat Detector	Room 110	Combination	42626491
M1-31	Heat Detector	Room 211	Combination	46876331
m1-32	Pull Station	In Hallway By Room 216	Single Action	42626422
M1-32	Heat Detector	Room 110	Combination	42626489
m1-33	Smoke Detector	East Vestibule	Photoelectric	33369440
M1-34	Smoke Detector	D Wing Corridor	Photoelectric	42626468
M1-34	Heat Detector	Room 113	Combination	42626493

M1-35	Smoke Detector	D Wing Corridor	Photoelectric	42626467
M1-35	Heat Detector	Room 113	Combination	42626495
M1-36	Heat Detector	Room 113	Combination	42626494
M1-37	Smoke Detector	D Wing Corridor	Photoelectric	42626466
M1-38	Smoke Detector	D Wing Corridor	Photoelectric	42626465
M1-38	Heat Detector	Room 113 Bathroom	Combination	42626496
M1-4	Heat Detector	Room 203	Combination	46875936
M1-40	Smoke Detector	D Wing Corridor	Photoelectric	42626464
M1-40	Heat Detector	Room 111 Bathroom	Combination	42626500
M1-41	Smoke Detector	D Wing Corridor By Skylight	Photoelectric	46875913
M1-41	Heat Detector	Room 111	Combination	42626499
M1-43	Smoke Detector	D Wing Corridor	Photoelectric	42626470
M1-43	Heat Detector	Room 111	Combination	42626498
M1-44	Smoke Detector	D Wing Corridor	Photoelectric	42626471
M1-44	Heat Detector	Room 111	Combination	42626497
M1-46	Smoke Detector	D Wing Corridor	Photoelectric	42626472
M1-46	Heat Detector	Room 109	Combination	46876345
M1-47	Smoke Detector	D Wing Corridor	Photoelectric	42626473
M1-48	Heat Detector	Room 109 Bathroom	Combination	46876346
M1-49	Smoke Detector	D Wing Corridor	Photoelectric	42626474
M1-5	Heat Detector	Room 106 Office 1	Combination	46876343
M1-51	Heat Detector	Room 202	Combination	46875935
M1-53	Heat Detector	Room 204	Combination	46875937
M1-55	Heat Detector	Room 206	Combination	46876321
M1-57	Heat Detector	Room 208	Combination	46876322
M1-59	Heat Detector	Storage Room 12	Combination	46876324
M1-6	Heat Detector	Room 205	Combination	46875938
M1-61	Smoke Detector	D Wing Corridor	Photoelectric	42626463
m1-61	Pull Station	In Main Office	Single Action	42626424
M1-62	Heat Detector	Central Office	Combination	46875914
M1-63	Heat Detector	Room 210	Combination	46876327
M1-65	Heat Detector	Electric Room 002	Combination	46876339
M1-67	Heat Detector	Room 212	Combination	46876328
M1-69	Heat Detector	Room 214	Combination	46876330
M1-7	Heat Detector	Room 106	Combination	46876341
M1-71	Heat Detector	Room 216	Combination	46876332
m1-72	Smoke Detector	East Corridor	Photoelectric	33369432
M1-72	Smoke Detector	B/D Link Corridor	Photoelectric	42626462
m1-73	Smoke Detector	East Corridor	Photoelectric	33369433
M1-74	Smoke Detector	B/D Link Corridor	Photoelectric	42626461
m1-75	Pull Station	B/D Link Corridor	Single Action	42626420
m1-76	Smoke Detector	East Corridor	Photoelectric	33369434
M1-77	Smoke Detector	B Wing Corridor	Photoelectric	42626460
m1-78	Smoke Detector	East Corridor	Photoelectric	33369435
m1-79	Smoke Detector	East Corridor	Photoelectric	33369437
M1-8	Heat Detector	Girls Toilet D-Wing	Combination	46876323
m1-81	Smoke Detector	East Corridor	Photoelectric	33369438
m1-82	Smoke Detector	East Corridor	Photoelectric	33369439
M1-83	Heat Detector	Room 311	Combination	46875928
m1-84	Pull Station	East Corridor Vestibule	Single Action	33369417
M1-85	Heat Detector	Room 313	Combination	46875930
m1-87	Heat Detector	Room 200	Combination	33369480
M1-87	Heat Detector	Room 315	Combination	46875933

M1-89	Heat Detector	Room 310	Combination	46875932
M1-9	Heat Detector	Room 106 Office 3	Combination	46876342
m1-91	Heat Detector	Computer Room	Combination	33369482
M1-91	Heat Detector	Room 308	Combination	46875931
m1-93	Heat Detector	Computer Room	Combination	33369481
m1-93	Heat Detector	Media Center	Combination	33369486
M1-93	Heat Detector	Room 306	Combination	46875929
M1-95	Heat Detector	Boys Toilet B Wing	Combination	46875927
M2-101	Heat Detector	Storage Room 13	Combination	46875923
M2-105	Heat Detector	Closet 003	Combination	46875925
M2-108	Smoke Detector	B Wing Corridor	Photoelectric	42626453
M2-109	Smoke Detector	B Wing Skylight	Photoelectric	46875912
m2-12	Smoke Detector	C-Wing Commons	Photoelectric	33369444
m2-12	Heat Detector	Room 115	Combination	33369476
m2-13	Smoke Detector	C-Wing Commons	Photoelectric	33369445
m2-14	Smoke Detector	A/C Wing Ramp	Photoelectric	33369446
m2-14	Heat Detector	Room 115	Combination	33369477
m2-18	Smoke Detector	A/C Link	Photoelectric	33369447
m2-18	Heat Detector	Room 115 mezz	Combination	33369479
m2-19	Smoke Detector	A/C Link	Photoelectric	33369448
m2-2	Pull Station	C Wing Ramp Exit	Single Action	33369419
m2-21	Smoke Detector	A/C Wing Ramp	Photoelectric	33369449
m2-21	Duct Detector	Art room mechanical loft AHU 1 115	Photoelectric	33369467
m2-22	Pull Station	A wing commons Exit by cafe	Single Action	33369420
m2-22	Pull Station	North Corridor Exit	Single Action	33369418
m2-23	Smoke Detector	North Corridor	Photoelectric	33369412
m2-23	Duct Detector	AHU-9 A Wing	Photoelectric	46875939
m2-25	Smoke Detector	A-Wing Commons	Photoelectric	33369451
m2-25	Pull Station	On Stage Right	Single Action	42626429
m2-26	Pull Station	Gym exit to north corridor by mech room	Single Action	33369429
m2-26	Pull Station	In Cafe Left Exit Door	Single Action	42626413
m2-26	Pull Station	In Hallway By Room 104	Single Action	42626427
m2-26	Pull Station	In Hallway By Room 2 Custodial Closet	Single Action	42626418
m2-26	Pull Station	In Hallway By Room 316	Single Action	42626419
m2-26	Pull Station	In Library By Left Exit Door	Single Action	42626416
m2-26	Pull Station	In Library By Right Exit Door	Single Action	42626417
m2-26	Pull Station	In Room 115	Dual Action	42626423
m2-27	Smoke Detector	A-Wing Vestibule	Photoelectric	33369452
m2-27	Smoke Detector	North Corridor	Photoelectric	42626447
m2-28	Pull Station	A wing vestibule	Single Action	33369421
m2-28	Heat Detector	Room 115 storage rm 2	Combination	33369474
m2-3	Pull Station	Mech room by Boiler room	Single Action	33369415
m2-30	Heat Detector	VP Office	Combination	33369490
m2-32	Heat Detector	A-Wing Office	Combination	33369489
m2-33	Smoke Detector	A-Wing Commons	Photoelectric	33369450
m2-33	Smoke Detector	North Corridor	Photoelectric	33369430
M2-33	Smoke Detector	North Corridor	Photoelectric	42626446
m2-34	Heat Detector	Room 115	Combination	33369472
m2-36	Heat Detector	Faculty lav	Combination	33369498
m2-38	Heat Detector	Room 115 lav	Combination	33369478
m2-39	Heat Detector	Cafeteria	Combination	33369491
m2-4	Smoke Detector	C-Wing Ramp	Photoelectric	33369441

M2-40	Smoke Detector	North Corridor	Photoelectric	42626445
m2-42	Pull Station	Gym exit to north corridor by band room	Single Action	33369428
m2-45	Pull Station	On Stage Left	Single Action	42626428
m2-47	Pull Station	In Cafe Right Exit Door	Single Action	42626414
m2-49	Heat Detector	Cafeteria	Combination	33369497
m2-5	Pull Station	Boiler room	Single Action	33369414
m2-5	Smoke Detector	C-Wing Ramp	Photoelectric	33369442
m2-51	Heat Detector	Cafeteria	Combination	33369492
m2-51	Pull Station	NW corridor Exit rear gym by stage	Single Action	33369424
m2-54	Heat Detector	Kitchen Food Storage	Combination	33369496
m2-56	Heat Detector	Closet 2	Combination	33369495
m2-6	Waterflow Switch	boiler room		33369504
m2-6	Waterflow Switch	boiler room		33369501
m2-6	Smoke Detector	C-Wing Ramp	Photoelectric	33369443
m2-62	Pull Station	Gym Office at Exit	Single Action	33369425
m2-62	Pull Station	In Kitchen By Exit Door	Single Action	42626415
m2-7	Tamper Switch	boiler rm control valve		33369502
m2-7	Tamper Switch	boiler room main control		33369503
m2-72	Heat Detector	Kitchen Prep	Combination	33369494
M2-74	Heat Detector	Room 301	Combination	46875915
M2-76	Heat Detector	Room 303	Combination	46875918
M2-78	Heat Detector	Room 305	Combination	46875920
M2-79	Heat Detector	Room 309	Combination	46875926
m2-8	Heat Detector	Computer Room work room	Combination	33369483
M2-80	Heat Detector	Room 307	Combination	46875921
M2-82	Heat Detector	Storage Room 15	Combination	46875924
M2-84	Smoke Detector	B Wing Corridor	Photoelectric	42626452
M2-85	Smoke Detector	B Wing Corridor	Photoelectric	42626451
m2-86	Duct Detector	B-Wing hall by 304 AHU 1	Photoelectric	33369471
m2-87	Pull Station	Gym exit to commons by office	Single Action	33369427
M2-88	Smoke Detector	B Wing Corridor	Photoelectric	42626450
M2-89	Smoke Detector	B Wing Corridor	Photoelectric	42626449
m2-9	Heat Detector	Room 115	Combination	33369475
M2-91	Smoke Detector	B Wing Corridor	Photoelectric	42626448
M2-93	Heat Detector	Room 300	Combination	46875916
M2-95	Heat Detector	Room 302	Combination	46875917
m2-96	Waterflow Switch	Mech room by boiler room		33369473
m2-97	Tamper Switch	Mech rm by boiler rm		33369500
M2-97	Heat Detector	Room 304	Combination	46875919
M2-99	Heat Detector	Girls Toilet B	Combination	46875922
m3-1	Smoke Detector	Commons	Photoelectric	33369459
m3-10	Smoke Detector	Commons	Photoelectric	33369454
m3-13	Pull Station	Main entrance	Single Action	33369422
m3-24	Smoke Detector	Front Vestibule	Photoelectric	33369453
m3-25	Smoke Detector	South Corridor	Photoelectric	42626443
m3-3	Smoke Detector	Commons	Photoelectric	33369460
m3-33	Smoke Detector	West Vestibule	Photoelectric	33369464
m3-34	Pull Station	West Entry by Nurse	Single Action	33369423
m3-35	Smoke Detector	West Entry	Photoelectric	33369463
m3-36	Pull Station	Gym exit to commons by nurse	Single Action	33369426
m3-39	Smoke Detector	West Entry	Photoelectric	33369462
M3-41	Heat Detector	Room 101 Bathroom	Combination	42626487
M3-43	Heat Detector	Room 101	Combination	42626485

M3-44	Heat Detector	Room 101	Combination	42626488
M3-45	Heat Detector	Room 101	Combination	42626486
m3-5	Smoke Detector	Commons	Photoelectric	33369461
m3-55	Smoke Detector	South Corridor	Photoelectric	42626442
M3-56	Heat Detector	Room 103	Combination	42626482
M3-57	Heat Detector	Room 103	Combination	42626483
m3-6	Smoke Detector	Commons	Photoelectric	33369458
M3-61	Heat Detector	Room 103	Combination	42626484
m3-63	Smoke Detector	South Corridor	Photoelectric	42626444
m3-7	Smoke Detector	Commons	Photoelectric	33369457
m3-72	Smoke Detector	South Corridor	Photoelectric	42626441
M3-74	Heat Detector	Room 104 Bathroom	Combination	42626480
M3-75	Heat Detector	Room 104	Combination	42626479
M3-77	Heat Detector	Room 105	Combination	42626478
M3-79	Heat Detector	Room 105 Bathroom	Combination	42626481
m3-8	Smoke Detector	Commons	Photoelectric	33369456
m3-82	Smoke Detector	South Corridor	Photoelectric	42626440
m3-87	Smoke Detector	Commons	Photoelectric	33369455

# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery Orchard Hill School  
244 Orchard Rd  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
Dec 27, 2018

Building: Montgomery Orchard Hill School  
Contact: Dave Klein  
Title: B&G Mgr.

Company: Alarm & Communication Technologies  
Contact: Robert Kilcher  
Title: Inspector

# Executive Summary

Generated by: BuildingReports.com

Building Information		
<b>Building:</b> Montgomery Orchard Hill School	<b>Contact:</b> Dave Klein	
<b>Address:</b> 244 Orchard Rd	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Robert Kilcher	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 2018416983	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 2018416983	
<b>Country:</b> United States of America	<b>Email:</b> RobertK@njact.com	
System Control Unit		
<b>Manufacturer:</b> EST	<b>Inspection Date:</b> 10/03/2018	<b>IDC Style:</b> B
<b>Model Number:</b> est3	<b>Install Date:</b> 09/02/2016	<b>SLC Style:</b> 4
<b>Software Version:</b>	<b>Version Date:</b> 09/02/2016	<b>NAC Style:</b> Y
<b>Location:</b> 1st Storage 51	<b>Current Protection:</b>	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b>	<b>Mfg:</b>	<b>Model #:</b>
<b>Test Time/Date:</b>	<b>Restore Time</b>	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	26	4.35%	26	100.00%	24	92.31%	2	7.69%
Initiating	567	94.82%	510	89.95%	510	100.00%	0	0%
Supervisory	5	0.84%	5	100.00%	5	100.00%	0	0%
<b>Totals</b>	<b>598</b>	<b>100%</b>	<b>541</b>	<b>90.47%</b>	<b>539</b>	<b>99.63%</b>	<b>2</b>	<b>0.37%</b>
Certification								
Company: Alarm & Communication Technologies				Building: Montgomery Orchard Hill School				
Inspector: Robert Kilcher				Contact: Dave Klein				
Signed:				Signed:				



# Discrepancy Report

Generated by: BuildingReports.com

<b>Building: Montgomery Orchard Hill School</b>		<b>Control Panel: 1</b>		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<b><i>Items listed for Recall by Manufacturer</i></b>				
No recalled items found during this inspection.				
ScanID	Location	Problem	Address	Reference
<b><i>Control</i></b>				
<b>Battery</b>				
42626395	1st In BPS In Room 81	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
42626394	1st In BPS In Room 81	Date Expired	1	NFPA72 Table 14.4.3.2 (9a)(1)
<b><i>Code References</i></b>				
NFPA72 Table 14.4.3.2 (9a)(1)	Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations			

# *Proposed Solutions Report*

*Generated by: BuildingReports.com*

Building: Montgomery Orchard Hill School					Control Panel: 1
<p><i>The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.</i></p>					
ScanID	Location	Solution	Model #	Cost	Fix
<b><i>Control</i></b>					
<b>Battery</b>					
42626395	1st In BPS In Room 81	Replace	UT1270	T/M	<input type="checkbox"/>
42626394	1st In BPS In Room 81	Replace	UT1270	T/M	<input type="checkbox"/>
<b>PO #:</b> (none)				<b>T/M</b>	

# Notes & Recommendations

Generated by: *BuildingReports.com*

## Building: Montgomery Orchard Hill School

*The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.*

### **General Note**

Smoke detector 01-02-0020 & 01-02-0019 need description changes they are room 102 not 101

Smoke detector 01-02-0060 & 01-02-0061 need description changes they are room 109 not 110

Room 13 has exit that needs pull (278)

Men's bathroom 30 and women's 29 have been renovated and smokes are above ceiling recommend removal

Following Rooms Have no pull stations by doors that indicate it's a fire door: Rm 110, Rm 111, Rm 112, Rm 113, Rm 114, Rm 115, Rm 116, Rm 117, Rm 118, Rm 119, Rm 120, Rm 121, Rm 122

## Building: Montgomery Orchard Hill School      Control Panel: 1

ScanID	Note	Device Type	Location	Comment
<b>Initiating</b>				
3993869920	2	Smoke Detector	Men's Room 30 Right	Passed
Misabeled after renovation only smoke in room				
3993875662	3	Smoke Detector	Women's Room 29 Left Front	Passed
Misabeled after renovation only smoke in room				

*The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.*

ScanID	Note	Device Type	Location	Comment
<b><i>Initiating</i></b>				
42626376	4	Duct Detector	1st AHU B2 RET. Faculty Room	Passed
Test switch led did not indicate alarm when device was action				

# Inspection & Testing

Generated by: BuildingReports.com

<b>Building: Montgomery Orchard Hill School</b>	<b>Control Panel: 1</b>
---	-------------------------

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Annunciator	1st In Main Entrance Vestibule	Tested	9:44:51 AM	10/03/2018
Annunciator	1st In Main Office	Tested	9:44:07 AM	10/03/2018
Battery	1st In BPS In Room 16	Tested	2:55:25 PM	10/03/2018
Battery	1st In BPS In Room 16	Tested	2:55:29 PM	10/03/2018
Battery	1st In BPS In Room 74 Above Door	Tested	2:51:49 PM	10/03/2018
Battery	1st In BPS In Room 74 Above Door	Tested	2:52:04 PM	10/03/2018
Battery	1st In Storage Room 6	Tested	1:39:52 PM	10/03/2018
Battery	1st In Storage Room 6	Tested	1:40:06 PM	10/03/2018
Battery	1st In Storage Room 6	Tested	1:40:33 PM	10/03/2018
Battery	1st In Storage Room 6	Tested	1:40:39 PM	10/03/2018
Battery	Head custodian office 51	Tested	8:38:51 AM	10/03/2018
Battery	Head custodian office 51	Tested	8:39:06 AM	10/03/2018
Battery	Storage 6	Tested	1:36:13 PM	10/03/2018
Battery	Storage 6	Tested	1:37:21 PM	10/03/2018
Battery	Storage 81	Tested	2:59:57 PM	10/03/2018
Battery	Storage 81	Tested	3:00:34 PM	10/03/2018
Expander Panel	1st In Room 81	Tested	2:57:39 PM	10/03/2018
Expander Panel	1st In Storage Room 6	Tested	1:38:14 PM	10/03/2018
Power Supply	1st In Room 16	Tested	2:55:32 PM	10/03/2018
Power Supply	1st In Room 74 Above Door	Tested	2:51:41 PM	10/03/2018
Power Supply	1st In Room 81	Tested	2:57:57 PM	10/03/2018
Power Supply	Storage 6	Tested	1:39:30 PM	10/03/2018
Power Supply	Storage 6	Tested	1:40:29 PM	10/03/2018
<b>Initiating</b>				
Beam Detector	1st M.P.R. 3 Front	Tested	1:31:16 PM	10/03/2018
Beam Detector	1st M.P.R. 3 Rear	Tested	1:31:18 PM	10/03/2018
Duct Detector	1st AHU 1 Upper M.P.R.	Tested	2:59:33 PM	10/03/2018
Duct Detector	1st AHU A-3 Hall Upper M.P.R.	Tested	11:46:16 AM	10/03/2018
Duct Detector	1st AHU-A4 Art Storage Room 12	Tested	11:46:19 AM	10/03/2018
Heat Detector	A/C Rm 135	Tested	1:55:46 PM	12/27/2018
Heat Detector	A/C Rm 17	Tested	1:58:18 PM	12/27/2018
Heat Detector	A/C sprinkler rm 11	Tested	1:54:11 PM	12/27/2018
Heat Detector	A/C storage rm 12	Tested	1:52:32 PM	12/27/2018
Pull Station	1st In Gym On Caring Street	Tested	10:11:44 AM	10/03/2018
Pull Station	1st In Gym On Caring Street Left Side	Tested	10:12:53 AM	10/03/2018
Pull Station	1st In Gym On Caring Street Left Side	Tested	10:13:26 AM	10/03/2018
Pull Station	1st In Hallway Next to Exit Door By Gym on Caring Street	Tested	10:15:52 AM	10/03/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st In Hallway Next to Exit Door By Room 101	Tested	10:16:47 AM	10/03/2018
Pull Station	1st In Hallway Next to Exit Door By Room 122/ Handicap Lift	Tested	10:03:40 AM	10/03/2018
Pull Station	1st In In Boiler Room 2	Tested	10:18:23 AM	10/03/2018
Pull Station	1st In Lobby By Sprinkler Room 6	Tested	10:15:00 AM	10/03/2018
Pull Station	1st In M.P.R. Storage Room Exit	Tested	10:30:01 AM	10/03/2018
Pull Station	1st In Room 109	Tested	10:07:27 AM	10/03/2018
Pull Station	1st In Storage Room 6	Tested	10:28:33 AM	10/03/2018
Smoke Detector	1st M.P.R. 3 Office	Tested	11:09:39 AM	12/27/2018
Smoke Detector	1st M.P.R. 3 Storage	Tested	11:09:17 AM	12/27/2018
Smoke Detector	1st Rm 7 Office	Tested	10:48:03 AM	12/27/2018
Smoke Detector	1st Room 109 Storage	Tested	11:17:43 AM	12/27/2018
Smoke Detector	1st Room 26 Staff Bathroom	Tested	10:46:28 AM	12/27/2018
Smoke Detector	1st Room 6 Center	Tested	11:16:47 AM	12/27/2018
Smoke Detector	1st Room 6 Front	Tested	11:17:13 AM	12/27/2018
Smoke Detector	1st Room 6 Rear	Tested	11:17:26 AM	12/27/2018
Smoke Detector	1st Room 7B Work Room	Tested	10:47:44 AM	12/27/2018
Smoke Detector	1st Room 8 Vice Principal	Tested	10:47:26 AM	12/27/2018
Smoke Detector	1st Room 9 Conference Room	Tested	10:45:51 AM	12/27/2018
Smoke Detector	Boy's Lav Right By Rm 129	Tested	10:04:28 AM	12/27/2018
Smoke Detector	Boy's Lav. Left By Rm 129	Tested	10:04:17 AM	12/27/2018
Smoke Detector	Boys Bathroom 27	Tested	10:46:50 AM	12/27/2018
Smoke Detector	Custodians Closet 16 CTR Left	Tested	10:03:23 AM	12/27/2018
Smoke Detector	Custodians Closet 16 CTR Right	Tested	10:02:55 AM	12/27/2018
Smoke Detector	Custodians Closet 16 Left	Tested	10:03:38 AM	12/27/2018
Smoke Detector	Custodians Closet 16 Right	Tested	10:03:07 AM	12/27/2018
Smoke Detector	Custodians Rm 1	Tested	11:17:08 AM	12/27/2018
Smoke Detector	Girl's Lav. Left By Rm 126	Tested	10:00:59 AM	12/27/2018
Smoke Detector	Girl's Lav. Right By Rm 126	Tested	10:01:07 AM	12/27/2018
Smoke Detector	Girls Bathroom 28	Tested	10:45:15 AM	12/27/2018
Smoke Detector	Hall By Rm 120	Tested	2:34:38 PM	10/03/2018
Smoke Detector	Lower Handicap Lift Area	Tested	2:33:24 PM	10/03/2018
Smoke Detector	Men's Room 30 Left	Tested	11:15:19 AM	12/27/2018
Smoke Detector	Men's Room 30 Right	Tested	9:52:42 AM	12/27/2018
Smoke Detector	Rm 10 Custodian Closet	Tested	11:18:06 AM	12/27/2018
Smoke Detector	Room 101 Alcove Left	Tested	11:07:18 AM	12/27/2018
Smoke Detector	Room 101 Bathroom	Tested	11:07:39 AM	12/27/2018
Smoke Detector	Room 101 Closet Right	Tested	11:06:32 AM	12/27/2018
Smoke Detector	Room 101 Entrance	Tested	11:06:01 AM	12/27/2018
Smoke Detector	Room 101	Tested	11:06:52 AM	12/27/2018
Smoke Detector	Room 102 Alcove Left	Tested	11:04:45 AM	12/27/2018
Smoke Detector	Room 102 Bathroom	Tested	11:05:10 AM	12/27/2018
Smoke Detector	Room 102 Closet Left	Tested	11:05:42 AM	12/27/2018
Smoke Detector	Room 102 Entrance	Tested	11:04:00 AM	12/27/2018
Smoke Detector	Room 102	Tested	11:04:32 AM	12/27/2018
Smoke Detector	Room 103 Bathroom	Tested	11:03:22 AM	12/27/2018
Smoke Detector	Room 103 Center Left	Tested	11:01:53 AM	12/27/2018
Smoke Detector	Room 103 Center Right	Tested	11:01:35 AM	12/27/2018
Smoke Detector	Room 103 Closet	Tested	11:02:44 AM	12/27/2018
Smoke Detector	Room 103 Left	Tested	11:02:15 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 103 Right	Tested	11:01:23 AM	12/27/2018
Smoke Detector	Room 104 Bathroom	Tested	11:00:45 AM	12/27/2018
Smoke Detector	Room 104 Center Left	Tested	11:00:05 AM	12/27/2018
Smoke Detector	Room 104 Center Right	Tested	10:59:47 AM	12/27/2018
Smoke Detector	Room 104 Left	Tested	11:00:25 AM	12/27/2018
Smoke Detector	Room 104 Right	Tested	10:59:38 AM	12/27/2018
Smoke Detector	Room 105 Bathroom	Tested	10:58:59 AM	12/27/2018
Smoke Detector	Room 105 Center Left	Tested	10:57:54 AM	12/27/2018
Smoke Detector	Room 105 Center Right	Tested	10:57:37 AM	12/27/2018
Smoke Detector	Room 105 Left	Tested	10:58:11 AM	12/27/2018
Smoke Detector	Room 105 Right	Tested	10:57:23 AM	12/27/2018
Smoke Detector	Room 105 Storage	Tested	10:58:34 AM	12/27/2018
Smoke Detector	Room 106 Bathroom	Tested	10:56:48 AM	12/27/2018
Smoke Detector	Room 106 Center Left	Tested	10:56:15 AM	12/27/2018
Smoke Detector	Room 106 Center Right	Tested	10:56:06 AM	12/27/2018
Smoke Detector	Room 106 Left	Tested	10:56:26 AM	12/27/2018
Smoke Detector	Room 106 Right	Tested	10:55:58 AM	12/27/2018
Smoke Detector	Room 107 Bathroom	Tested	10:54:46 AM	12/27/2018
Smoke Detector	Room 107 Center Left	Tested	10:53:27 AM	12/27/2018
Smoke Detector	Room 107 Center Right	Tested	10:53:10 AM	12/27/2018
Smoke Detector	Room 107 Left	Tested	10:53:46 AM	12/27/2018
Smoke Detector	Room 107 Right	Tested	10:52:58 AM	12/27/2018
Smoke Detector	Room 107 Storage Rm	Tested	10:54:11 AM	12/27/2018
Smoke Detector	Room 108 Bathroom	Tested	10:51:35 AM	12/27/2018
Smoke Detector	Room 108 Center Left	Tested	10:50:52 AM	12/27/2018
Smoke Detector	Room 108 Center Right	Tested	10:50:37 AM	12/27/2018
Smoke Detector	Room 108 Left	Tested	10:51:11 AM	12/27/2018
Smoke Detector	Room 108 Right	Tested	10:50:27 AM	12/27/2018
Smoke Detector	Room 109 Center	Tested	10:42:21 AM	12/27/2018
Smoke Detector	Room 109 Front	Tested	10:41:35 AM	12/27/2018
Smoke Detector	Room 109 HNDCP Bathroom	Tested	10:43:49 AM	12/27/2018
Smoke Detector	Room 109 Mid. Front	Tested	10:41:58 AM	12/27/2018
Smoke Detector	Room 109 Mid. Rear	Tested	10:42:40 AM	12/27/2018
Smoke Detector	Room 109 Rear	Tested	10:42:54 AM	12/27/2018
Smoke Detector	Room 110 Center	Tested	10:40:38 AM	12/27/2018
Smoke Detector	Room 110 Front	Tested	10:40:19 AM	12/27/2018
Smoke Detector	Room 110 Left Bathroom	Tested	10:44:13 AM	12/27/2018
Smoke Detector	Room 110 Rear	Tested	10:40:52 AM	12/27/2018
Smoke Detector	Room 110 Right Bathroom	Tested	10:44:35 AM	12/27/2018
Smoke Detector	Room 111 Center	Tested	10:38:06 AM	12/27/2018
Smoke Detector	Room 111 Front	Tested	10:37:44 AM	12/27/2018
Smoke Detector	Room 111 Rear	Tested	10:38:24 AM	12/27/2018
Smoke Detector	Room 112 Center	Tested	10:36:50 AM	12/27/2018
Smoke Detector	Room 112 Front	Tested	10:36:32 AM	12/27/2018
Smoke Detector	Room 112 Rear	Tested	10:37:06 AM	12/27/2018
Smoke Detector	Room 113 Center	Tested	10:34:48 AM	12/27/2018
Smoke Detector	Room 113 Front	Tested	10:34:32 AM	12/27/2018
Smoke Detector	Room 113 Rear	Tested	10:35:12 AM	12/27/2018
Smoke Detector	Room 114 Center	Tested	10:33:40 AM	12/27/2018
Smoke Detector	Room 114 Front	Tested	10:33:25 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 114 Rear	Tested	10:33:55 AM	12/27/2018
Smoke Detector	Room 115 Center	Tested	10:32:13 AM	12/27/2018
Smoke Detector	Room 115 Front	Tested	10:31:58 AM	12/27/2018
Smoke Detector	Room 115 Rear	Tested	10:32:33 AM	12/27/2018
Smoke Detector	Room 116 Center	Tested	10:31:04 AM	12/27/2018
Smoke Detector	Room 116 Front	Tested	10:30:44 AM	12/27/2018
Smoke Detector	Room 116 Rear	Tested	10:31:18 AM	12/27/2018
Smoke Detector	Room 117 Center	Tested	10:29:33 AM	12/27/2018
Smoke Detector	Room 117 Front	Tested	10:27:56 AM	12/27/2018
Smoke Detector	Room 117 Rear	Tested	10:29:58 AM	12/27/2018
Smoke Detector	Room 118 Center	Tested	10:26:48 AM	12/27/2018
Smoke Detector	Room 118 Front	Tested	10:26:11 AM	12/27/2018
Smoke Detector	Room 118 Rear	Tested	10:27:07 AM	12/27/2018
Smoke Detector	Room 119 Center	Tested	10:23:29 AM	12/27/2018
Smoke Detector	Room 119 Front	Tested	10:23:14 AM	12/27/2018
Smoke Detector	Room 119 Rear	Tested	10:25:18 AM	12/27/2018
Smoke Detector	Room 120 Center	Tested	10:22:17 AM	12/27/2018
Smoke Detector	Room 120 Front	Tested	10:22:07 AM	12/27/2018
Smoke Detector	Room 120 Rear	Tested	10:22:31 AM	12/27/2018
Smoke Detector	Room 121 Center	Tested	10:21:02 AM	12/27/2018
Smoke Detector	Room 121 Front	Tested	10:20:50 AM	12/27/2018
Smoke Detector	Room 121 Rear	Tested	10:21:20 AM	12/27/2018
Smoke Detector	Room 122 Center	Tested	10:19:52 AM	12/27/2018
Smoke Detector	Room 122 Front	Tested	10:19:40 AM	12/27/2018
Smoke Detector	Room 122 Rear	Tested	10:20:10 AM	12/27/2018
Smoke Detector	Room 123 Center Left	Tested	11:16:38 AM	12/27/2018
Smoke Detector	Room 123 Center Right	Tested	11:17:18 AM	12/27/2018
Smoke Detector	Room 123 Left	Tested	11:15:35 AM	12/27/2018
Smoke Detector	Room 123 Right	Tested	11:15:09 AM	12/27/2018
Smoke Detector	Room 126 Center Left	Tested	9:59:44 AM	12/27/2018
Smoke Detector	Room 126 Center Right	Tested	9:59:59 AM	12/27/2018
Smoke Detector	Room 126 Left	Tested	9:59:34 AM	12/27/2018
Smoke Detector	Room 126 Right	Tested	10:00:12 AM	12/27/2018
Smoke Detector	Room 129 Center Left	Tested	10:06:21 AM	12/27/2018
Smoke Detector	Room 129 Center Right	Tested	10:06:44 AM	12/27/2018
Smoke Detector	Room 129 Left	Tested	10:06:12 AM	12/27/2018
Smoke Detector	Room 129 Right	Tested	10:06:58 AM	12/27/2018
Smoke Detector	Room 13 Center Left	Tested	9:54:17 AM	12/27/2018
Smoke Detector	Room 13 Center Right	Tested	9:54:03 AM	12/27/2018
Smoke Detector	Room 13 Far Left	Tested	11:17:57 AM	12/27/2018
Smoke Detector	Room 13 Far Right	Tested	9:53:05 AM	12/27/2018
Smoke Detector	Room 13 Left	Tested	9:54:30 AM	12/27/2018
Smoke Detector	Room 13 Right	Tested	9:53:48 AM	12/27/2018
Smoke Detector	Room 131 Center Left	Tested	10:09:10 AM	12/27/2018
Smoke Detector	Room 131 Center Right	Tested	10:09:35 AM	12/27/2018
Smoke Detector	Room 131 Left	Tested	10:09:00 AM	12/27/2018
Smoke Detector	Room 131 Right	Tested	10:09:47 AM	12/27/2018
Smoke Detector	Room 133 Center Left	Tested	10:12:32 AM	12/27/2018
Smoke Detector	Room 133 Center Right	Tested	10:12:59 AM	12/27/2018
Smoke Detector	Room 133 Left	Tested	10:12:23 AM	12/27/2018



Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
Smoke Detector	Room 133 Right	Tested	10:13:10 AM	12/27/2018
Smoke Detector	Room 135	Tested	11:31:17 AM	12/27/2018
Smoke Detector	Room 15 Center	Tested	9:55:54 AM	12/27/2018
Smoke Detector	Room 15 Left	Tested	9:56:10 AM	12/27/2018
Smoke Detector	Room 15 Right	Tested	9:55:42 AM	12/27/2018
Smoke Detector	Room 17	Tested	1:58:12 PM	12/27/2018
Smoke Detector	Sprinkler Room 11	Tested	11:17:04 AM	12/27/2018
Smoke Detector	Storage Room Across From Room 110	Tested	10:39:35 AM	12/27/2018
Smoke Detector	Storage Room 12	Tested	9:47:49 AM	12/27/2018
Smoke Detector	Strg Behind Custodians Rm 1	Tested	11:17:31 AM	12/27/2018
Smoke Detector	Upper Handicap Lift Area	Tested	2:34:16 PM	10/03/2018
Smoke Detector	Women's Room 29 Left Front	Tested	9:55:03 AM	12/27/2018
Smoke Detector	Hall by bathroom 29	Tested	2:32:11 PM	10/03/2018
Smoke Detector	Hall by boiler rm 2	Tested	2:37:55 PM	10/03/2018
Smoke Detector	Hall by exit near MPR 3	Tested	2:37:43 PM	10/03/2018
Smoke Detector	Hall by office 7	Tested	2:37:08 PM	10/03/2018
Smoke Detector	Hall by rm 101	Tested	2:41:24 PM	10/03/2018
Smoke Detector	Hall by rm 105	Tested	2:41:11 PM	10/03/2018
Smoke Detector	Hall By Rm 107	Tested	2:39:44 PM	10/03/2018
Smoke Detector	Hall by rm 110	Tested	2:36:29 PM	10/03/2018
Smoke Detector	Hall by rm 112	Tested	2:35:57 PM	10/03/2018
Smoke Detector	Hall by rm 114	Tested	2:35:33 PM	10/03/2018
Smoke Detector	Hall by rm 118	Tested	2:35:16 PM	10/03/2018
Smoke Detector	Hall by rm 8 Vice Principal	Tested	2:36:42 PM	10/03/2018
Smoke Detector	Hall by smoke doors near MPR 3	Tested	2:37:28 PM	10/03/2018
Smoke Detector	Hall stair by handicap lift	Tested	2:34:04 PM	10/03/2018
Waterflow Switch	1st In Room 11 Inside Room 123	Tested	3:13:18 PM	10/03/2018
Waterflow Switch	1st In Storage Room 6	Tested	3:16:36 PM	10/03/2018
<b>Supervisory</b>				
Tamper Switch	1st In Room 11 Inside Room 123	Tested	3:13:22 PM	10/03/2018
Tamper Switch	1st In Room 11 Inside Room 123	Tested	3:13:26 PM	10/03/2018
Tamper Switch	1st In Room 11 Inside Room 123	Tested	3:13:28 PM	10/03/2018
Tamper Switch	1st In Storage Room 6	Tested	3:16:29 PM	10/03/2018
Tamper Switch	1st In Storage Room 6	Tested	3:16:33 PM	10/03/2018
Device Type	Location	Service	Time	Date
<b><i>Failed/Other</i></b>				
<b>Control</b>				
Battery	1st In BPS In Room 81	Tested	2:58:29 PM	10/03/2018
Battery	1st In BPS In Room 81	Tested	2:58:41 PM	10/03/2018
Device Type	Location	Service	Time	Date
<b><i>Untested</i></b>				
<b>Initiating</b>				
Heat Detector	Above ceiling Hall by 101			
Heat Detector	Above ceiling Hall by 105			
Heat Detector	Above ceiling Hall by 107			
Heat Detector	Above ceiling Hall by boiler room 2			
Heat Detector	Above ceiling Hall by Computer lab 137			

Device Type	Location	Service	Time	Date
<i>Untested</i>				
Heat Detector	Above ceiling Hall by Main office			
Heat Detector	Above ceiling Hall by Nurse room 47			
Heat Detector	Above ceiling Hall by office 7			
Heat Detector	Above ceiling Hall by room 110			
Heat Detector	Above ceiling Hall by room 112			
Heat Detector	Above ceiling Hall by room 114			
Heat Detector	Above ceiling Hall by room 118			
Heat Detector	Above ceiling Hall by room 120			
Heat Detector	Above ceiling Hall by room 124			
Heat Detector	Above ceiling Hall by room 125			
Heat Detector	Above ceiling Hall by room 127			
Heat Detector	Above ceiling Hall by room 128			
Heat Detector	Above ceiling Hall by room 130			
Heat Detector	Above ceiling Hall by room 134			
Heat Detector	Above ceiling Hall by room 136			
Heat Detector	Above ceiling Hall by room 138			
Heat Detector	Above ceiling Hall by room 140			
Heat Detector	Above ceiling Hall by room 156			
Heat Detector	Above ceiling Hall by room 159			
Heat Detector	Above ceiling Hall by room 160			
Heat Detector	Above ceiling Hall by room 79			
Heat Detector	Above ceiling Hall near rest room 29			
Heat Detector	Above ceiling In room 110			
Heat Detector	Above ceiling In room 111			
Heat Detector	Above ceiling In room 112			
Heat Detector	Above ceiling In room 113			
Heat Detector	Above ceiling In room 114			
Heat Detector	Above ceiling In room 115			
Heat Detector	Above ceiling In room 116			
Heat Detector	Above ceiling In room 117			
Heat Detector	Above ceiling In room 118			
Heat Detector	Above ceiling In room 119			
Heat Detector	Above ceiling In room 120			
Heat Detector	Above ceiling In room 121			
Heat Detector	Above ceiling In room 122			
Heat Detector	Above ceiling Room 101 classroom			
Heat Detector	Above ceiling Room 102 classroom			
Heat Detector	Above ceiling Room 102 entry			

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Control</b>				
Control Panel	1st Storage 51	Tested	8:38:22 AM	10/03/2018
<b>Initiating</b>				
Duct Detector	1st AHU B2 RET. Faculty Room	Tested	11:46:05 AM	10/03/2018
Duct Detector	1st Boys Lav. By Cafe AHU-6	Tested	11:46:02 AM	10/03/2018
Duct Detector	1st Custodians Office Front AHU-5	Tested	11:46:00 AM	10/03/2018
Duct Detector	1st Custodians Office Rear AHU-4	Tested	11:46:01 AM	10/03/2018
Duct Detector	1st Faculty Room	Tested	11:46:04 AM	10/03/2018
Duct Detector	1st HVAC 10 Nurses Office	Tested	11:46:08 AM	10/03/2018
Duct Detector	1st HVAC 11 Main Office	Tested	11:46:06 AM	10/03/2018
Duct Detector	1st HVAC 9 Main Office Mail Room	Tested	11:46:07 AM	10/03/2018
Duct Detector	1st HVAC B8 Room 62	Tested	11:46:23 AM	10/03/2018
Heat Detector	A/C boy's bathroom 53	Tested	1:31:54 PM	12/27/2018
Heat Detector	A/C comp lab 137 front	Tested	1:43:26 PM	12/27/2018
Heat Detector	A/C comp lab 137 rear	Tested	1:45:01 PM	12/27/2018
Heat Detector	A/C conference rm 69	Tested	1:29:40 PM	12/27/2018
Heat Detector	A/C custodian closet 52	Tested	1:33:11 PM	12/27/2018
Heat Detector	A/C custodian office 51	Tested	1:34:38 PM	12/27/2018
Heat Detector	A/C girl's bathroom 54	Tested	1:30:42 PM	12/27/2018
Heat Detector	A/C hall by faculty rm	Tested	2:21:08 PM	12/27/2018
Heat Detector	A/C main office bathroom	Tested	1:43:14 PM	12/27/2018
Heat Detector	A/C main office kitchen	Tested	1:27:41 PM	12/27/2018
Heat Detector	A/C principal's office rm 72	Tested	1:25:27 PM	12/27/2018
Heat Detector	A/C Rm 136	Tested	2:00:42 PM	12/27/2018
Heat Detector	A/C Rm 18	Tested	2:07:56 PM	12/27/2018
Heat Detector	cafe under stage center left	Tested	2:25:40 PM	12/27/2018
Heat Detector	cafe under stage center right	Tested	2:26:31 PM	12/27/2018
Heat Detector	cafe under stage far left	Tested	2:22:51 PM	12/27/2018
Heat Detector	cafe under stage left	Tested	2:24:37 PM	12/27/2018
Heat Detector	cafe under stage right	Tested	2:27:22 PM	12/27/2018
Heat Detector	cafe under stage right	Tested	2:39:12 PM	12/27/2018
Heat Detector	Supply Rm 50	Tested	1:40:13 PM	12/27/2018
Pull Station	1st Cafe Rear Exit	Tested	9:50:21 AM	10/03/2018
Pull Station	1st Cafetorium Exit to Main Lobby	Tested	9:49:33 AM	10/03/2018
Pull Station	1st In Boiler Room Inside Faculty Dining Room	Tested	10:33:08 AM	10/03/2018
Pull Station	1st In Cafe By Room 40 Faculty Bathroom	Tested	9:52:05 AM	10/03/2018
Pull Station	1st In Hallway By Nurses Office	Tested	9:56:32 AM	10/03/2018
Pull Station	1st In Hallway By Room 135	Tested	10:01:26 AM	10/03/2018
Pull Station	1st In Hallway By Room 16 Storage	Tested	9:59:12 AM	10/03/2018
Pull Station	1st In Hallway By Room 39 Faculty Dining	Tested	10:00:08 AM	10/03/2018
Pull Station	1st Kitchen Exit	Tested	9:50:56 AM	10/03/2018
Pull Station	1st Main Entrance Lobby	Tested	9:44:38 AM	10/03/2018
Pull Station	1st Main Lobby Rear Exit	Tested	9:46:20 AM	10/03/2018
Pull Station	1st Media Center Front Entrance	Tested	9:47:17 AM	10/03/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Pull Station	1st Media Center Rear Exit	Tested	9:55:21 AM	10/03/2018
Pull Station	1st Next to exit door By Room 12 Art Storage	Tested	9:57:21 AM	10/03/2018
Pull Station	1st On Stage left	Tested	9:54:05 AM	10/03/2018
Pull Station	1st Rear Stage Exit	Tested	9:53:19 AM	10/03/2018
Smoke Detector	Boys Bathroom 53	Tested	9:40:51 AM	12/27/2018
Smoke Detector	Cafe Center Front	Tested	9:25:02 AM	12/27/2018
Smoke Detector	Cafe Left Front	Tested	9:25:18 AM	12/27/2018
Smoke Detector	Cafe Middle Right	Tested	9:32:05 AM	12/27/2018
Smoke Detector	Cafe Right Front	Tested	9:24:39 AM	12/27/2018
Smoke Detector	Custodian Closet 52	Tested	9:41:20 AM	12/27/2018
Smoke Detector	Faculty Room	Tested	9:38:01 AM	12/27/2018
Smoke Detector	Girls Bathroom 54	Tested	9:40:30 AM	12/27/2018
Smoke Detector	Hall By Boy's Bathroom 53	Tested	2:25:37 PM	10/03/2018
Smoke Detector	Hallway Across From Room 15	Tested	9:56:47 AM	12/27/2018
Smoke Detector	Kitchen Custodial Closet	Tested	9:36:21 AM	12/27/2018
Smoke Detector	Kitchen Lav	Tested	9:36:49 AM	12/27/2018
Smoke Detector	Kitchen Locker Rm	Tested	9:36:34 AM	12/27/2018
Smoke Detector	Kitchen storage	Tested	11:17:22 AM	12/27/2018
Smoke Detector	Nurses Office Exam Room 1	Tested	11:14:41 AM	12/27/2018
Smoke Detector	Nurses Office Exam Room 2	Tested	11:14:50 AM	12/27/2018
Smoke Detector	Nurses Room 47 Bathroom	Tested	11:16:17 AM	12/27/2018
Smoke Detector	Nurses Room 47	Tested	11:15:47 AM	12/27/2018
Smoke Detector	Rm 137 Computer Lab Front	Tested	11:14:29 AM	12/27/2018
Smoke Detector	Rm 137 Computer Lab Rear	Tested	11:14:45 AM	12/27/2018
Smoke Detector	Room 124 Center Left	Tested	9:45:59 AM	12/27/2018
Smoke Detector	Room 124 Center Right	Tested	9:46:15 AM	12/27/2018
Smoke Detector	Room 124 Far Left	Tested	9:45:05 AM	12/27/2018
Smoke Detector	Room 124 Far Right	Tested	9:46:49 AM	12/27/2018
Smoke Detector	Room 124 Kilm Closet	Tested	9:45:15 AM	12/27/2018
Smoke Detector	Room 124 Left	Tested	9:45:42 AM	12/27/2018
Smoke Detector	Room 124 Right	Tested	9:46:32 AM	12/27/2018
Smoke Detector	Room 125 Center Left	Tested	9:49:57 AM	12/27/2018
Smoke Detector	Room 125 Center Right	Tested	9:49:37 AM	12/27/2018
Smoke Detector	Room 125 Far Left	Tested	9:50:54 AM	12/27/2018
Smoke Detector	Room 125 Far Right	Tested	9:49:16 AM	12/27/2018
Smoke Detector	Room 125 Left	Tested	9:50:16 AM	12/27/2018
Smoke Detector	Room 125 Right	Tested	9:49:25 AM	12/27/2018
Smoke Detector	Room 127 Center Left	Tested	9:58:03 AM	12/27/2018
Smoke Detector	Room 127 Center Right	Tested	9:58:19 AM	12/27/2018
Smoke Detector	Room 127 Left	Tested	9:57:47 AM	12/27/2018
Smoke Detector	Room 127 Right	Tested	9:58:34 AM	12/27/2018
Smoke Detector	Room 128 Center Left	Tested	10:01:50 AM	12/27/2018
Smoke Detector	Room 128 Center Right	Tested	10:02:05 AM	12/27/2018
Smoke Detector	Room 128 Left	Tested	10:01:38 AM	12/27/2018
Smoke Detector	Room 128 Right	Tested	10:02:21 AM	12/27/2018
Smoke Detector	Room 130 Center Left	Tested	10:07:49 AM	12/27/2018
Smoke Detector	Room 130 Center Right	Tested	10:08:03 AM	12/27/2018
Smoke Detector	Room 130 Left	Tested	10:07:40 AM	12/27/2018
Smoke Detector	Room 130 Right	Tested	10:08:15 AM	12/27/2018
Smoke Detector	Room 132 Center Left	Tested	10:10:36 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 132 Center Right	Tested	10:11:23 AM	12/27/2018
Smoke Detector	Room 132 Left	Tested	10:10:26 AM	12/27/2018
Smoke Detector	Room 132 Right	Tested	10:11:38 AM	12/27/2018
Smoke Detector	Room 134 Center Left	Tested	10:14:09 AM	12/27/2018
Smoke Detector	Room 134 Center Right	Tested	10:14:24 AM	12/27/2018
Smoke Detector	Room 134 Left	Tested	10:14:00 AM	12/27/2018
Smoke Detector	Room 134 Right	Tested	10:14:42 AM	12/27/2018
Smoke Detector	Room 136	Tested	10:16:40 AM	12/27/2018
Smoke Detector	Room 18	Tested	10:15:23 AM	12/27/2018
Smoke Detector	Stage Center Cafetorium	Tested	9:29:11 AM	12/27/2018
Smoke Detector	Stage Hall Door 42	Tested	9:42:58 AM	12/27/2018
Smoke Detector	Stage Left Cafetorium	Tested	9:30:26 AM	12/27/2018
Smoke Detector	Stage Right Cafetorium	Tested	9:28:40 AM	12/27/2018
Smoke Detector	Supply Room 50	Tested	9:42:23 AM	12/27/2018
Smoke Detector	Cafe Middle Center	Tested	9:31:37 AM	12/27/2018
Smoke Detector	Cafe Middle Left	Tested	9:31:18 AM	12/27/2018
Smoke Detector	Cafe Rear center	Tested	9:34:34 AM	12/27/2018
Smoke Detector	Cafe Rear left	Tested	9:34:54 AM	12/27/2018
Smoke Detector	Cafe Rear right	Tested	9:32:26 AM	12/27/2018
Smoke Detector	Custodians office 51	Tested	9:41:48 AM	12/27/2018
Smoke Detector	Faculty Lav 40	Tested	9:35:35 AM	12/27/2018
Smoke Detector	Hall by Computer Lab 137	Tested	2:26:09 PM	10/03/2018
Smoke Detector	Hall by conference room 69	Tested	2:23:02 PM	10/03/2018
Smoke Detector	Hall by courtyard near stage	Tested	2:29:42 PM	10/03/2018
Smoke Detector	Hall by faculty rm	Tested	2:29:58 PM	10/03/2018
Smoke Detector	Hall by girls bathroom 54	Tested	2:25:06 PM	10/03/2018
Smoke Detector	Hall by main office	Tested	2:23:29 PM	10/03/2018
Smoke Detector	Hall by Nurse's Office	Tested	2:26:43 PM	10/03/2018
Smoke Detector	Hall by rm 124	Tested	2:26:55 PM	10/03/2018
Smoke Detector	Hall by rm 125	Tested	2:27:10 PM	10/03/2018
Smoke Detector	Hall by rm 127	Tested	2:27:34 PM	10/03/2018
Smoke Detector	Hall by rm 128	Tested	2:27:46 PM	10/03/2018
Smoke Detector	Hall by rm 130	Tested	2:30:17 PM	10/03/2018
Smoke Detector	Hall by rm 134	Tested	2:30:29 PM	10/03/2018
Smoke Detector	Hall by rm 136	Tested	2:30:50 PM	10/03/2018
Smoke Detector	Hall by supply room 50	Tested	2:25:55 PM	10/03/2018
Smoke Detector	Kitchen Break room	Tested	9:37:15 AM	12/27/2018
Smoke Detector	Kitchen Office	Tested	11:16:56 AM	12/27/2018
Smoke Detector	Main entrance left	Tested	2:24:19 PM	10/03/2018
Smoke Detector	Main entrance right	Tested	2:24:04 PM	10/03/2018
Smoke Detector	Main Entrance Vestibule Left	Tested	2:24:30 PM	10/03/2018
Smoke Detector	Main entrance vestibule right	Tested	2:24:42 PM	10/03/2018
Smoke Detector	Main lobby front	Tested	2:23:44 PM	10/03/2018
Smoke Detector	Main lobby rear	Tested	2:24:56 PM	10/03/2018
Smoke Detector	Main Office	Tested	9:11:10 AM	12/27/2018
Smoke Detector	Main Office Bathroom	Tested	9:11:37 AM	12/27/2018
Smoke Detector	Main Office Kitchen	Tested	9:12:40 AM	12/27/2018
Smoke Detector	Media Center Alcove	Tested	9:23:30 AM	12/27/2018
Smoke Detector	Media Center by Entrance	Tested	9:16:01 AM	12/27/2018
Smoke Detector	Media Center Computer Area	Tested	9:17:28 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Media Center Conference rm	Tested	9:21:44 AM	12/27/2018
Smoke Detector	Media Center Front Desk Area	Tested	9:16:21 AM	12/27/2018
Smoke Detector	Media Center Office 58	Tested	11:15:52 AM	12/27/2018
Smoke Detector	Media Center Office 59	Tested	9:16:41 AM	12/27/2018
Smoke Detector	Media Center Over Books	Tested	9:22:44 AM	12/27/2018
Smoke Detector	Media Center Table Area 1	Tested	9:23:09 AM	12/27/2018
Smoke Detector	Media Center Table Area 2	Tested	9:22:20 AM	12/27/2018
Smoke Detector	Room 60	Tested	9:08:33 AM	12/27/2018
Smoke Detector	Room 62	Tested	9:10:33 AM	12/27/2018
Smoke Detector	Room 63	Tested	9:10:14 AM	12/27/2018
Smoke Detector	Room 64	Tested	9:09:42 AM	12/27/2018
Smoke Detector	Room 65	Tested	9:09:29 AM	12/27/2018
Smoke Detector	Room 66	Tested	9:08:51 AM	12/27/2018
Smoke Detector	Room 69 Conference	Tested	9:07:48 AM	12/27/2018
Smoke Detector	Room 71 Asst Principals Off	Tested	11:14:36 AM	12/27/2018
Smoke Detector	Room 72 Principals Office	Tested	9:12:00 AM	12/27/2018
Smoke Detector	Small Hall between rms 128 & 130	Tested	2:27:58 PM	10/03/2018
Device Type	Location	Service	Time	Date
<i>Untested</i>				
<b>Initiating</b>				
Heat Detector	A/C Main Office			
Heat Detector	A/C Nurses Exam Rm 1			
Heat Detector	A/C Nurses Exam Rm 2			
Heat Detector	A/C Nurses Rm 47			
Heat Detector	A/C Nurses Rm 47 Lav			
Heat Detector	A/C Rm 60			
Heat Detector	A/C Rm 62			
Heat Detector	A/C Rm 63			
Heat Detector	A/C Rm 64			
Heat Detector	A/C Rm 65			
Heat Detector	A/C Rm 66			

*The Inspection & Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time & date at which testing occurred.*

Device Type	Location	Service	Time	Date
<b><i>Passed</i></b>				
<b>Initiating</b>				
Beam Detector	1st M.P.R. Front	Tested	1:31:19 PM	10/03/2018
Beam Detector	1st M.P.R. Rear	Tested	1:31:20 PM	10/03/2018
Duct Detector	1st MPR Back Stage	Tested	11:46:27 AM	10/03/2018
Duct Detector	1st MPR Storage Room 95	Tested	11:46:28 AM	10/03/2018
Duct Detector	1st Music Room Office	Tested	11:46:26 AM	10/03/2018
Pull Station	1st Boiler Room Exit	Tested	8:53:23 AM	10/03/2018
Pull Station	1st Hall Exit By M.P.R.	Tested	9:23:50 AM	10/03/2018
Pull Station	1st Hall Exit By Rm 139	Tested	9:42:16 AM	10/03/2018
Pull Station	1st Hall Exit By Rm 151	Tested	9:36:51 AM	10/03/2018
Pull Station	1st Hall Exit By Room 164	Tested	8:47:38 AM	10/03/2018
Pull Station	1st M.P.R. Rm Exit By Stage	Tested	8:45:53 AM	10/03/2018
Pull Station	1st M.P.R. Storage Room 96 Exit	Tested	8:51:08 AM	10/03/2018
Pull Station	1st Receiving Room 90	Tested	10:36:13 AM	10/03/2018
Pull Station	1st Room 162 Exit	Tested	8:54:17 AM	10/03/2018
Pull Station	1st Room 164 Exit	Tested	8:55:18 AM	10/03/2018
Smoke Detector	Room 139 Bathroom	Tested	8:46:06 AM	12/27/2018
Smoke Detector	Boys Lav 99D	Tested	8:09:38 AM	12/27/2018
Smoke Detector	Boys Lav by Room 152	Tested	8:26:15 AM	12/27/2018
Smoke Detector	Closet in storage 74	Tested	9:05:51 AM	12/27/2018
Smoke Detector	Custodian closet by Room 151	Tested	8:27:49 AM	12/27/2018
Smoke Detector	Girls Lav 99E	Tested	8:08:51 AM	12/27/2018
Smoke Detector	Girls lav by rm 150	Tested	9:04:04 AM	12/27/2018
Smoke Detector	Hall by boiler rm	Tested	2:14:48 PM	10/03/2018
Smoke Detector	Hall by MPR	Tested	2:15:45 PM	10/03/2018
Smoke Detector	Hall by MPR 92	Tested	2:16:00 PM	10/03/2018
Smoke Detector	Hall by rm 138	Tested	2:21:29 PM	10/03/2018
Smoke Detector	Hall by rm 140	Tested	2:21:15 PM	10/03/2018
Smoke Detector	Hall by rm 144	Tested	2:20:44 PM	10/03/2018
Smoke Detector	Hall by rm 149	Tested	2:20:25 PM	10/03/2018
Smoke Detector	Hall by rm 150	Tested	2:20:02 PM	10/03/2018
Smoke Detector	Hall by rm 151	Tested	2:19:44 PM	10/03/2018
Smoke Detector	Hall by rm 152	Tested	2:18:33 PM	10/03/2018
Smoke Detector	Hall by rm 156	Tested	2:17:31 PM	10/03/2018
Smoke Detector	Hall by rm 159	Tested	2:16:58 PM	10/03/2018
Smoke Detector	Hall by rm 160	Tested	2:16:45 PM	10/03/2018
Smoke Detector	Hall by rm 162	Tested	2:15:05 PM	10/03/2018
Smoke Detector	Hall by rm 79	Tested	2:16:26 PM	10/03/2018
Smoke Detector	Hall by rm 84	Tested	2:15:29 PM	10/03/2018
Smoke Detector	Janitors closet room 83	Tested	8:09:15 AM	12/27/2018
Smoke Detector	MPR Office 93	Tested	11:16:52 AM	12/27/2018
Smoke Detector	MPR Office 93 lav	Tested	11:16:22 AM	12/27/2018
Smoke Detector	MPR Stage Center	Tested	7:57:37 AM	12/27/2018
Smoke Detector	MPR Stage Center Left	Tested	7:57:47 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	MPR Stage Center Right	Tested	7:57:59 AM	12/27/2018
Smoke Detector	MPR Stage Far Left	Tested	7:57:26 AM	12/27/2018
Smoke Detector	MPR Stage Far Right	Tested	7:58:10 AM	12/27/2018
Smoke Detector	MPR Storage rm 95 left	Tested	11:17:35 AM	12/27/2018
Smoke Detector	MPR Storage rm 95 right	Tested	11:16:26 AM	12/27/2018
Smoke Detector	MPR Storage rm 96 closet	Tested	11:14:54 AM	12/27/2018
Smoke Detector	MPR Storage rm 96 left	Tested	11:16:35 AM	12/27/2018
Smoke Detector	MPR Storage rm 96 right	Tested	11:16:10 AM	12/27/2018
Smoke Detector	Music Office 86	Tested	11:17:39 AM	12/27/2018
Smoke Detector	Practice Room 87 A	Tested	11:15:14 AM	12/27/2018
Smoke Detector	Practice Room 88 B	Tested	11:17:47 AM	12/27/2018
Smoke Detector	Receiving room 90 left	Tested	11:16:59 AM	12/27/2018
Smoke Detector	Receiving room 90 right	Tested	11:14:58 AM	12/27/2018
Smoke Detector	Room 138	Tested	8:46:54 AM	12/27/2018
Smoke Detector	Room 138 lav	Tested	8:47:06 AM	12/27/2018
Smoke Detector	Room 139	Tested	8:46:17 AM	12/27/2018
Smoke Detector	Room 140 Center	Tested	8:47:56 AM	12/27/2018
Smoke Detector	Room 140 Left	Tested	8:48:24 AM	12/27/2018
Smoke Detector	Room 140 Right	Tested	8:47:41 AM	12/27/2018
Smoke Detector	Room 141 Center	Tested	8:49:13 AM	12/27/2018
Smoke Detector	Room 141 Left	Tested	8:49:24 AM	12/27/2018
Smoke Detector	Room 141 Right	Tested	8:48:51 AM	12/27/2018
Smoke Detector	Room 142 Center	Tested	8:50:15 AM	12/27/2018
Smoke Detector	Room 142 Left	Tested	8:50:31 AM	12/27/2018
Smoke Detector	Room 142 Right	Tested	8:49:59 AM	12/27/2018
Smoke Detector	Room 143 Center	Tested	8:51:27 AM	12/27/2018
Smoke Detector	Room 143 Left	Tested	8:51:56 AM	12/27/2018
Smoke Detector	Room 143 Right	Tested	8:51:09 AM	12/27/2018
Smoke Detector	Room 144 Center	Tested	8:52:55 AM	12/27/2018
Smoke Detector	Room 144 Left	Tested	8:53:12 AM	12/27/2018
Smoke Detector	Room 144 Right	Tested	8:52:36 AM	12/27/2018
Smoke Detector	Room 145 Center	Tested	11:16:43 AM	12/27/2018
Smoke Detector	Room 145 Left	Tested	11:17:52 AM	12/27/2018
Smoke Detector	Room 145 Right	Tested	11:15:30 AM	12/27/2018
Smoke Detector	Room 146 Center	Tested	8:54:38 AM	12/27/2018
Smoke Detector	Room 146 Far Left	Tested	11:18:02 AM	12/27/2018
Smoke Detector	Room 146 Far Right	Tested	8:54:10 AM	12/27/2018
Smoke Detector	Room 146 Left	Tested	8:54:49 AM	12/27/2018
Smoke Detector	Room 146 Right	Tested	8:54:24 AM	12/27/2018
Smoke Detector	Room 147 Center	Tested	8:56:21 AM	12/27/2018
Smoke Detector	Room 147 Left	Tested	8:56:39 AM	12/27/2018
Smoke Detector	Room 147 Right	Tested	8:56:07 AM	12/27/2018
Smoke Detector	Room 148 Center	Tested	8:59:50 AM	12/27/2018
Smoke Detector	Room 148 Far Left	Tested	9:00:26 AM	12/27/2018
Smoke Detector	Room 148 Far Right	Tested	8:59:21 AM	12/27/2018
Smoke Detector	Room 148 Left	Tested	9:00:05 AM	12/27/2018
Smoke Detector	Room 148 Right	Tested	8:59:33 AM	12/27/2018
Smoke Detector	Room 149 Center	Tested	8:58:16 AM	12/27/2018
Smoke Detector	Room 149 Left	Tested	8:58:34 AM	12/27/2018
Smoke Detector	Room 149 Right	Tested	8:58:04 AM	12/27/2018



Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 150 Center	Tested	9:03:05 AM	12/27/2018
Smoke Detector	Room 150 Left	Tested	9:03:15 AM	12/27/2018
Smoke Detector	Room 150 Right	Tested	9:02:53 AM	12/27/2018
Smoke Detector	Room 151 Center	Tested	8:27:02 AM	12/27/2018
Smoke Detector	Room 151 Left	Tested	8:27:17 AM	12/27/2018
Smoke Detector	Room 151 Right	Tested	8:26:50 AM	12/27/2018
Smoke Detector	Room 152 Center	Tested	8:25:18 AM	12/27/2018
Smoke Detector	Room 152 Right	Tested	8:25:08 AM	12/27/2018
Smoke Detector	Room 153 Center	Tested	8:24:00 AM	12/27/2018
Smoke Detector	Room 153 Left	Tested	8:23:49 AM	12/27/2018
Smoke Detector	Room 153 Right	Tested	8:24:17 AM	12/27/2018
Smoke Detector	Room 154 Center	Tested	8:22:44 AM	12/27/2018
Smoke Detector	Room 154 Left	Tested	8:22:59 AM	12/27/2018
Smoke Detector	Room 154 Right	Tested	8:22:33 AM	12/27/2018
Smoke Detector	Room 155 Center	Tested	8:21:30 AM	12/27/2018
Smoke Detector	Room 155 Left	Tested	8:21:19 AM	12/27/2018
Smoke Detector	Room 155 Right	Tested	8:21:42 AM	12/27/2018
Smoke Detector	Room 156 Center	Tested	8:20:08 AM	12/27/2018
Smoke Detector	Room 156 Center	Tested	8:20:26 AM	12/27/2018
Smoke Detector	Room 156 Right	Tested	8:19:57 AM	12/27/2018
Smoke Detector	Room 157 Center	Tested	8:18:57 AM	12/27/2018
Smoke Detector	Room 157 Left	Tested	8:19:08 AM	12/27/2018
Smoke Detector	Room 157 Right	Tested	8:18:47 AM	12/27/2018
Smoke Detector	Room 158 Center	Tested	8:17:39 AM	12/27/2018
Smoke Detector	Room 158 Left	Tested	8:18:00 AM	12/27/2018
Smoke Detector	Room 158 Right	Tested	8:17:23 AM	12/27/2018
Smoke Detector	Room 159 Center	Tested	8:16:38 AM	12/27/2018
Smoke Detector	Room 159 Left	Tested	8:16:47 AM	12/27/2018
Smoke Detector	Room 159 Right	Tested	8:16:08 AM	12/27/2018
Smoke Detector	Room 160 Center	Tested	8:13:04 AM	12/27/2018
Smoke Detector	Room 160 Far Left	Tested	8:13:34 AM	12/27/2018
Smoke Detector	Room 160 Far Right	Tested	8:12:35 AM	12/27/2018
Smoke Detector	Room 160 Left	Tested	8:13:18 AM	12/27/2018
Smoke Detector	Room 160 Right	Tested	8:12:49 AM	12/27/2018
Smoke Detector	Room 160 Storage	Tested	8:14:05 AM	12/27/2018
Smoke Detector	Room 161 Center	Tested	8:06:01 AM	12/27/2018
Smoke Detector	Room 161 Left	Tested	8:05:53 AM	12/27/2018
Smoke Detector	Room 161 Right	Tested	8:06:28 AM	12/27/2018
Smoke Detector	Room 162 Center	Tested	8:02:07 AM	12/27/2018
Smoke Detector	Room 162 Center Left	Tested	8:01:01 AM	12/27/2018
Smoke Detector	Room 162 Center Right	Tested	8:00:29 AM	12/27/2018
Smoke Detector	Room 162 Far Left	Tested	8:01:15 AM	12/27/2018
Smoke Detector	Room 162 Far Right	Tested	8:00:40 AM	12/27/2018
Smoke Detector	Room 163 Center Left	Tested	8:02:56 AM	12/27/2018
Smoke Detector	Room 163 Center Right	Tested	8:03:16 AM	12/27/2018
Smoke Detector	Room 163 Far Left	Tested	8:02:45 AM	12/27/2018
Smoke Detector	Room 163 Far Right	Tested	8:03:37 AM	12/27/2018
Smoke Detector	Room 164 Center	Tested	11:15:24 AM	12/27/2018
Smoke Detector	Room 164 Center Left	Tested	11:16:05 AM	12/27/2018
Smoke Detector	Room 164 Center Right	Tested	11:15:03 AM	12/27/2018

Device Type	Location	Service	Time	Date
<i>Passed</i>				
Smoke Detector	Room 164 Far Left	Tested	11:15:59 AM	12/27/2018
Smoke Detector	Room 164 Far Right	Tested	11:15:41 AM	12/27/2018
Smoke Detector	Room 75	Tested	8:15:19 AM	12/27/2018
Smoke Detector	Room 75 lav	Tested	8:15:39 AM	12/27/2018
Smoke Detector	Room 76	Tested	8:14:47 AM	12/27/2018
Smoke Detector	Room 77	Tested	8:12:01 AM	12/27/2018
Smoke Detector	Room 78	Tested	8:11:40 AM	12/27/2018
Smoke Detector	Room 79	Tested	8:10:16 AM	12/27/2018
Smoke Detector	Room 81 Storage	Tested	8:10:48 AM	12/27/2018
Smoke Detector	Room 84	Tested	11:16:31 AM	12/27/2018
Smoke Detector	Room 85 Left	Tested	8:04:37 AM	12/27/2018
Smoke Detector	Room 85 Right	Tested	8:04:21 AM	12/27/2018
Smoke Detector	Staff Lav 99F	Tested	8:08:27 AM	12/27/2018
Smoke Detector	Storage rm 74 left by rm 150	Tested	9:04:57 AM	12/27/2018
Smoke Detector	Storage rm 74 right by rm 150	Tested	9:04:47 AM	12/27/2018
Smoke Detector	Storage Room 99H	Tested	8:57:29 AM	12/27/2018
Smoke Detector	Storage Room between 148 & 146	Tested	8:55:16 AM	12/27/2018
Smoke Detector	Work Room 82	Tested	8:07:12 AM	12/27/2018
Smoke Detector	Work Room 82 Lav	Tested	8:07:49 AM	12/27/2018
Device Type	Location	Service	Time	Date
<i>Untested</i>				
<b>Initiating</b>				
Heat Detector	A/C Rm 77			
Heat Detector	A/C Rm 78			
Heat Detector	A/C Rm 79			

# Service Summary

Generated by: BuildingReports.com

Building: Montgomery Orchard Hill School

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Battery	Tested	2
Total		2
<b><i>Passed</i></b>		
Annunciator	Tested	2
Battery	Tested	14
Beam Detector	Tested	4
Control Panel	Tested	1
Duct Detector	Tested	15
Expander Panel	Tested	2
Heat Detector	Tested	24
Power Supply	Tested	5
Pull Station	Tested	37
Smoke Detector	Tested	428
Tamper Switch	Tested	5
Waterflow Switch	Tested	2
Total		541
<b><i>Untested</i></b>		
Heat Detector		57
Total		598

# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery Orchard Hill School		Control Panel: 1					
<p>The Control &amp; Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</p>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<b>Passed</b>							
<b>Battery</b>							
Sealed Lead Acid	1st In BPS In Room 16	4	12				
Sealed Lead Acid	1st In BPS In Room 16	4	12				
Sealed Lead Acid	1st In BPS In Room 74 Above Door	4	12				
Sealed Lead Acid	1st In BPS In Room 74 Above Door	4	12				
Sealed Lead Acid	1st In Storage Room 6	7	12				
Sealed Lead Acid	1st In Storage Room 6	7	12				
Sealed Lead Acid	1st In Storage Room 6	7	12				
Sealed Lead Acid	1st In Storage Room 6	7	12				
Sealed Lead Acid	Head custodian office 51	35	12				
Sealed Lead Acid	Head custodian office 51	35	12				
Sealed Lead Acid	Storage 6	18	12				
Sealed Lead Acid	Storage 6	18	12				
Sealed Lead Acid	Storage 81	18	12				
Sealed Lead Acid	Storage 81	18	12				
<b>Power Supply</b>							
	Storage 6	10					
<b>Failed/Other</b>							
<b>Battery</b>							
Sealed Lead Acid	1st In BPS In Room 81	7	12				
Sealed Lead Acid	1st In BPS In Room 81	7	12				

# Inventory & Warranty Report

Generated by: *BuildingReports.com*

Building: Montgomery Orchard Hill School		Control Panel: 1		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	13.55%	81	
Control Panel	Control	0.17%	1	
Battery	Control	2.68%	16	
Pull Station	Initiating	6.19%	37	
Annunciator	Control	0.33%	2	
Duct Detector	Initiating	2.51%	15	
Beam Detector	Initiating	0.67%	4	
Expander Panel	Control	0.33%	2	
Power Supply	Control	0.84%	5	
Smoke Detector	Initiating	71.57%	428	
Waterflow Switch	Initiating	0.33%	2	
Tamper Switch	Supervisory	0.84%	5	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Power Supply	2	BPS10a		09/02/2016
<b>Interstate</b>				
Battery	2	BSL1116	Sealed Lead Acid	09/02/2016
<b>Power-Sonic</b>				
Battery	2	ps-12350	Sealed Lead Acid	09/02/2016
<b>EST</b>				
Annunciator	2	LCD-3	LCD Display	09/01/2016
Beam Detector	2			09/01/2016
Duct Detector	1	EST3		09/01/2016
Duct Detector	1	SD		09/01/2016
Duct Detector	1	SIGA-SD	Photoelectric	09/01/2016
Heat Detector	27	SIGA		09/01/2016
Heat Detector	14	SIGA HFS		09/01/2016
Heat Detector	1	SIGA HRS		09/01/2016
Heat Detector	5	SIGA HRS	Rate-of-Rise	09/01/2016
Power Supply	1	BPS6A		09/01/2016
Power Supply	2	EST3		09/01/2016
Pull Station	11	SIGA 278	Dual Action	09/01/2016
Smoke Detector	3	SIGA PS		09/01/2016
Smoke Detector	165	SIGA PS	Photoelectric	09/01/2016
<b>EST3</b>				
Expander Panel	1			09/01/2016

<b>Potter Electric</b>				
Tamper Switch	5	OSYSU-2		09/01/2016
Waterflow Switch	2	VSR-F		09/01/2016
<b>Power Patrol</b>				
Battery	4	SEC1050	Sealed Lead Acid	09/01/2016
<i><b>In Service - 3 Years to 5 Years</b></i>				
<b>Power-Sonic</b>				
Battery	1	PS-12180	Sealed Lead Acid	06/06/2015
<b>EST</b>				
Expander Panel	1	PS-12180		06/05/2015
<b>Power-Sonic</b>				
Battery	1	PS-12180 F2	Sealed Lead Acid	06/05/2015
<b>Ultra Tech</b>				
Battery	4	UT1270	Sealed Lead Acid	06/05/2015
Battery	2	UT1270	Sealed Lead Acid	09/19/2014

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Control Panel	1	est3		09/02/2016
Duct Detector	6	EST3		09/01/2016
Duct Detector	1	EST3	Photoelectric	09/01/2016
Duct Detector	1	SD		09/01/2016
Duct Detector	1	SIGA-SD	Photoelectric	09/01/2016
Heat Detector	20	SIGA HRS	Rate-of-Rise	09/01/2016
Heat Detector	11	SIGA-HRS	Fixed Temperature	09/01/2016
Pull Station	2	SIGA 278		09/01/2016
Pull Station	14	SIGA 278	Dual Action	09/01/2016
Smoke Detector	113	SIGA PS	Photoelectric	09/01/2016

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
<b>EST</b>				
Beam Detector	1			09/01/2016
Beam Detector	1	EST3		09/01/2016
Duct Detector	3	EST3		09/01/2016
Heat Detector	3	SIGA-HRS	Fixed Temperature	09/01/2016
Pull Station	10	SIGA 278	Dual Action	09/01/2016
Smoke Detector	147	SIGA PS	Photoelectric	09/01/2016



# Zone Address Report

Generated by: BuildingReports.com

**Building: Montgomery Orchard Hill School      Control Panel: 1**

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
0000	Smoke Detector	1st Room 109 Storage	Photoelectric	3993764645
0001	Smoke Detector	Room 102 Alcove Left	Photoelectric	3993878731
0002	Smoke Detector	Room 102 Closet Left	Photoelectric	3993859242
0003	Smoke Detector	Room 102	Photoelectric	3993870148
0004	Smoke Detector	Room 101 Entrance	Photoelectric	3993875228
0005	Smoke Detector	Room 101 Closet Right	Photoelectric	3993877871
0006	Smoke Detector	Room 101 Bathroom	Photoelectric	3993877598
0007	Smoke Detector	Room 101 Alcove Left	Photoelectric	3993859846
0008	Smoke Detector	Room 101	Photoelectric	3993870568
0009	Smoke Detector	Room 103 Center Left	Photoelectric	3993874580
0010	Smoke Detector	Room 103 Left	Photoelectric	3993877055
0011	Smoke Detector	Room 103 Bathroom	Photoelectric	3993877963
0012	Smoke Detector	Room 103 Closet	Photoelectric	3993870476
0013	Smoke Detector	Room 104 Right	Photoelectric	3993874467
0014	Smoke Detector	Room 104 Center Right	Photoelectric	3993878076
0015	Smoke Detector	Room 104 Center Left	Photoelectric	3993874443
0016	Smoke Detector	Room 104 Left	Photoelectric	3993871947
0017	Smoke Detector	Room 104 Bathroom	Photoelectric	3993873729
0018	Smoke Detector	Hall by rm 101	Photoelectric	3993877994
0019	Smoke Detector	Room 102 Entrance	Photoelectric	3993860040
0020	Smoke Detector	Room 102 Bathroom	Photoelectric	3993876584
0021	Smoke Detector	Room 106 Right	Photoelectric	3993877666
0022	Smoke Detector	Room 106 Center Right	Photoelectric	3993877802
0023	Smoke Detector	Room 106 Center Left	Photoelectric	3993871053
0024	Smoke Detector	Room 106 Left	Photoelectric	3993871961
0025	Smoke Detector	Room 106 Bathroom	Photoelectric	3993874788
0026	Smoke Detector	Room 105 Left	Photoelectric	3993871411
0027	Smoke Detector	Room 105 Center Left	Photoelectric	3993870100
0028	Smoke Detector	Room 105 Center Right	Photoelectric	3993870209
0029	Smoke Detector	Room 105 Right	Photoelectric	3993871992
0030	Smoke Detector	Room 105 Storage	Photoelectric	3993871107
0031	Smoke Detector	Room 105 Bathroom	Photoelectric	3993877840
0032	Smoke Detector	Hall by rm 105	Photoelectric	3993875129
0033	Smoke Detector	Room 103 Right	Photoelectric	3993873507
0034	Smoke Detector	Room 103 Center Right	Photoelectric	3993873668
0035	Smoke Detector	Custodians Rm 1	Photoelectric	3993870728
0036	Smoke Detector	Strg Behind Custodians Rm 1	Photoelectric	3993859860
0037	Smoke Detector	Room 108 Right	Photoelectric	3993874016
0038	Smoke Detector	Room 108 Center Right	Photoelectric	3993875341
0039	Smoke Detector	Room 108 Center Left	Photoelectric	3993878045

0040	Smoke Detector	Room 108 Left	Photoelectric	3993873880
0041	Smoke Detector	Room 108 Bathroom	Photoelectric	3993870032
0042	Smoke Detector	Hall By Rm 107	Photoelectric	3993870391
0043	Smoke Detector	Room 107 Right	Photoelectric	3993870544
0044	Smoke Detector	Room 107 Center Right	Photoelectric	3993878069
0045	Smoke Detector	Room 107 Center Left	Photoelectric	3993870223
0046	Smoke Detector	Room 107 Left	Photoelectric	3993870902
0047	Smoke Detector	Room 107 Storage Rm	Photoelectric	3993870315
0048	Smoke Detector	Room 107 Bathroom	Photoelectric	3993870056
0049	Smoke Detector	Hall by office 7	Photoelectric	3993870117
0050	Smoke Detector	1st Room 6 Front		3993869890
0051	Smoke Detector	1st Room 6 Center		3993870773
0052	Smoke Detector	1st Room 6 Rear		3993860002
0053	Smoke Detector	1st M.P.R. 3 Office	Photoelectric	3993875037
0055	Smoke Detector	1st M.P.R. 3 Storage	Photoelectric	3993873453
0056	Smoke Detector	Hall by smoke doors near MPR 3	Photoelectric	3993872012
0057	Smoke Detector	Hall by exit near MPR 3	Photoelectric	3993875303
0058	Smoke Detector	Hall by boiler rm 2	Photoelectric	3993859372
0059	Smoke Detector	Hall by rm 110	Photoelectric	3993874627
0060	Smoke Detector	Room 110 Left Bathroom	Photoelectric	3993870346
0061	Smoke Detector	Room 110 Right Bathroom	Photoelectric	3993874108
0062	Smoke Detector	Rm 10 Custodian Closet	Photoelectric	3993871985
0063	Smoke Detector	Girls Bathroom 28	Photoelectric	3993870599
0064	Smoke Detector	Boys Bathroom 27	Photoelectric	3993875624
0065	Smoke Detector	1st Room 9 Conference Room	Photoelectric	3993870018
0066	Smoke Detector	1st Room 26 Staff Bathroom	Photoelectric	3993871930
0067	Smoke Detector	Hall by rm 8 Vice Principal	Photoelectric	3993870308
0068	Smoke Detector	1st Room 8 Vice Principal	Photoelectric	3993871213
0069	Smoke Detector	1st Room 7B Work Room	Photoelectric	3993872005
0070	Smoke Detector	1st Rm 7 Office	Photoelectric	3993870285
0076	Heat Detector	Above ceiling Hall by 105		3603235084
0083	Smoke Detector	Room 109 HNDPC Bathroom	Photoelectric	42626412
0085	Duct Detector	1st AHU A-3 Hall Upper M.P.R.		42626370
0086	Duct Detector	1st AHU 1 Upper M.P.R.		42626371
0138	Beam Detector	1st M.P.R. 3 Front		42626381
0139	Beam Detector	1st M.P.R. 3 Rear		42626380
0142	Waterflow Switch	1st In Storage Room 6		42626408
0143	Tamper Switch	1st In Storage Room 6		42626406
0251	Smoke Detector	Room 112 Front	Photoelectric	3993875044
0252	Smoke Detector	Room 112 Center	Photoelectric	3993873156
0253	Smoke Detector	Room 112 Rear	Photoelectric	3993870605
0254	Smoke Detector	Room 110 Front	Photoelectric	3993878137
0255	Smoke Detector	Room 110 Center	Photoelectric	3993874528
0256	Smoke Detector	Room 110 Rear	Photoelectric	3993877703
0257	Smoke Detector	Storage Room Across From Room 110	Photoelectric	3993873613
0258	Smoke Detector	Room 109 Front	Photoelectric	3993874221
0259	Smoke Detector	Room 109 Mid. Front	Photoelectric	3993870292
0260	Smoke Detector	Room 109 Center	Photoelectric	3993873897
0261	Smoke Detector	Room 109 Mid. Rear	Photoelectric	3993875822
0262	Smoke Detector	Room 109 Rear	Photoelectric	3993873644
0263	Smoke Detector	Hall by rm 114	Photoelectric	3993875440
0264	Smoke Detector	Room 114 Front	Photoelectric	3993874559
0265	Smoke Detector	Room 114 Center	Photoelectric	3993859778

0266	Smoke Detector	Room 114 Rear	Photoelectric	3993870841
0267	Smoke Detector	Room 113 Front	Photoelectric	3993871770
0268	Smoke Detector	Room 113 Center	Photoelectric	3993870025
0269	Smoke Detector	Room 113 Rear	Photoelectric	3993871688
0270	Smoke Detector	Room 111 Front	Photoelectric	3993872548
0271	Smoke Detector	Room 111 Center	Photoelectric	3993875075
0272	Smoke Detector	Room 111 Rear	Photoelectric	3993876966
0273	Smoke Detector	Hall by rm 112	Photoelectric	3993870483
0274	Smoke Detector	Hall by rm 118	Photoelectric	3993871220
0275	Smoke Detector	Room 118 Front	Photoelectric	3993870353
0276	Smoke Detector	Room 118 Center	Photoelectric	3993870452
0277	Smoke Detector	Room 118 Rear	Photoelectric	3993874726
0278	Smoke Detector	Room 115 Front	Photoelectric	3993878052
0279	Smoke Detector	Room 115 Center	Photoelectric	3993874986
0280	Smoke Detector	Room 115 Rear	Photoelectric	3993860156
0281	Smoke Detector	Room 116 Front	Photoelectric	3993870155
0282	Smoke Detector	Room 116 Center	Photoelectric	3993877956
0283	Smoke Detector	Room 116 Rear	Photoelectric	3993874948
0284	Smoke Detector	Room 119 Front	Photoelectric	3993860187
0285	Smoke Detector	Room 119 Center	Photoelectric	3993858931
0286	Smoke Detector	Room 119 Rear	Photoelectric	3993871909
0287	Smoke Detector	Hall By Rm 120	Photoelectric	3993870087
0288	Smoke Detector	Room 120 Front	Photoelectric	3993874900
0289	Smoke Detector	Room 120 Center	Photoelectric	3993873903
0290	Smoke Detector	Room 120 Rear	Photoelectric	3993870278
0291	Smoke Detector	Room 117 Front	Photoelectric	3993871978
0292	Smoke Detector	Room 117 Center	Photoelectric	3993874269
0293	Smoke Detector	Room 117 Rear	Photoelectric	3993872555
0294	Smoke Detector	Sprinkler Room 11	Photoelectric	3993870438
0295	Smoke Detector	Storage Room 12	Photoelectric	3993871015
0296	Smoke Detector	Hall by bathroom 29	Photoelectric	3993874917
0297	Smoke Detector	Hall stair by handicap lift	Photoelectric	3993869999
0298	Smoke Detector	Upper Handicap Lift Area	Photoelectric	3993878663
0299	Smoke Detector	Room 121 Front	Photoelectric	3993870179
0300	Smoke Detector	Room 121 Center	Photoelectric	3993873071
0301	Smoke Detector	Room 121 Rear	Photoelectric	3993878656
0302	Smoke Detector	Room 122 Front	Photoelectric	3993874634
0303	Smoke Detector	Room 122 Center	Photoelectric	3993860118
0304	Smoke Detector	Room 122 Rear	Photoelectric	3993874764
0305	Smoke Detector	Room 13 Center Right	Photoelectric	3993860149
0306	Smoke Detector	Room 13 Center Left	Photoelectric	3993871367
0307	Smoke Detector	Room 13 Left	Photoelectric	3993860279
0308	Smoke Detector	Room 13 Far Left	Photoelectric	3993871541
0309	Smoke Detector	Men's Room 30 Right	Photoelectric	3993869920
0315	Smoke Detector	Room 123 Right	Photoelectric	3993878670
0316	Smoke Detector	Room 123 Center Right	Photoelectric	3993869784
0317	Smoke Detector	Room 123 Center Left	Photoelectric	3993871169
0318	Smoke Detector	Room 123 Left	Photoelectric	3993875082
0319	Smoke Detector	Girl's Lav. Right By Rm 126	Photoelectric	3993871077
0320	Smoke Detector	Girl's Lav. Left By Rm 126	Photoelectric	3993875532
0321	Smoke Detector	Boy's Lav Right By Rm 129	Photoelectric	3993870582
0322	Smoke Detector	Boy's Lav. Left By Rm 129	Photoelectric	3993870414
0323	Smoke Detector	Custodians Closet 16 Right	Photoelectric	3993878649

0324	Smoke Detector	Custodians Closet 16 CTR Right	Photoelectric	3993872524
0325	Smoke Detector	Custodians Closet 16 CTR Left	Photoelectric	3993874719
0326	Smoke Detector	Custodians Closet 16 Left	Photoelectric	3993870735
0327	Smoke Detector	Room 126 Right	Photoelectric	3993871374
0328	Smoke Detector	Room 126 Center Right	Photoelectric	3993875495
0329	Smoke Detector	Room 126 Center Left	Photoelectric	3993870919
0330	Smoke Detector	Room 126 Left	Photoelectric	3993859785
0331	Smoke Detector	Room 15 Right	Photoelectric	3993875099
0332	Smoke Detector	Room 15 Center	Photoelectric	3993871282
0333	Smoke Detector	Room 15 Left	Photoelectric	3993874832
0334	Smoke Detector	Room 13 Far Right	Photoelectric	3993870810
0335	Smoke Detector	Room 13 Right	Photoelectric	3993873118
0336	Smoke Detector	Room 135	Photoelectric	3993873842
0337	Smoke Detector	Room 17	Photoelectric	3993870124
0338	Smoke Detector	Room 133 Right	Photoelectric	3993875419
0339	Smoke Detector	Room 133 Center Right	Photoelectric	3993875488
0340	Smoke Detector	Room 133 Left	Photoelectric	3993871435
0341	Smoke Detector	Room 133 Center Left	Photoelectric	3993874252
0342	Smoke Detector	Room 131 Right	Photoelectric	3993874696
0343	Smoke Detector	Room 131 Center Right	Photoelectric	3993873125
0344	Smoke Detector	Room 131 Left	Photoelectric	3993871732
0345	Smoke Detector	Room 131 Center Left	Photoelectric	3993874887
0346	Smoke Detector	Room 129 Right	Photoelectric	3993874757
0347	Smoke Detector	Room 129 Center Right	Photoelectric	3993870445
0348	Smoke Detector	Room 129 Left	Photoelectric	3993871466
0349	Smoke Detector	Room 129 Center Left	Photoelectric	3993869944
0350	Heat Detector	Above ceiling In room 112		3603236920
0351	Heat Detector	Above ceiling In room 110		3603233707
0352	Heat Detector	Above ceiling Hall by room 114		3603232052
0353	Heat Detector	Above ceiling In room 114		3603230195
0354	Heat Detector	Above ceiling In room 113		3603230676
0355	Heat Detector	Above ceiling In room 111		3603230720
0356	Heat Detector	Above ceiling Hall by room 112		3603229182
0357	Heat Detector	Above ceiling Hall by room 118		3603229229
0358	Heat Detector	Above ceiling In room 118		3603233431
0359	Heat Detector	Above ceiling In room 115		3603232366
0360	Heat Detector	Above ceiling In room 116		3603237002
0361	Heat Detector	Above ceiling In room 122		3603233639
0362	Heat Detector	Above ceiling In room 119		3603233660
0363	Heat Detector	Above ceiling Hall by room 120		3603233035
0364	Heat Detector	Above ceiling In room 120		3603231482
0365	Heat Detector	Above ceiling In room 117		3603228635
0366	Heat Detector	A/C sprinkler rm 11	Rate-of-Rise	3603232021
0367	Heat Detector	A/C storage rm 12	Rate-of-Rise	3603232014
0370	Heat Detector	Above ceiling In room 121		3603230331
0371	Heat Detector	A/C Rm 135	Rate-of-Rise	3603232090
0372	Heat Detector	A/C Rm 17	Rate-of-Rise	3603233554
0373	Smoke Detector	Lower Handicap Lift Area	Photoelectric	3993874979
0374	Duct Detector	1st AHU-A4 Art Storage Room 12	Photoelectric	42626369
0375	Smoke Detector	Women's Room 29 Left Front	Photoelectric	3993875662
0377	Waterflow Switch	1st In Room 11 Inside Room 123		42626400
0378	Tamper Switch	1st In Room 11 Inside Room 123		42626399
126	Pull Station	1st In Hallway Next to Exit Door By Gym	Dual Action	42626332

		on Caring Street		
135	Pull Station	1st In Hallway Next to Exit Door By Room 101	Dual Action	42626333
367	Pull Station	1st In Hallway Next to Exit Door By Room 122/ Handicap Lift	Dual Action	42626331
<b>Zone/Circuit: 2</b>				
127	Pull Station	1st In Room 109	Dual Action	42626365
128	Pull Station	1st In Lobby By Sprinkler Room 6	Dual Action	42626337
129	Pull Station	1st In Storage Room 6	Dual Action	42626360
130	Pull Station	1st In Gym On Caring Street Left Side	Dual Action	42626336
131	Pull Station	1st In Gym On Caring Street Left Side	Dual Action	42626335
133	Pull Station	1st In M.P.R. Storage Room Exit	Dual Action	42626366
134	Pull Station	1st In In Boiler Room 2	Dual Action	42626361

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
	Heat Detector	cafe under stage right	Rate-of-Rise	3603234810
0001	Smoke Detector	Room 134 Center Right	Photoelectric	3993875013
0002	Smoke Detector	Room 134 Right	Photoelectric	3993871534
0003	Smoke Detector	Room 134 Center Left	Photoelectric	3993878700
0004	Smoke Detector	Room 134 Left	Photoelectric	3993871145
0005	Smoke Detector	Hall by rm 136	Photoelectric	3993870629
0006	Smoke Detector	Room 18	Photoelectric	3993870193
0007	Smoke Detector	Room 136	Photoelectric	3993874290
0008	Smoke Detector	Stage Right Cafetorium	Photoelectric	3993870322
0009	Smoke Detector	Stage Center Cafetorium	Photoelectric	3993875501
0010	Smoke Detector	Stage Left Cafetorium	Photoelectric	3993875549
0011	Smoke Detector	Small Hall between rms 128 & 130	Photoelectric	3993870261
0012	Smoke Detector	Hall by rm 130	Photoelectric	3993870070
0013	Smoke Detector	Room 130 Right	Photoelectric	3993858955
0014	Smoke Detector	Room 130 Center Right	Photoelectric	3993859853
0015	Smoke Detector	Room 130 Left	Photoelectric	3993869913
0016	Smoke Detector	Room 130 Center Left	Photoelectric	3993875594
0017	Smoke Detector	Room 132 Center Right	Photoelectric	3993872173
0018	Smoke Detector	Room 132 Right	Photoelectric	3993874894
0019	Smoke Detector	Room 132 Center Left	Photoelectric	3993871473
0020	Smoke Detector	Room 132 Left	Photoelectric	3993870230
0021	Smoke Detector	Hall by rm 134	Photoelectric	3993875709
0022	Smoke Detector	Room 125 Center Left	Photoelectric	3993875655
0023	Smoke Detector	Room 125 Left	Photoelectric	3993874870
0024	Smoke Detector	Room 125 Far Left	Photoelectric	3993870513
0025	Smoke Detector	Hallway Across From Room 15	Photoelectric	3993860026
0026	Smoke Detector	Hall by rm 127	Photoelectric	3993874924
0027	Smoke Detector	Room 127 Center Right	Photoelectric	3993875310
0028	Smoke Detector	Room 127 Right	Photoelectric	3993874573
0029	Smoke Detector	Room 127 Center Left	Photoelectric	3993874733
0030	Smoke Detector	Room 127 Left	Photoelectric	3993873064
0031	Smoke Detector	Hall by rm 128	Photoelectric	3993874238
0032	Smoke Detector	Room 128 Right	Photoelectric	3993859945
0033	Smoke Detector	Room 128 Center Right	Photoelectric	3993870575
0034	Smoke Detector	Room 128 Left	Photoelectric	3993871190
0035	Smoke Detector	Room 128 Center Left	Photoelectric	3993870551
0036	Smoke Detector	Hall by rm 124	Photoelectric	3993986894
0037	Smoke Detector	Room 124 Kilm Closet	Photoelectric	3993980052
0038	Smoke Detector	Room 124 Far Left	Photoelectric	3993874597
0039	Smoke Detector	Room 124 Left	Photoelectric	3993874214
0040	Smoke Detector	Room 124 Center Left	Photoelectric	3993986320
0041	Smoke Detector	Room 124 Center Right	Photoelectric	3993870377
0042	Smoke Detector	Room 124 Right	Photoelectric	3993875051
0043	Smoke Detector	Room 124 Far Right	Photoelectric	3993979728
0044	Smoke Detector	Hall by Nurse's Office	Photoelectric	3993980908

0045	Smoke Detector	Hall by rm 125	Photoelectric	3993870131
0046	Smoke Detector	Room 125 Far Right	Photoelectric	3993871244
0047	Smoke Detector	Room 125 Right	Photoelectric	3993875280
0048	Smoke Detector	Room 125 Center Right	Photoelectric	3993874283
0049	Duct Detector	1st Faculty Room		42626375
0050	Duct Detector	1st AHU B2 RET. Faculty Room		42626376
0052	Heat Detector	cafe under stage far left	Rate-of-Rise	3603233882
0053	Heat Detector	cafe under stage left	Rate-of-Rise	3603232946
0054	Heat Detector	cafe under stage center left	Rate-of-Rise	3603236975
0055	Heat Detector	cafe under stage center right	Rate-of-Rise	3603230249
0055	Heat Detector	cafe under stage right	Rate-of-Rise	3603229496
0059	Heat Detector	A/C Rm 18	Rate-of-Rise	3603231918
0060	Heat Detector	A/C Rm 136	Rate-of-Rise	3603236418
0079	Heat Detector	A/C hall by faculty rm	Rate-of-Rise	3603233226
0085	Smoke Detector	Kitchen Break room	Photoelectric	3993859815
0086	Smoke Detector	Cafe Left Front	Photoelectric	3993859969
0087	Smoke Detector	Kitchen Locker Rm	Photoelectric	3993859976
0088	Smoke Detector	Kitchen storage	Photoelectric	3993869777
0089	Smoke Detector	Cafe Right Front	Photoelectric	3993870063
0090	Smoke Detector	Kitchen Office	Photoelectric	3993870537
0091	Smoke Detector	Kitchen Custodial Closet	Photoelectric	3993870612
0092	Smoke Detector	Cafe Rear left	Photoelectric	3993870667
0093	Smoke Detector	Faculty Room	Photoelectric	3993871428
0094	Smoke Detector	Cafe Middle Right	Photoelectric	3993871923
0095	Smoke Detector	Kitchen Lav	Photoelectric	3993873620
0096	Smoke Detector	Cafe Middle Center	Photoelectric	3993873682
0097	Smoke Detector	Cafe Rear right	Photoelectric	3993873804
0098	Smoke Detector	Hall by courtyard near stage	Photoelectric	3993875136
0099	Smoke Detector	Cafe Middle Left	Photoelectric	3993875358
0100	Smoke Detector	Cafe Center Front	Photoelectric	3993875860
0101	Smoke Detector	Hall by faculty rm	Photoelectric	3993877345
0102	Smoke Detector	Cafe Rear center	Photoelectric	3993878151
0103	Smoke Detector	Faculty Lav 40	Photoelectric	3994221673
0134	Pull Station	1st Kitchen Exit	Dual Action	42626341
0136	Pull Station	1st Rear Stage Exit	Dual Action	42626343
0137	Pull Station	1st Cafe Rear Exit	Dual Action	42626342
0251	Smoke Detector	Media Center Front Desk Area	Photoelectric	3993859983
0252	Smoke Detector	Media Center by Entrance	Photoelectric	3993869739
0254	Smoke Detector	Media Center Table Area 1	Photoelectric	3993874658
0255	Smoke Detector	Media Center Alcove	Photoelectric	3993871954
0256	Smoke Detector	Media Center Over Books	Photoelectric	3993870094
0257	Smoke Detector	Media Center Table Area 2	Photoelectric	3993870698
0258	Smoke Detector	Nurses Room 47 Bathroom	Photoelectric	3993874054
0259	Smoke Detector	Nurses Office Exam Room 1	Photoelectric	3993980168
0260	Smoke Detector	Nurses Office Exam Room 2	Photoelectric	3993980007
0261	Smoke Detector	Media Center Conference rm	Photoelectric	3993875143
0262	Smoke Detector	Media Center Computer Area	Photoelectric	3993874030
0263	Smoke Detector	Media Center Office 58	Photoelectric	3993874498
0264	Smoke Detector	Media Center Office 59	Photoelectric	3993869982
0265	Smoke Detector	Supply Room 50	Photoelectric	3993875570
0266	Smoke Detector	Hall by supply room 50	Photoelectric	3993860033
0267	Smoke Detector	Hall by Computer Lab 137	Photoelectric	3993986313
0268	Smoke Detector	Stage Hall Door 42	Photoelectric	3993981295

0269	Smoke Detector	Rm 137 Computer Lab Front	Photoelectric	3993986856
0270	Smoke Detector	Rm 137 Computer Lab Rear	Photoelectric	3993979872
0272	Smoke Detector	Nurses Room 47	Photoelectric	3993874641
0273	Smoke Detector	Main lobby front	Photoelectric	3993859938
0274	Smoke Detector	Main lobby rear	Photoelectric	3993980892
0275	Smoke Detector	Hall by girls bathroom 54	Photoelectric	3993979957
0276	Smoke Detector	Girls Bathroom 54	Photoelectric	3993874245
0277	Smoke Detector	Boys Bathroom 53	Photoelectric	3993986344
0278	Smoke Detector	Hall By Boy's Bathroom 53	Photoelectric	3993869753
0279	Smoke Detector	Custodian Closet 52	Photoelectric	3993870001
0280	Smoke Detector	Custodians office 51	Photoelectric	3993980960
0281	Smoke Detector	Main Office Kitchen	Photoelectric	3993979988
0282	Smoke Detector	Room 72 Principals Office	Photoelectric	3993979834
0283	Smoke Detector	Room 71 Asst Principals Off	Photoelectric	3993981271
0284	Smoke Detector	Main Office Bathroom	Photoelectric	3993860019
0285	Smoke Detector	Hall by main office	Photoelectric	3993986757
0286	Smoke Detector	Main entrance vestibule right	Photoelectric	3993981462
0287	Smoke Detector	Main Entrance Vestibule Left	Photoelectric	3993980625
0288	Smoke Detector	Main entrance right	Photoelectric	3993875112
0289	Smoke Detector	Main entrance left	Photoelectric	3993980984
0290	Smoke Detector	Hall by conference room 69	Photoelectric	3993875464
0291	Smoke Detector	Room 60	Photoelectric	3993874023
0292	Smoke Detector	Room 66	Photoelectric	3993870490
0293	Smoke Detector	Room 65	Photoelectric	3993860163
0294	Smoke Detector	Room 64	Photoelectric	3993873958
0295	Smoke Detector	Room 63	Photoelectric	3993874191
0296	Smoke Detector	Room 62	Photoelectric	3993981455
0297	Smoke Detector	Main Office	Photoelectric	3993980069
0298	Smoke Detector	Room 69 Conference	Photoelectric	3993979810
0305	Heat Detector	A/C Nurses Rm 47 Lav	Fixed Temperature	3603229311
0306	Heat Detector	A/C Nurses Exam Rm 1	Fixed Temperature	3603228338
0307	Heat Detector	A/C Nurses Exam Rm 2	Fixed Temperature	3603226488
0312	Heat Detector	Supply Rm 50	Rate-of-Rise	3603230751
0314	Heat Detector	A/C comp lab 137 front	Rate-of-Rise	3603226068
0315	Heat Detector	A/C comp lab 137 rear	Rate-of-Rise	3603226396
0317	Heat Detector	A/C Nurses Rm 47	Fixed Temperature	3603229120
0320	Heat Detector	A/C girl's bathroom 54	Rate-of-Rise	3603230324
0321	Heat Detector	A/C boy's bathroom 53	Rate-of-Rise	3603230423
0322	Heat Detector	A/C custodian closet 52	Rate-of-Rise	3603230140
0323	Heat Detector	A/C custodian office 51	Rate-of-Rise	3603229168
0324	Heat Detector	A/C main office kitchen	Rate-of-Rise	3603230775
0325	Heat Detector	A/C principal's office rm 72	Rate-of-Rise	3603231260
0327	Heat Detector	A/C main office bathroom	Rate-of-Rise	3603226495
0330	Heat Detector	A/C Rm 60	Fixed Temperature	3603228741
0331	Heat Detector	A/C Rm 66	Fixed Temperature	3603231215
0332	Heat Detector	A/C Rm 65	Fixed Temperature	3603226211
0333	Heat Detector	A/C Rm 64	Fixed Temperature	3603226013
0334	Heat Detector	A/C Rm 63	Fixed Temperature	3603230997
0335	Heat Detector	A/C Rm 62	Fixed Temperature	3603230096
0336	Heat Detector	A/C Main Office	Fixed Temperature	3603231123
0337	Heat Detector	A/C conference rm 69	Rate-of-Rise	3603225986
0338	Duct Detector	1st Custodians Office Front AHU-5	Photoelectric	42626372
0339	Duct Detector	1st Custodians Office Rear AHU-4	Photoelectric	42626373



0341	Duct Detector	1st Boys Lav. By Cafe AHU-6		42626374
0341	Duct Detector	1st HVAC 11 Main Office		42626377
0342	Duct Detector	1st HVAC 9 Main Office Mail Room		42626378
0343	Duct Detector	1st HVAC B8 Room 62		33369591
0344	Duct Detector	1st HVAC 10 Nurses Office		42626379
0376	Pull Station	1st Main Entrance Lobby	Dual Action	42626347
0377	Pull Station	1st Main Lobby Rear Exit	Dual Action	42626346
0378	Pull Station	1st Cafetorium Exit to Main Lobby	Dual Action	42626345
0381	Pull Station	1st Media Center Front Entrance	Dual Action	42626349
0382	Pull Station	1st Media Center Rear Exit	Dual Action	42626350
126	Pull Station	1st Next to exit door By Room 12 Art Storage		42626330
<b>Zone/Circuit: 2</b>				
127	Pull Station	1st In Hallway By Room 16 Storage	Dual Action	42626338
128	Pull Station	1st In Hallway By Room 135	Dual Action	42626339
133	Pull Station	1st In Cafe By Room 40 Faculty Bathroom	Dual Action	42626363
135	Pull Station	1st In Boiler Room Inside Faculty Dining Room	Dual Action	42626362
138	Pull Station	1st In Hallway By Room 39 Faculty Dining		42626340
379	Pull Station	1st On Stage left	Dual Action	42626344
380	Pull Station	1st In Hallway By Nurses Office	Dual Action	42626359

*The Zone Address Report lists all of the devices and items that have an individual address, or are grouped together under a common zone. The device type, location, and description are included for your reference.*

Address	Device Type	Location	Type	ScanID
<b>Zone/Circuit: 02</b>				
0001	Smoke Detector	Room 158 Left	Photoelectric	33369574
0002	Smoke Detector	Room 156 Center	Photoelectric	3993873262
0003	Smoke Detector	Room 156 Center	Photoelectric	3993872791
0004	Smoke Detector	Room 156 Right	Photoelectric	3993873415
0005	Smoke Detector	Hall by rm 156	Photoelectric	3993872814
0006	Smoke Detector	Room 160 Far Right	Photoelectric	3993874672
0007	Smoke Detector	Room 160 Right	Photoelectric	3993871091
0008	Smoke Detector	Room 160 Center	Photoelectric	3993872821
0009	Smoke Detector	Room 160 Left	Photoelectric	3993875211
0010	Smoke Detector	Room 160 Far Left	Photoelectric	3993872999
0011	Smoke Detector	Room 160 Storage	Photoelectric	3993870049
0012	Smoke Detector	Room 76	Photoelectric	3993870704
0013	Smoke Detector	Room 159 Left	Photoelectric	3993873866
0014	Smoke Detector	Room 159 Center	Photoelectric	3993859952
0015	Smoke Detector	Room 159 Right	Photoelectric	3993870186
0016	Smoke Detector	Room 75	Photoelectric	3993859761
0017	Smoke Detector	Room 75 lav	Photoelectric	3993874306
0018	Smoke Detector	Hall by rm 159	Photoelectric	3993873941
0019	Smoke Detector	Room 158 Right	Photoelectric	3993873828
0020	Smoke Detector	Room 158 Center	Photoelectric	3993874603
0021	Smoke Detector	MPR Office 93 lav	Photoelectric	3993873996
0022	Smoke Detector	MPR Office 93	Photoelectric	3993870636
0023	Smoke Detector	Hall by rm 79	Photoelectric	3993869746
0024	Smoke Detector	Room 79	Photoelectric	3993873132
0025	Smoke Detector	Room 81 Storage	Photoelectric	3993874146
0026	Smoke Detector	Room 78	Photoelectric	3993874689
0027	Smoke Detector	Room 77	Photoelectric	3993870520
0028	Smoke Detector	Hall by rm 160	Photoelectric	3993875235
0029	Smoke Detector	Staff Lav 99F	Photoelectric	3993873934
0030	Smoke Detector	Work Room 82 Lav	Photoelectric	3993877352
0031	Smoke Detector	Work Room 82	Photoelectric	3993872807
0032	Smoke Detector	Hall by MPR	Photoelectric	3993871442
0033	Smoke Detector	Girls Lav 99E	Photoelectric	3993874009
0034	Smoke Detector	Janitors closet room 83	Photoelectric	3993872883
0035	Smoke Detector	Boys Lav 99D	Photoelectric	3993872753
0036	Smoke Detector	Hall by MPR 92	Photoelectric	3993873347
0037	Smoke Detector	MPR Storage rm 96 closet	Photoelectric	3993878717
0038	Smoke Detector	MPR Storage rm 96 left	Photoelectric	3993873040
0039	Smoke Detector	MPR Storage rm 96 right	Photoelectric	3993874160
0040	Smoke Detector	MPR Storage rm 95 left	Photoelectric	3993869951
0041	Smoke Detector	MPR Storage rm 95 right	Photoelectric	3993873798
0042	Smoke Detector	Room 163 Far Left	Photoelectric	3993873002
0043	Smoke Detector	Room 163 Center Left	Photoelectric	3993874153
0044	Smoke Detector	Room 163 Center Right	Photoelectric	3993873019
0045	Smoke Detector	Room 163 Far Right	Photoelectric	3993874184

0046	Smoke Detector	MPR Stage Far Left	Photoelectric	3993875266
0047	Smoke Detector	MPR Stage Center Left	Photoelectric	3993874368
0048	Smoke Detector	MPR Stage Center	Photoelectric	3993873361
0049	Smoke Detector	MPR Stage Center Right	Photoelectric	3993873989
0050	Smoke Detector	MPR Stage Far Right	Photoelectric	3993874771
0051	Smoke Detector	Room 85 Left	Photoelectric	3993870384
0052	Smoke Detector	Room 85 Right	Photoelectric	3993873088
0053	Smoke Detector	Hall by rm 84	Photoelectric	3993874566
0054	Smoke Detector	Room 84	Photoelectric	3993873422
0055	Smoke Detector	Room 161 Center	Photoelectric	3993873781
0056	Smoke Detector	Room 161 Left	Photoelectric	3993860231
0057	Smoke Detector	Room 161 Right	Photoelectric	3993873460
0058	Smoke Detector	Room 164 Far Right	Photoelectric	3993874863
0059	Smoke Detector	Room 164 Center Right	Photoelectric	3993878694
0060	Smoke Detector	Room 164 Center	Photoelectric	3993875242
0061	Smoke Detector	Room 164 Center Left	Photoelectric	3993874399
0062	Smoke Detector	Room 164 Far Left	Photoelectric	3993874405
0063	Smoke Detector	Music Office 86	Photoelectric	3993871527
0064	Smoke Detector	Practice Room 87 A	Photoelectric	3993878366
0065	Smoke Detector	Practice Room 88 B	Photoelectric	3993860224
0066	Smoke Detector	Hall by boiler rm	Photoelectric	3993872784
0067	Smoke Detector	Receiving room 90 right	Photoelectric	3993878748
0068	Smoke Detector	Receiving room 90 left	Photoelectric	3993870469
0069	Smoke Detector	Room 162 Far Left	Photoelectric	3993874481
0070	Smoke Detector	Room 162 Center Left	Photoelectric	3993874702
0071	Smoke Detector	Room 162 Center	Photoelectric	3993875259
0072	Smoke Detector	Room 162 Center Right	Photoelectric	3993873491
0073	Smoke Detector	Room 162 Far Right	Photoelectric	3993873569
0074	Smoke Detector	Hall by rm 162	Photoelectric	3993873750
0082	Heat Detector	A/C Rm 79	Fixed Temperature	3603225900
0083	Heat Detector	A/C Rm 78	Fixed Temperature	3603228390
0084	Heat Detector	A/C Rm 77	Fixed Temperature	3603226099
0097	Duct Detector	1st MPR Back Stage		33369589
0098	Duct Detector	1st MPR Storage Room 95		33369588
0099	Duct Detector	1st Music Room Office		33369590
0126	Pull Station	1st Room 164 Exit	Dual Action	42626368
0127	Pull Station	1st Hall Exit By Room 164	Dual Action	42626353
0128	Pull Station	1st Boiler Room Exit	Dual Action	42626357
0129	Pull Station	1st Receiving Room 90	Dual Action	42626364
0130	Pull Station	1st Room 162 Exit	Dual Action	42626367
0131	Pull Station	1st Hall Exit By M.P.R.	Dual Action	42626352
0132	Pull Station	1st M.P.R. Rm Exit By Stage	Dual Action	42626354
0133	Pull Station	1st M.P.R. Storage Room 96 Exit	Dual Action	42626358
0134	Beam Detector	1st M.P.R. Front		42626382
0135	Beam Detector	1st M.P.R. Rear		42626383
0251	Smoke Detector	Room 140 Center	Photoelectric	3993873712
0252	Smoke Detector	Room 140 Right	Photoelectric	3993875150
0253	Smoke Detector	Hall by rm 138	Photoelectric	3993874740
0254	Smoke Detector	Room 138	Photoelectric	3993874047
0255	Smoke Detector	Room 138 lav	Photoelectric	3993870643
0256	Smoke Detector	Room 139	Photoelectric	3993874115
0257	Smoke Detector	Room 139 Bathroom	Photoelectric	3993870681
0258	Smoke Detector	Room 143 Center	Photoelectric	3993875181

0259	Smoke Detector	Room 143 Right	Photoelectric	3993875198
0260	Smoke Detector	Room 142 Right	Photoelectric	3993873910
0261	Smoke Detector	Room 142 Center	Photoelectric	3993870780
0262	Smoke Detector	Room 142 Left	Photoelectric	3993872777
0263	Smoke Detector	Room 141 Right	Photoelectric	3993874207
0264	Smoke Detector	Room 141 Center	Photoelectric	3993873545
0265	Smoke Detector	Room 141 Left	Photoelectric	3993874061
0266	Smoke Detector	Hall by rm 140	Photoelectric	3993871176
0267	Smoke Detector	Room 140 Left	Photoelectric	3993873835
0268	Smoke Detector	Room 146 Right	Photoelectric	3993873279
0269	Smoke Detector	Room 146 Far Right	Photoelectric	3993874122
0270	Smoke Detector	Room 145 Left	Photoelectric	3993873538
0271	Smoke Detector	Room 145 Center	Photoelectric	3993871022
0272	Smoke Detector	Room 145 Right	Photoelectric	3993875204
0273	Smoke Detector	Hall by rm 144	Photoelectric	3993873972
0274	Smoke Detector	Room 144 Left	Photoelectric	3993874542
0275	Smoke Detector	Room 144 Center	Photoelectric	3993870896
0276	Smoke Detector	Room 144 Right	Photoelectric	3993874092
0277	Smoke Detector	Room 143 Left	Photoelectric	3993870339
0278	Smoke Detector	Room 149 Left	Photoelectric	3993873767
0279	Smoke Detector	Room 149 Right	Photoelectric	3993873743
0280	Smoke Detector	Room 149 Center	Photoelectric	3993875396
0281	Smoke Detector	Hall by rm 149	Photoelectric	3993874177
0282	Smoke Detector	Room 147 Center	Photoelectric	3993875433
0283	Smoke Detector	Room 147 Left	Photoelectric	3993872869
0284	Smoke Detector	Room 147 Right	Photoelectric	3993870865
0285	Smoke Detector	Room 146 Far Left	Photoelectric	3993873293
0286	Smoke Detector	Room 146 Left	Photoelectric	3993870650
0287	Smoke Detector	Room 146 Center	Photoelectric	3993875471
0288	Smoke Detector	Room 150 Right	Photoelectric	3993870674
0289	Smoke Detector	Room 150 Center	Photoelectric	3993873286
0290	Smoke Detector	Room 150 Left	Photoelectric	3993874535
0291	Smoke Detector	Room 148 Far Right	Photoelectric	3993873477
0292	Smoke Detector	Storage Room between 148 & 146	Photoelectric	3993870506
0293	Smoke Detector	Room 148 Right	Photoelectric	3993873873
0294	Smoke Detector	Room 148 Center	Photoelectric	3993873187
0295	Smoke Detector	Room 148 Far Left	Photoelectric	3993859822
0296	Smoke Detector	Room 148 Left	Photoelectric	3993873552
0297	Smoke Detector	Hall by rm 150	Photoelectric	3993875105
0298	Smoke Detector	Storage Room 99H	Photoelectric	3993872968
0299	Smoke Detector	Room 153 Left	Photoelectric	3993874474
0300	Smoke Detector	Room 153 Center	Photoelectric	3993873927
0301	Smoke Detector	Room 153 Right	Photoelectric	3993875167
0302	Smoke Detector	Boys Lav by Room 152	Photoelectric	3993873859
0303	Smoke Detector	Room 151 Right	Photoelectric	3993873811
0304	Smoke Detector	Room 151 Center	Photoelectric	3993872593
0305	Smoke Detector	Room 151 Left	Photoelectric	3993875730
0306	Smoke Detector	Custodian closet by Room 151	Photoelectric	3993871725
0307	Smoke Detector	Storage rm 74 right by rm 150	Photoelectric	3993875648
0308	Smoke Detector	Storage rm 74 left by rm 150	Photoelectric	3993873446
0309	Smoke Detector	Girls lav by rm 150	Photoelectric	3993870216
0310	Smoke Detector	Hall by rm 151	Photoelectric	3993873514
0311	Smoke Detector	Closet in storage 74	Photoelectric	3993874085

0312	Smoke Detector	Room 155 Left	Photoelectric	3993873408
0313	Smoke Detector	Room 155 Center	Photoelectric	3993871121
0314	Smoke Detector	Room 155 Right	Photoelectric	3993869975
0315	Smoke Detector	Room 157 Right	Photoelectric	3993874504
0316	Smoke Detector	Room 157 Center	Photoelectric	3993873521
0317	Smoke Detector	Room 157 Left	Photoelectric	3993873392
0318	Smoke Detector	Room 154 Right	Photoelectric	3993875174
0319	Smoke Detector	Room 154 Center	Photoelectric	3993872944
0320	Smoke Detector	Room 154 Left	Photoelectric	3993872906
0322	Smoke Detector	Room 152 Center	Photoelectric	3993872838
0323	Smoke Detector	Room 152 Right	Photoelectric	3993873200
0324	Smoke Detector	Hall by rm 152	Photoelectric	3993872890
0376	Pull Station	1st Hall Exit By Rm 151	Dual Action	42626351
0377	Pull Station	1st Hall Exit By Rm 139	Dual Action	42626356

# Fire Alarm and Life Safety System Inspection Certificate

*For*

Montgomery Transportation/Bus  
Garage  
375 Burnt Hill Rd  
Skillman, NJ 08558

Tested to NFPA 72 Standards

*This Inspection was performed in accordance with applicable NFPA Standards. The subsequent pages of this report provide performance measurements, listed ranges of acceptable results, and complete documentation of the inspection. Whenever discrepancies exist between acceptable performance standards and actual test results, notes and/or recommended solutions have been proposed or provided for immediate review and approval.*

*Inspection Date*  
*Oct 11, 2018*

Building: Montgomery Transportation/Bus Garage  
Contact: Dave Klein  
Title: B&G Mgr.

Company: Alarm & Communication Technologies  
Contact: Robert Kilcher  
Title: Inspector

# Executive Summary

Generated by: BuildingReports.com





Building Information		
<b>Building:</b> Montgomery Transportation/Bus Garage	<b>Contact:</b> Dave Klein	
<b>Address:</b> 375 Burnt Hill Rd	<b>Phone:</b> 609-466-7601	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Skillman, NJ 08558	<b>Mobile:</b>	
<b>Country:</b> United States of America	<b>Email:</b>	
Inspection Performed By		
<b>Company:</b> Alarm & Communication Technologies	<b>Inspector:</b> Robert Kilcher	
<b>Address:</b> 25 Ross Street	<b>Phone:</b> 2018416983	
<b>Address:</b>	<b>Fax:</b>	
<b>City/State/Zip:</b> Wharton, NJ 07885	<b>Mobile:</b> 2018416983	
<b>Country:</b> United States of America	<b>Email:</b> RobertK@njact.com	
System Control Unit		
<b>Manufacturer:</b> Ademco	<b>Inspection Date:</b> 10/11/2018	<b>IDC Style:</b> B
<b>Model Number:</b> vista 100	<b>Install Date:</b> 08/29/2016	<b>SLC Style:</b>
<b>Software Version:</b>	<b>Version Date:</b> 08/29/2016	<b>NAC Style:</b> Y
<b>Location:</b> Boiler rm	<b>Current Protection:</b> Breaker	
Monitoring		
<b>Company:</b>	<b>Phone:</b>	<b>Account #:</b>
Central Station Signal Verification		
<b>Type:</b>	<b>Mfg:</b>	<b>Model #:</b>
<b>Test Time/Date:</b>	<b>Restore Time</b>	

Inspection Summary								
Category	Total Items		Serviced		Passed		Failed/Other	
	Qty	%	Qty	%	Qty	%	Qty	%
Control	2	10.53%	2	100.00%	1	50.00%	1	50.00%
Initiating	14	73.68%	7	50.00%	4	57.14%	3	42.86%
Indicating	3	15.79%	3	100.00%	2	66.67%	1	33.33%
<b>Totals</b>	<b>19</b>	<b>100%</b>	<b>12</b>	<b>63.16%</b>	<b>7</b>	<b>58.33%</b>	<b>5</b>	<b>41.67%</b>
Certification								
Company: Alarm & Communication Technologies				Building: Montgomery Transportation/Bus Garage				
Inspector: Robert Kilcher				Contact: Dave Klein				
Signed:				Signed:				



# Discrepancy Report

Generated by: BuildingReports.com

Building: Montgomery Transportation/Bus Garage		Control Panel: 1 - Ademco vista 100		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
Device Type	Manufacturer	ModelNumber	Date	Qty
<b>Items listed for Recall by Manufacturer</b>				
No recalled items found during this inspection.				
 ScanID	 Location	 Problem	Address	 Reference
<b>Indicating</b>				
<b>Horn/Strobe</b>				
33369384	Transportation dispatch trailer	Failed Test	1	NFPA72 14.2.2.2.2
<b>Initiating</b>				
<b>Pull Station</b>				
33369381	Transportation dispatch trailer	Failed Test	1	NFPA72 14.2.2.2.2
<b>Smoke Detector</b>				
33369383	Transportation dispatch trailer	Failed Test	1	NFPA72 14.2.2.2.2
33369382	Transportation dispatch trailer office	Failed Test	1	NFPA72 14.2.2.2.2
<b>Code References</b>				
NFPA72 14.2.2.2.2	System deficiencies shall be corrected.			

Building: Montgomery Transportation/Bus Garage		Control Panel: 2		
<p><i>The Discrepancy Report consolidates each discrepancy listed within the various Testing sections of your Inspection. Discrepancies are listed by Category, and grouped by device type. The description of the problem is provided and where appropriate, code references are listed for your convenience. Any item that was inspected that is listed on the Consumer Product Safety Commission's website and is subject to a recall by the manufacturer is included.</i></p>				
<b>Device Type</b>	<b>Manufacturer</b>	<b>ModelNumber</b>	<b>Date</b>	<b>Qty</b>
<b><i>Items listed for Recall by Manufacturer</i></b>				
No recalled items found during this inspection.				
<b>ScanID</b>	<b>Location</b>	<b>Problem</b>	<b>Address</b>	<b>Reference</b>
<b><i>Control</i></b>				
<b>Battery</b>				
33369372	Boiler rm	Date Expired	2	NFPA72 Table 14.4.3.2 (9a)(1)
<b><i>Code References</i></b>				
NFPA72 Table 14.4.3.2 (9a)(1)	Batteries shall be replaced in accordance with the recommendations of the alarm equipment manufacturer or when the recharged battery voltage or current falls below the manufacturer's recommendations			

# Proposed Solutions Report

Generated by: BuildingReports.com

Building: Montgomery Transportation/Bus Garage	Control Panel: 1 - Ademco vista 100
--	-------------------------------------

*The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.*

ScanID	Location	Solution	Model #	Cost	Fix
<b>Indicating</b>					
<b>Horn/Strobe</b>					
33369384	Transportation dispatch trailer	Investigate		T/M	<input type="checkbox"/>
<b>Initiating</b>					
<b>Pull Station</b>					
33369381	Transportation dispatch trailer	Investigate	270-SPO	T/M	<input type="checkbox"/>
<b>Smoke Detector</b>					
33369383	Transportation dispatch trailer	Investigate		T/M	<input type="checkbox"/>
33369382	Transportation dispatch trailer office	Investigate		T/M	<input type="checkbox"/>

Building: Montgomery Transportation/Bus Garage	Control Panel: 2
--	------------------

*The Proposed Solution Report provides a solution for each discrepancy listed on the Discrepancy Report. Provide a check mark where indicated to approve repairs listed within the report. Items listed as T/M are available for repair on a Time and Materials basis.*

ScanID	Location	Solution	Model #	Cost	Fix
<b>Control</b>					
<b>Battery</b>					
33369372	Boiler rm	Replace	vista 100	T/M	<input type="checkbox"/>
			PO #: (none)	T/M	

# *Notes & Recommendations*

Generated by: *BuildingReports.com*

## **Building: Montgomery Transportation/Bus Garage**

*The Notes & Recommendations Report details additional inspection notes made by the Inspectors during the course of the building inspection. Notes are grouped by Category.*

### ***General Note***

All initiating devices in trailer failed when tested. Send tech out to troubleshoot.

# Inspection & Testing

Generated by: BuildingReports.com

Device Type	Location	Service	Time	Date
<b>Building: Montgomery Transportation/Bus Garage</b>		<b>Control Panel: 1 - Ademco vista 100</b>		
<p><i>The Inspection &amp; Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time &amp; date at which testing occurred.</i></p>				
<b><i>Passed</i></b>				
<b>Control</b>				
Control Panel	Boiler rm	Tested	3:07:09 PM	10/11/2018
<b>Indicating</b>				
Horn/Strobe	Center bay	Tested	3:06:50 PM	10/11/2018
Horn/Strobe	North bay	Tested	3:06:54 PM	10/11/2018
<b>Initiating</b>				
Heat Detector	Parts storage	Tested	2:56:55 PM	10/11/2018
Pull Station	Center garage door	Tested	2:39:32 PM	10/11/2018
Pull Station	North east exit	Tested	2:37:42 PM	10/11/2018
Pull Station	South east exit	Tested	2:38:32 PM	10/11/2018
<b><i>Failed/Other</i></b>				
<b>Indicating</b>				
Horn/Strobe	Transportation dispatch trailer	Tested	3:06:44 PM	10/11/2018
<b>Initiating</b>				
Pull Station	Transportation dispatch trailer	Tested	2:50:04 PM	10/11/2018
Smoke Detector	Transportation dispatch trailer	Tested	2:50:42 PM	10/11/2018
Smoke Detector	Transportation dispatch trailer office	Tested	2:50:27 PM	10/11/2018
<b><i>Untested</i></b>				
<b>Initiating</b>				
Heat Detector	Boiler room			
Heat Detector	Center Bay front			
Heat Detector	Center Bay rear			
Heat Detector	North Bay front			
Heat Detector	North Bay rear			
Heat Detector	South Bay front			
Heat Detector	South Bay rear			

<b>Building: Montgomery Transportation/Bus Garage</b>		<b>Control Panel: 2</b>		
<i>The Inspection &amp; Testing section lists all of the items inspected in your building. Items are grouped by Passed or Failed/Other. Items are listed by Category. Each item includes the services performed, and the time &amp; date at which testing occurred.</i>				
<b>Device Type</b>	<b>Location</b>	<b>Service</b>	<b>Time</b>	<b>Date</b>
<b><i>Failed/Other</i></b>				
<b>Control</b>				
Battery	Boiler rm	Checked	3:07:31 PM	10/11/2018

# Service Summary

Generated by: BuildingReports.com

Building: Montgomery Transportation/Bus Garage

The Service Summary section provides an overview of the services performed in this report.

Device Type	Service	Quantity
<b><i>Failed/Other</i></b>		
Battery	Checked	1
Horn/Strobe	Tested	1
Pull Station	Tested	1
Smoke Detector	Tested	2
Total		5
<b><i>Passed</i></b>		
Control Panel	Tested	1
Heat Detector	Tested	1
Horn/Strobe	Tested	2
Pull Station	Tested	3
Total		12
<b><i>Untested</i></b>		
Heat Detector		7
Total		19

# Battery & Power Supply Testing

Generated by: BuildingReports.com

Building: Montgomery Transportation/Bus Garage		Control Panel: 2					
<p><i>The Control &amp; Power Testing section details the readings and measurements of batteries and power supplies used to provide power to the fire alarm and life safety systems. Items are grouped by Passed or Failed/Other.</i></p>							
Type	Location	Rated Ah	Rated Volts	Pre Test	Post Test	Min Ah	Tested Ah
<i>Failed/Other</i>							
<b>Battery</b>							
Sealed Lead Acid	Boiler rm	7	12				



# Inventory & Warranty Report

Generated by: *BuildingReports.com*

Building: Montgomery Transportation/Bus Garage		Control Panel: 1 - Ademco vista 100		
<p><i>The Inventory &amp; Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.</i></p>				
Device or Item	Category	% of Inventory	Quantity	
Heat Detector	Initiating	42.11%	8	
Pull Station	Initiating	21.05%	4	
Smoke Detector	Initiating	10.53%	2	
Horn/Strobe	Indicating	15.79%	3	
Control Panel	Control	5.26%	1	
Battery	Control	5.26%	1	
Type	Qty	Model #	Description	Install Date
<b><i>In Service - 2 Years to 3 Years</i></b>				
Heat Detector	6	281-BPL	Fixed Temperature	08/29/2016
Heat Detector	2	281-BPL	Rate-of-Rise	08/29/2016
Pull Station	1			08/29/2016
Pull Station	1	4050-211T		08/29/2016
<b>Ademco</b>				
Control Panel	1	vista 100		08/29/2016
Horn/Strobe	1			08/29/2016
Pull Station	1		Single Action	08/29/2016
Smoke Detector	2			08/29/2016
<b>EST</b>				
Pull Station	1	270-SPO	Single Action	08/29/2016
<b>System Sensor</b>				
Horn/Strobe	2	121575		08/29/2016

Building: Montgomery Transportation/Bus  
Garage

Control Panel: 2

*The Inventory & Warranty Report lists each of the devices and items that are included in your Inspection Report. A complete inventory count by device type and category is provided. Items installed within the last 90 days, within the last year, and devices installed for two years or more are grouped together for easy reference.*

Type	Qty	Model #	Description	Install Date
<b><i>In Service - 5 Years to 10 Years</i></b>				
<b>Ultra Tech</b>				
Battery	1	vista 100	Sealed Lead Acid	05/22/2013